

Release Notes for QX20/QX500 6.3.26, Edition 1

THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY INFORMATION OWNED BY EPYGI TECHNOLOGIES, LLC. ANY COPYING, USE OR DISCLOSURE OF THE DOCUMENT OR THE INFORMATION CONTAINED HEREIN WITHOUT THE WRITTEN PERMISSION OF EPYGI TECHNOLOGIES, LLC. IS STRICTLY PROHIBITED.

THIS DOCUMENT IS PROVIDED TO YOU FOR INFORMATIONAL PURPOSES ONLY. The information furnished in this document, believed by Epygi Technologies to be accurate as of the date of publication, is subject to change without notice. Epygi Technologies assumes no responsibility for any errors or omissions in this document and shall have no obligation to you as a result of having made this document available to you or based upon the information it contains.

Epygi, QX and Quadro are registered trademarks of Epygi Technologies, LLC. All other products and services are the registered trademarks of their respective holders.

1 Introduction

This Release Notes describes hardware and firmware requirements to use with the

QX20/QX500 firmware 6.3.26 Date: September 02, 2020

Additional enhancements, bug fixes and known issues incorporated in this firmware will be listed as known.

Date: September 04, 2020



2 Requirements

2.1 Hardware Requirements

- The firmware (FW) can be used on QX20 and QX500 models only.
- The model name is written on the front plate of the unit; the unit serial number is on the bottom label.

2.2 Firmware Requirements

Attention: The firmware upgrade to 6.3.26 can ONLY be done from 6.1.45 and higher versions.

2.3 Supported IP Phones

Listed below are the Epygi Supported IP phones with the corresponding software (firmware) versions that are tested and recommended for use with QX20/QX500 FW 6.3.26.

Note:

- The Auto Configuration and PnP services are described in detail in the Configuring Epygi Supported IP Phones with QX IP PBXs guide.
- Any known issues and limitations regarding the usage of the QX20/QX500 FW 6.3.26 telephony services and features for each IP phone are described in detail in the QX IP PBX Features on Epygi Supported IP Phones guide.

				PnP	
Vendor	Model	SW/FW Version	PnP (Multicast)	Assisted PnP (DHCP options 66/67)	Auto Configuration
Akuvox	R15(P)	15.0.5.235	Yes	Yes	Yes
Akuvox	SP-R53(P)	53.0.6.115	Yes	Yes	Yes
Alcatel	IP2015 (IP15)	1.0.7A-0	No	No	Yes
Alcatel	Lucent 8058S	1.51.07	Yes	No	Yes
Alcatel	Temporis IP100	1.0.6A-0	No	No	Yes
Alcatel	Temporis IP150	1.0.6A-0	No	No	Yes
Alcatel	Temporis IP200	13.60.0.89	Yes	Yes	Yes
Alcatel	Temporis IP300	1.0.7B-0	No	No	Yes
Alcatel	Temporis IP600	14.60.0.89	Yes	Yes	Yes
Alcatel	Temporis IP700G	1.0.7A-0	No	No	Yes
Alcatel	Temporis IP800	15.60.0.89	Yes	Yes	Yes
AudioCodes	310HD	1.6.0_build_37	No	No	Yes
AudioCodes	320HD	1.6.0_build_37	No	No	Yes
Cisco	CP-6821	11.2.3	No	No	Yes
Cisco	CP-6851	11.1.1	No	No	Yes
Cisco	CP-7861	11.1.1	No	No	Yes
Cisco	CP-8851	11.1.1	No	No	Yes
Cisco	CP-8861	11.1.1	No	No	Yes
Cisco	SPA303	7.4.9c	No	Yes	Yes
Cisco	SPA501G	7.4.9c	No	Yes	Yes



Vendor	Model	SW/FW Version	PnP (Multicast)	Assisted PnP (DHCP options 66/67)	Auto Configuration
Cisco	SPA508G	7.5.2	No	Yes	Yes
Cisco	SPA509G	7.4.9c	No	Yes	Yes
Cisco	SPA525G2	7.4.9c	No	Yes	Yes
Epygi	UC912G	2.0.4.8.7	No	No	Yes
Epygi	UC923	2.0.4.8.7	No	No	Yes
Epygi	UC924E	2.0.4.8.7	No	No	Yes
Fanvil	C58/C58P	2.3.233.129	No	No	Yes
Fanvil	C62/C62P	2.5.787.97	No	No	Yes
Fanvil	C400	14.0.0.3.r1	No	No	Yes
Fanvil	C600	14.0.0.3.r1	No	No	Yes
Fanvil	F52/F52P	2.3.123.78	Yes	Yes	Yes
Fanvil	H2/H2S	2.8.0.6251	Yes	Yes	Yes
Fanvil	H3	2.8.0.6251	Yes	Yes	Yes
Fanvil	H5	2.8.0.6251	Yes	Yes	Yes
Fanvil	X3/X3P	1.4.0.2016	Yes	Yes	Yes
Fanvil	X3S/X3G	2.8.0.6251	Yes	Yes	Yes
Fanvil	X4/X4G/X4S	2.8.0.6251	Yes	Yes	Yes
Fanvil	X5/X5G	1.4.0.2016	Yes	Yes	Yes
Fanvil	X5S	1.8.0	Yes	Yes	Yes
Fanvil	X6	1.8.0	Yes	Yes	Yes
Flyingvoice	FIP13G	0.3.46	Yes	No	Yes
Gigaset	Maxwell 3 PRO	82.2.22.7	Yes	Yes	Yes
Gigaset	N720 DM PRO	70.113.00.000.000	No	No	Yes
Grandstream	GXP1100	1.0.8.6	No	Yes	Yes
Grandstream	GXP1105	1.0.8.6	No	Yes	Yes
Grandstream	GXP1160	1.0.8.6	No	Yes	Yes
Grandstream	GXP1165	1.0.8.6	No	Yes	Yes
Grandstream	GXP1400	1.0.8.6	No	Yes	Yes
Grandstream	GXP1405	1.0.8.6	No	Yes	Yes
Grandstream	GXP1450	1.0.8.6	No	Yes	Yes
Grandstream	GXP1615/1610	1.0.4.55	No	Yes	Yes
Grandstream	GXP1625/1620	1.0.4.55	No	Yes	Yes
Grandstream	GXP1628	1.0.4.55	No	Yes	Yes
Grandstream	GXP1630	1.0.4.55	No	Yes	Yes
Grandstream	GXP1760	1.0.0.48	No	No	Yes
Grandstream	GXP1782/1780	1.0.0.48	No	No	Yes
Grandstream	GXP2100	1.0.8.6	No	Yes	Yes
Grandstream	GXP2110	1.0.8.6	No	Yes	Yes
Grandstream	GXP2120	1.0.8.6	No	Yes	Yes
Grandstream	GXP2124	1.0.8.6	No	Yes	Yes
Grandstream	GXP2130	1.0.7.99	No	Yes	Yes
Grandstream	GXP2135	1.0.7.99	No	Yes	Yes
Grandstream	GXP2140	1.0.7.99	No	Yes	Yes



Vendor Model SW/FW Version PnP (Multicast) (DHG) Grandstream GXP2160 1.0.7.99 No Grandstream GXP2170 1.0.7.99 No Grandstream GXP2200 1.0.3.27 No Grandstream GXV3140 1.0.7.80 No	sisted PnP CP options 66/67) Yes	Auto Configuration Yes Yes Yes Yes Yes Yes Yes
Grandstream GXP2170 1.0.7.99 No Grandstream GXP2200 1.0.3.27 No Grandstream GXV3140 1.0.7.80 No	Yes Yes Yes Yes Yes	Yes Yes Yes
Grandstream GXP2200 1.0.3.27 No Grandstream GXV3140 1.0.7.80 No	Yes Yes Yes Yes	Yes Yes
Grandstream GXV3140 1.0.7.80 No	Yes Yes Yes	Yes
	Yes Yes	
0.14.	Yes	Yes
Grandstream GXV3175 1.0.3.76 No		
Grandstream GXV3240 1.0.3.62 No	Yes	Yes
Grandstream GXV3275 1.0.3.62 No		Yes
Htek UC902 2.0.4.4.41 Yes	Yes	Yes
Htek UC903 2.0.4.4.41 Yes	Yes	Yes
Htek UC912 2.0.4.4.41 Yes	Yes	Yes
Htek UC912E 2.0.4.4.41 Yes	Yes	Yes
Htek UC912G 2.0.4.4.41 Yes	Yes	Yes
Htek UC923 2.0.4.4.41 Yes	Yes	Yes
Htek UC924 2.0.4.4.41 Yes	Yes	Yes
Htek UC924E 2.0.4.4.41 Yes	Yes	Yes
Htek UC926 2.0.4.4.41 Yes	Yes	Yes
Htek UC926E 2.0.4.4.41 Yes	Yes	Yes
iServ 8660 (8430/8630/8830) 03.55.0025 No	No	Yes
iServ Escene ES282-PC V1.1.0.10143324 No	No	Yes
iServ U3S V1.1.0.10143813 No	No	Yes
iServ U6S V1.1.0.10143813 No	No	Yes
Mitel (Aastra) 6730 3.3.1.4305-SIP Yes	Yes	Yes
Mitel (Aastra) 6731 3.3.1.4305-SIP Yes	Yes	Yes
Mitel (Aastra) 6735 3.3.1.8140-SIP Yes	Yes	Yes
Mitel (Aastra) 6737 3.3.1.8140-SIP Yes	Yes	Yes
Mitel (Aastra) 6739 3.3.1.4305-SIP Yes	Yes	Yes
Mitel (Aastra) 6753 3.3.1.4305-SIP Yes	Yes	Yes
Mitel (Aastra) 6755 3.3.1.4305-SIP Yes	Yes	Yes
Mitel (Aastra) 6757 3.3.1.4305-SIP Yes	Yes	Yes
Mitel (Aastra) 9143 3.3.1.4305-SIP Yes	Yes	Yes
Mitel (Aastra) 9480 3.3.1.4305-SIP Yes	Yes	Yes
Mitel 6863 4.2.0.2023-SIP Yes	Yes	Yes
Mitel 6865 4.2.0.2023-SIP Yes	Yes	Yes
Mitel 6867 4.2.0.2023-SIP Yes	Yes	Yes
Mitel 6869 4.2.0.2023-SIP Yes	Yes	Yes
Panasonic KX-HDV130 03.004 Yes	Yes	Yes
Panasonic KX-HDV130NE, KX-HDV130X 06.101 Yes	Yes	Yes
Panasonic KX-HDV230 03.004 Yes	Yes	Yes
Panasonic KX-HDV230NE, KX-HDV230X 06.101 Yes	Yes	Yes
Panasonic KX-TGP550T04 12.17 No	No	Yes
Panasonic KX-UT123 (NE/RU/X) 01.302 No	No	Yes



				PnP	
Vendor	Model	SW/FW Version	PnP (Multicast)	Assisted PnP (DHCP options 66/67)	Auto Configuration
Panasonic	KX-UT136 (NE/RU/X)	01.302	No	No	Yes
Polycom	SoundPoint IP 330	3.3.5.0247	No	Yes	Yes
Polycom	SoundPoint IP 331	4.0.13.1445	No	Yes	Yes
Polycom	SoundPoint IP 335	4.0.13.1445	No	Yes	Yes
Polycom	SoundPoint IP 450	4.0.13.1445	No	Yes	Yes
Polycom	SoundPoint IP 550	4.0.13.1445	No	Yes	Yes
Polycom	SoundPoint IP 650	4.0.13.1445	No	Yes	Yes
Polycom	SoundPoint IP 670	4.0.13.1445	No	Yes	Yes
Polycom	SoundStation IP 5000	4.0.13.1445	No	Yes	Yes
Polycom	SoundStation IP 6000	4.0.13.1445	No	Yes	Yes
Polycom	Trio 8500	5.9.2.7553	No	Yes	Yes
Polycom	VVX 150	6.1.1.2670	No	Yes	Yes
Polycom	VVX 250	6.1.1.2670	No	Yes	Yes
Polycom	VVX 300/310	5.7.0.14430	No	Yes	Yes
Polycom	VVX 301/311	5.7.0.14430	No	No	Yes
Polycom	VVX 350	6.1.1.2670	No	Yes	Yes
Polycom	VVX 400/410	5.7.0.14430	No	No	Yes
Polycom	VVX 401/411	5.7.0.14430	No	Yes	Yes
Polycom	VVX 450	6.1.1.2670	No	Yes	Yes
Polycom	VVX 500/501	5.7.0.14430	No	No	Yes
Polycom	VVX 600/601	5.7.0.14430	No	Yes	Yes
Polycom	VVX 1500	5.7.0.14430	No	Yes	Yes
QOSIP	Q7104/Q7204	1.0.3.98	No	No	Yes
snom	300	8.4.35	Yes	Yes	Yes
snom	320	8.4.35	Yes	Yes	Yes
snom	360	8.4.35	Yes	Yes	Yes
snom	370	8.7.5.35	Yes	Yes	Yes
snom	720	8.9.3.60	Yes	Yes	Yes
snom	760	8.9.3.60	Yes	Yes	Yes
snom	821	8.7.5.35	Yes	Yes	Yes
snom	870	8.7.5.35	Yes	Yes	Yes
snom	D120	10.1.10.1	Yes	Yes	Yes
snom	D345	8.9.3.60	Yes	Yes	Yes
snom	D375	8.9.3.60	Yes	Yes	Yes
snom	D710/710	8.9.3.60	Yes	Yes	Yes
snom	D712	8.9.3.60	Yes	Yes	Yes
snom	D715/715	8.9.3.60	Yes	Yes	Yes
snom	D717	10.1.33.1	Yes	Yes	Yes
snom	D725	8.9.3.60	Yes	Yes	Yes
snom	D735	10.1.39.11	Yes	Yes	Yes
snom	D745	8.9.3.60	Yes	Yes	Yes
snom	D765	8.9.3.60	Yes	Yes	Yes
snom	D785	10.1.20.0	Yes	Yes	Yes



				PnP		
Vendor	Model	SW/FW Version	PnP (Multicast)	Assisted PnP (DHCP options 66/67)	Auto Configuration	
snom	M700 (M85/M65/M25)	03.24.0007	Yes	Yes	Yes	
snom	m9	9.4.7	Yes	Yes	Yes	
snom	MeetingPoint	8.7.5.35	Yes	Yes	Yes	
Spectralink	KIRK Wireless Server 300	PCS14C_	No	No	Yes	
Spectralink	KIRK Wireless Server 6000	PCS14C_	No	No	Yes	
VTech	ErisStation VCS754	1.1.4.0-0	No	No	Yes	
VTech	ErisTerminal VSP600 (VSP601)	1.1.4.1-0	No	No	Yes	
VTech	ErisTerminal VSP715	1.1.4.0-0	No	No	Yes	
VTech	ErisTerminal VSP725	1.1.4.0-0	No	No	Yes	
VTech	ErisTerminal VSP726	2.0.3.2-0	Yes	Yes	Yes	
VTech	ErisTerminal VSP735	1.1.4.0-0	No	No	Yes	
VTech	ErisTerminal VSP736	2.0.3.2-0	Yes	Yes	Yes	
Yealink	CP860	37.81.0.10	Yes	Yes	Yes	
Yealink	CP920	78.84.0.15	Yes	Yes	Yes	
Yealink	CP960	73.83.0.30	Yes	Yes	Yes	
Yealink	SIP-T19P	31.72.0.1	Yes	Yes	Yes	
Yealink	SIP-T19P E2	53.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T20P	9.72.0.1	Yes	Yes	Yes	
Yealink	SIP-T21P	34.72.0.1	Yes	Yes	Yes	
Yealink	SIP-T21P E2	52.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T22P	7.72.0.1	Yes	Yes	Yes	
Yealink	SIP-T23G(P)	44.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T26P	6.72.0.1	Yes	Yes	Yes	
Yealink	SIP-T27G	69.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T27P	45.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T28P	2.72.0.1	Yes	Yes	Yes	
Yealink	SIP-T29G	46.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T32G	32.70.0.130	Yes	Yes	Yes	
Yealink	SIP-T38G	38.70.0.125	Yes	Yes	Yes	
Yealink	SIP-T40G	76.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T40P	54.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T41P	36.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T41S	66.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T42G	29.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T42S	66.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T46G	28.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T46S	66.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T48G	35.83.0.50	Yes	Yes	Yes	
Yealink	SIP-T48S	66.83.0.50	Yes	Yes	Yes	
Yealink	SIP VP-T49G	51.80.0.100	Yes	Yes	Yes	
Yealink	SIP-T52S	70.83.0.50	Yes	Yes	Yes	



			ſ	PnP	
Vendor	Model	SW/FW Version	PnP (Multicast)	Assisted PnP (DHCP options 66/67)	Auto Configuration
Yealink	SIP-T53/53W	95.84.0.30	Yes	Yes	Yes
Yealink	SIP-T54S	70.83.0.50	Yes	Yes	Yes
Yealink	SIP-T54W	96.84.0.30	Yes	Yes	Yes
Yealink	SIP-T56A	58.83.0.15	Yes	Yes	Yes
Yealink	SIP-T57W	97.84.0.30	Yes	Yes	Yes
Yealink	SIP-T58V/A	58.83.0.15	Yes	Yes	Yes
Yealink	VP59	91.283.0.40	Yes	Yes	Yes
Yealink	VP-530	23.70.0.40	Yes	Yes	Yes
Yealink	W52P	25.30.0.20	Yes	Yes	Yes
Yealink	W60B	77.83.0.25	Yes	Yes	Yes
Yealink	W80B DM	103.83.0.70	Yes	Yes	Yes

2.4 Interaction with Other Epygi Software Releases

Use the latest SW and FW versions for other Epygi products to achieve maximum compatibility with QX20/QX500 FW 6.3.26:

- QXE1T1, QXFXO4 and QXISDN4 gateways used in the Share mode should have FW 6.3.14 or higher.
- QXFXS24 should have FW 6.3.14 or higher for PnP configuration.
- eQall for Windows SW 1.3.2 or higher should be used. Check eQall User Guide.
- eQall for Android SW 1.3.3 or higher should be used. eQall for iOS to be determined.
- iQall (IOS application) version 1.2.0 and iQall (Android application) version 1.2.1 or higher should be used.
- Desktop Communication Console (DCC) SW 1.18 or higher should be used.
- Epygi Hotel Console (EHC) SW 1.0.7 or higher should be used.
- Epygi Media Streamer (EMS) SW 2.4 or higher should be used.
- HotCall Add-In SW 2.5 or higher should be used.
- HotKeyCall SW 1.14 or higher should be used.
- Bulk User Extensions Importer version 1.7 or higher should be used.
- CallControl Pack SW 5.8.0 or higher should be used.
- To use QX20/QX500 with a **3PCC** or **Click2Dial** application, the **Allow 3pcc/Click2Dial Access** option should be enabled for each extension using this feature.
- Auto Dialer SW 1.0.11 or higher should be used.
- QX-Quadro Configuration Console (QCC) SW 2.5 or higher should be used.

Important Note: The ACD, AOC, EAC, EHC and Auto Dialer features are available on QX500 only.



3 New Features

The table below indicates a high-level list of new features that have been added beginning with the most recent QX20/QX500 FW release.

Release	New Features
	QX Integration with the CRM systems Vtiger and Salesforce for providing support to create, view and update Vtiger and Salesforce contacts automatically when receiving inbound calls on the QX.
	Added auto configuration support for the new Yealink W80B DM (DECT Manager) phone.
	Added auto configuration support for the new Cisco IP phones: CP-6821 and CP-8861.
	Added auto configuration support for the new Epygi IP phones: UC912G, UC923 and UC924E.
	Added PnP and auto configuration support for the new Flyingvoice FIP13G IP phone.
	Added support to add and manage associated groups of call park extensions. In the scenarios
6.3.26	when external callers are using the call park option on the custom auto attendant prompt, and
	there is a call already parked on the selected extension, call parking will failover to the next
	available park extension in the same group.
	Added multi-edit support for groups of call park with page extensions.
	Added support to configure programmable keys on the Yealink T4/T5 series phones to be able
	to make and receive Multicast Paging, to allow paging to unlimited number of phones. Support for other phones will be added in future releases.
	Added support to be able to change the default admin password of supported IP phones from
	the QX.
	The Call Park feature has been enhanced with new capabilities:
	1. Call park configuration and functionality has been integrated with paging. When the call is
	parked, the system will automatically do a page to the predefined paging group to
	announce a call is parked.
	2. A new Park the call option has been added in the User input options list for auto
	attendant custom scenario. Pressing the key assigned to that option on auto attendant
	prompt would park the call on the preconfigured call park extension.
	Added support for new video codecs: VP8, H.265 HEVC (High-Efficiency Video Coding).
6.3.14	Added auto configuration support for the new Polycom Trio 8500 Conference phone.
0.3.14	Added PnP and autoconfiguration support for the new Yealink VP59 Video phone.
	Added Receptionist support for the Polycom VVX 450 IP phone.
	Added support to connect QX to MS Teams, so that Team's users can make SIP and PSTN
	calls over the QX IP PBX and vice versa.
	Added a new Show on login page option in the Event Setting allowing to show the selected
	events on the QX login page.
	Added support for users to be able to change the system default SSL/TLS certificate with their
	own. This will give users ability to change the system default SSL/TLS certificates, namely the
	Certificate Authority, Certificate, Private Key with their own from the new GUI page.
6.3.5	
6.3.4	Added a Oall for Analysis are not the profession and the least of the OV ID DDV
6.3.3	Added eQall for Android support, the softphone designed to be used with QX IP PBXs.
	Added auto configuration support for the following Polycom IP phones: WX 150, WX 250, WX 350, VVX 450, WX 501 and VVX 601.
0.0.0	Added auto configuration support for the following iServ IP phones: Escene ES282-PC, U3S, U6S.
	Added auto configuration support for the Gigaset N720 DM PRO IP phone.



Release	New Features
6.3.1	Added support for eQall, the softphone designed to be used with QX IP PBXs. The current version of eQall supports the full set of QX20/QX500 telephony features, like other Epygi supported IP phones. The QX20/QX500 by default has support for one eQall license included. To use more eQall softphones, a license key needs to be installed on the QX. Added PnP support for the Alcatel-Lucent 8058S IP phone.

4 Changed Features

The table below provides a high-level list of changed features that have been changed beginning with the most recent QX20/QX500 FW release.

Release	Changed Features
	The value for ACD wrap-up timeout is changed to be in the range 5-300 sec.
	OpenVPN enhancements:
	OpenVPN updated from 2.3.7 to 2.4.9 version.
	 Added Allow no encryption option in the server configuration. If this option is enabled, then clients can establish data channel without encryption.
0.000	 Added ability to change cipher per client. The following ciphers added into the allowed ciphers list to be negotiated: AES-256-GCM, AES-256-CBC, AES-128-GCM, AES-128- CBC. Clients with the different ciphers can connect at the same time.
6.3.26	For OpenVPN the NTP Server on the phones is set to ntp1.epygi.com.
	The behavior for the Call park with paging feature has been modified as follows:
	 If users have recorded their own paging notification message, then at the end of the message the system will not play the call park extension number.
	 If they have not recorded a message then paging notification will play the park extension number only.
	The VoIP Carrier Wizard updated with the Flowroute new server: us-east-va.sip.flowroute.com. Note: The old server sip.flowroute.com no longer works.
	ACD/EAC behavior has been modified, so that if the agent closes the EAC web browser, his status changes to Offline .
	 Added a new checkbox below the existing "Set agent status "Offline" on log out" in the EAC General Settings->Agents settings. The name of the new checkbox is "Set agent status "Offline" on closing EAC".
	 If this checkbox is enabled then agent's status changes to offline when agent closes the browser, or EAC tab in browser, or somehow closes connection to QX.
	Note: This setting is available only for EAC admin and applies to all agents.
6.3.14	ACD/EAC behavior has been modified to restrict the access to Agents menu in the EAC.
	 Added a new checkbox in the EAC->General Settings->Agents settings. The name of the new checkbox is "Show Agents menu only for admins and supervisors".
	 If this checkbox is enabled then only admins and supervisors can see and access the Agents menu.
	Increased the queues sizes for SIP local messages.
	Increased the size for URL fields in the Firewall configuration.
	Increased the max number of templates in the manage IP phones templates table to 40.
	The max number of recordings in the recording box has been increased from 1000 to 5000.

Edition 1 9 4-Sep-20



Release	Changed Features
	Support to add FQDN-s in the SIP IDS Exceptions. This will give users ability to add also FQDN-s in the SIP IDS Exceptions, besides the trusted IP addresses.
6.3.5	
6.3.4	
6.3.3	Added a new Mandatory Participant option under the conference participant settings. If that option is selected for a participant, the active conference will be closed regardless of the number of participants connected, if that participant leaves the conference. SIP IDS GUI and functionality has been redesigned. See the appropriate documentation for the details. The Caller ID behavior has been enhanced for the Fanvil X6, X5S, X4/X4G/X4S, and X3S/X3G models.
6.3.1	The value for the Retrieve Timeout field in the Call Park extension settings has been changed to seconds. Now the user can use any value for call park retrieve timeout in the range of 30-3600 sec. Added the Actions dropdown menu under the Destination Number Pattern column for the Call Routing Table. In addition to the existing Edit icon, the Move Up, Move Down, Move To, Duplicate, Enable, Disable, and Delete options are available. This significantly reduces the necessity of scrolling when working with routing rules. The recommended FW version has been changed for the Alcatel Lucent - 8058S IP phone from 1.51.05 to 1.51.07.

Edition 1 10 4-Sep-20



5 Fixed Issues

Issues fixed since version 6.3.14:

T: Title

D: Description

	T:	An issue with the authentication password in the ETD conver configuration pages
20787	11	An issue with the authentication password in the FTP server configuration pages The FTP server configuration doesn't allow some specific symbols for the password,
20101	D:	namely the !, @, #.
20760	T:	All OpenVPN connections lost because of the OpenVPN certificate expired
20700	D:	
	T:	The list of special devices in the DHCP→Special Devices web management incorrectly shows as empty
20758	D:	You are unable to view the list of special devices through the DHCP→Special Devices web management interface of the QX. We know for sure there are special devices configured there because when attempt to duplicate a special device the management console tells the entry already exists.
	T:	Not possible to create new User IDs or add to the room condition mapping table, getting error always
20757	D:	PMSLINK is using the same DB as EHC. If EHC is not installed, there is no DB and PMSLINK was failing. Need to separate the EHC and PMSLINK databases to resolve this issue.
	T:	3PCC service crashes in a specific scenario
		1. User opens DCC application connected to QX.
20747		2. Closes it and reopens again.
	D:	3. User sets "custom" status note as an addition for his/her main status.
		4. This causes 3PCC service crash.
	T:	Audio problems after OpenVPN client connection
20739	D:	
00707	T:	Cannot add Static IP for the OpenVPN Client file
20737	D:	
	T:	The time server doesn't work for the phones using OpenVPN
20735	D:	The IP phone connected via OpenVPN does not resolve the NTP server IP and show wrong time.
	T:	DNS doesn't update the IP address
20731	D:	IP address for FQDN was changed, but DNS server on QX doesn't resolve the new IP and shows the old one.
20728	T:	In some scenarios with QX connected to MS Teams, QX drops the call when MS Teams user tries to transfer that call or put it on hold
	D:	
20727	T:	The DNS status is always showing stopped in the Status → Network Status page
20727	D:	DNS is running, but network status incorrectly show the DNS status as stopped.



6 Known Issues

T: Title

D: Description

C: Consequences

Fix: How to avoid the situation, or what to do in case the situation has occurred

	T:	Functions configured on the line keys for Flyingvoice FIP13G don't work
	D:	- arreading corringation are the top of the right of the
20790	C:	
	Fix:	Will be fixed in future release.
	T:	Sometimes pressing Finish in the system configuration wizard gives the error "Page Not Found"
	D:	1 ound
20785	C:	
	Fix:	Workaround: When getting Page Not Found click the Go Back button or refresh the page, then click OK button for confirmation.
	T:	The presence status has no effect in the caller id-based services for extensions, concerning the Find me/Follow me and Dial & Announce options
20725	D:	
	C:	
	Fix:	Will be fixed in future release.
	T:	Store & Forward option wouldn't work for password protected Paging
20684	D:	When you pass password authorization and make paging, that will function as a direct page, not as a Store & Forward.
20001	C:	
	Fix:	Will be fixed in future release.
	T:	iServ phones Escene ES282-PC, U3S and U6S may freeze and become unresponsive unexpectedly
20659	D:	
	C:	
	Fix:	Needs to be fixed in some future FW version from iServ.
	T:	iServ phones Escene ES282-PC, U3S and U6S ring only once on receiving a call
00057	D:	However, the call can be answered before the phone's no answer timeout.
20657	C:	
	Fix:	Needs to be fixed in some future FW version from iServ.
	T:	The 3pcc server sends the display name (DN) to its clients only for incoming SIP and PBX calls
20537	D:	In the Find Me/Follow Me, ACD and some other scenarios the 3pcc server sends the DN to its clients only for incoming SIP and PBX calls.
	C:	
	Fix:	Will be fixed in future release.
	T:	The status for LAN/WAN Ethernet is always incorrectly shown as N/A under the System Status - Hardware Status page
20315	D:	
	C:	No consequences.
	Fix:	Will be fixed in future release.



T: Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing			The DIE to the Atlant (for any annual to be and a line of the state of
D: The issue appears on snom 3xx and 8xx series running 8.7.5.35 firmware version. C: Fix: Workaround: The issue is solved in snom 8.7.5.44 beta firmware. T: A problem when restoring a config backup downloaded from the QX with custom language Pack (LP) is installed Scenario that cause this problem: Backup and download a config file on the QX with a custom LP installed Remove the custom LP Upload and restore back that config file to the same QX At this point none of the system voice messages is playing. The reason why this is happening is the following: the system is looking for the audio files specific for that LF. C: No consequences. Fix: Install the same LP on the QX, after remove that LP in the upload language pack pag Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing	19805	T:	
C: Fix: Workaround: The issue is solved in snom 8.7.5.44 beta firmware. T: A problem when restoring a config backup downloaded from the QX with custom language Pack (LP) is installed Scenario that cause this problem: Backup and download a config file on the QX with a custom LP installed Remove the custom LP Upload and restore back that config file to the same QX At this point none of the system voice messages is playing. The reason why this is happening is the following: the system is looking for the audio files specific for that LF C: No consequences. Install the same LP on the QX, after remove that LP in the upload language pack pag Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing		D:	
Fix: Workaround: The issue is solved in snom 8.7.5.44 beta firmware. T: A problem when restoring a config backup downloaded from the QX with custom language Pack (LP) is installed Scenario that cause this problem: Backup and download a config file on the QX with a custom LP installed Remove the custom LP Upload and restore back that config file to the same QX At this point none of the system voice messages is playing. The reason why this is happening is the following: the system is looking for the audio files specific for that LF C: No consequences. Fix: Install the same LP on the QX, after remove that LP in the upload language pack pag Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing			<u> </u>
19725 language Pack (LP) is installed Scenario that cause this problem: Backup and download a config file on the QX with a custom LP installed Remove the custom LP Upload and restore back that config file to the same QX At this point none of the system voice messages is playing. The reason why this is happening is the following: the system is looking for the audio files specific for that LF C: No consequences.			Workaround: The issue is solved in snom 8.7.5.44 beta firmware.
Scenario that cause this problem: Backup and download a config file on the QX with a custom LP installed Remove the custom LP Upload and restore back that config file to the same QX At this point none of the system voice messages is playing. The reason why this is happening is the following: the system is looking for the audio files specific for that LF C: No consequences. Install the same LP on the QX, after remove that LP in the upload language pack pag Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing	19725	T:	
19725 • Remove the custom LP • Upload and restore back that config file to the same QX At this point none of the system voice messages is playing. The reason why this is happening is the following: the system is looking for the audio files specific for that LF C: No consequences. Fix: Install the same LP on the QX, after remove that LP in the upload language pack pag Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing			
19725 • Remove the custom LP • Upload and restore back that config file to the same QX At this point none of the system voice messages is playing. The reason why this is happening is the following: the system is looking for the audio files specific for that LF C: No consequences. Fix: Install the same LP on the QX, after remove that LP in the upload language pack pag Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing			Backup and download a config file on the QX with a custom LP installed
Upload and restore back that config file to the same QX At this point none of the system voice messages is playing. The reason why this is happening is the following: the system is looking for the audio files specific for that LF C: No consequences. Install the same LP on the QX, after remove that LP in the upload language pack pag Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing			
At this point none of the system voice messages is playing. The reason why this is happening is the following: the system is looking for the audio files specific for that LF C: No consequences. Fix: Install the same LP on the QX, after remove that LP in the upload language pack pag Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing		D:	
C: No consequences. Fix: Install the same LP on the QX, after remove that LP in the upload language pack pag Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing			At this point none of the system voice messages is playing. The reason why this is
Fix: Install the same LP on the QX, after remove that LP in the upload language pack page Will be fixed in future release. T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing		C:	
T: It's not possible to park a call twice to the same call park extension by using programmable key on Yealink T32G and T38G Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing		Fix:	Install the same LP on the QX, after remove that LP in the upload language pack page.
Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key). C: Fix: Workaround: Park the call to different call park extension. Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing	18839	T:	It's not possible to park a call twice to the same call park extension by using
C: Fix: Workaround: Park the call to different call park extension. T: Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing.		D:	Upon successful call park/pick up the second attempt to park the call, using the park ext. programmable key fails. The problem is happening only if you park the call to the same park extension (by pressing Call Park key).
T: Could not dial out (*1) or use any other moderator feature while welcome message had been playing Could not dial out (*1) or use other moderator features while welcome message has been playing.		C:	
T: Could not dial out (*1) or use any other moderator feature while welcome message has been playing Could not dial out (*1) or use other moderator features while welcome message has been playing.		Fix:	Workaround: Park the call to different call park extension.
Could not dial out (*1) or use other moderator features while welcome message has k	18549	T:	Could not dial out (*1) or use any other moderator feature while welcome message has
features. It is recommended to keep the welcome message to a short duration.		D:	Could not dial out (*1) or use other moderator features while welcome message has been playing. You should listen to the whole welcome message first, after that use moderator
C:		C:	
Fix: Will be fixed in future release.		Fix:	Will be fixed in future release.
T: Part of conference recording is lost after recording pause/resume	18548	T:	Part of conference recording is lost after recording pause/resume
		D:	When pausing the conference recording and then resuming it again, the final recording contains only the part after resuming.
C:		C:	y - 12
Fix: Will be fixed in future release.			Will be fixed in future release.



7 General Hints

7.1 Technical Advisory

- When using Call Recording and/or ACD features on the QX20/QX500 it is advisable to use a micro SD memory card to expand the system memory. Currently, the recommended micro SD card's largest capacity is 256 GB.
- Always power down the QX20/QX500 before inserting/removing micro SD memory card.
- Some system information (Call History, Conference History and Pending Events) will be lost when QX20/QX500 is powered down. You may maximum lose the portion of the above-mentioned system information, which occurred during last hour before the QX is powered down. It's recommended to enable Call History – Archiving to minimize the loss of Call History.

7.2 Firmware Update

It is recommended to execute the update by downloading the firmware first to a PC located in the LAN side of the QX20/QX500 and perform the firmware update from the LAN side. This is to ensure that the Internet connection will not affect the upgrade process.

Attention: It is recommended to back up the configuration for emergency purposes prior to upgrading the firmware. You can do that from Maintenance > Backup/Restore > Backup and download current Configuration page. The current configuration will remain after the firmware update. Moreover, the locally saved voice mails and call recordings, all custom messages and call history will be saved during the upgrade.

To perform the manual firmware update:

- 1. Go to the Maintenance > Firmware > Manual Firmware Update page.
- 2. Click the **Download Configuration** link to back up the current configuration (recommended).
- 3. Click the Choose File button to browse for image.bin file.
- 4. Click Save to start uploading the file.
- 5. Click **Yes** to proceed the firmware upgrade.

Note: The update process takes about 5 minutes. Normal operation will be stopped during that time.

7.3 Limitations and Restrictions

- The Network Capture size is limited to 24 MB. This will put a limitation on the duration of captured file.
- The Call Capture duration is limited to 160 seconds.
- The capture duration is limited to 160 seconds in DSP Capture hidden page.
- In case if Voice Mail Recording Codec is other than PCMU, the maximum length of voice message sent by email is limited to 5 minutes.
- The Voice Mailbox size is limited to 300 voice mails for each extension.