

TECH ARTICLE

Date: 12/11/2007

Revision Date (6 months max): N/A

Topic / Issue: ESM XP3 Series Serial numbers and Firmware Upgrades

Written By: Scott Young

An ESM (XP3 series) switch updated with the wrong firmware will report a "Data Abort error" on startup.

This can only be repaired by Alloy Service Department, and will be subject to a Service Charge. (NOT Covered under Warranty)

Summary:
(If required)