

TECH ARTICLE

Date: 12/11/2007

Revision Date (6 months max): N/A

Topic / Issue: Jetstream Serial Servers LAN interface stops responding after 3 minutes

Written By: Scott Young

Related Products:

JS4008, JS4008/RMB, JS8516/RJX, JS8524/RJX

The Jetstream will report "Deleting route to interface le0" on the console screen.

This problem will occur when RIP messages are not received by the Jetstream unit. In its default state it expects to send and receive RIP routing status information.

To overcome this issues:

Disable RIP by setting OEM Mode = 4 in the Server Configuration Option.

Summary:
(If required)