

TECH ARTICLE

Date: 13/11/2007

Revision Date (6 months max): N/A

Topic / Issue: Wireless card Blue Screens or Lockups on Driver load WinXP SP2- WLT245401 / WLT2454VP

Written By: Scott Young

Some customers may be experiencing blue screens or system lock up on driver load under WinXP SP2.

To resolve this problem perform the following.

A) Upgrade to at least version 1.3 of the driver

The upgrade can be found here:

http://www.alloy.com.au/web_download/Wireless/54Mb/WLT245401_VP/

B) before upgrading, remove the wireless card, delete the following files from system32\drivers :

TNET1130.sys, FW1130.bin, FWRAD16.bin, FWRAD17.bin

Summary:
(If required)