



TEST REPORT

Report No.: HC70238A/2006

Page: 1 of 5

Date : August 14, 2006

ALLOY COMPUTER PRODUCTS
4/585 BLACKBURN RD.
NOTTING HILL, VICTORIA, AUSTRALIA

The following merchandise was submitted and identified by the vendor as:

Product Description: 24 PORT SNMP MODULAR FIBRE SWITCH
Style/ Item No.: MS888G2/ No.1
Manufacturer/ Vendor: Alloy Computer Products
Country of Origin: Taiwan
Quantity: Total 1 set

We have tested the submitted sample(s) as requested and the following results were obtained:

Test Required: (According to client's test specification, please see following sheets in detail.)

1. Mechanical Shock Test

Test Results: - PLEASE SEE ATTACHED SHEETS -

*HC70238/2006, dated August 7, 2006, is hereby canceled and replaced by HC70238A/2006.

Cedric Chen
Asst. Supervisor

1. Mechanical Shock Test:

Test Equipment:

Name	Brand	Model	Serial No.
Shock Test System	LANSMONT	65-81 TTSII	M-13418
Data Acquisition & Analysis System	LANSMONT	103570-2-B	0503-73
ICP Accelerometer	PCB	353B14	79713

Lab Environmental Conditions:

 Ambient temperature: 25±3°C

 Relative humidity: 55±20%RH

Test Method/ Specification:

 Sample condition: Packaged

 Pulse shape: Half-sine

 Acceleration: 4 G

 Pulse duration: 11 ms

 Shock direction: X, Y, Z axes

 No. of shock: 10 shock/ axis (total 6 shocks, see photo 5~10)

- Examine the appearance of specimen by visual check and perform functional check after this test.
- Functional check: Connect the specimen with PC via RJ45 port and examine the Network Connecting Function of specimen could be work normally or not.

TEST REPORT

Report No.: HC70238A/2006

Page: 3 of 5

Specimen:

Style/Item No.: MS888G2/ No.1

Quantity: total 1 set


Test Result:

<div style="text-align: right;">Check Item</div> <div style="text-align: left;">Style/ Item No.</div>	Appearance Check (Visual Check)	Functional Check
MS888G2/ No.1	No visible damage	Normal

Test Photos:

	
<p>1. Appearance of specimen (Packaged)</p>	<p>2. Package style (inside carton)</p>
	
<p>3. Package style</p>	<p>4. Appearance of specimen (MS888G2)</p>
	
<p>5. Mechanical shock test: X axis</p>	<p>6. Mechanical shock test: X axis</p>

Test Photos--Continued:



— — — The End of Test Report — — —

Any unauthorized alteration, forgery or falsification of the content or appearance of this report is unlawful and offenders may be prosecuted to the fullest extent of the law. 對本報告內容或外觀之任何未經授權之變更、偽造、竄改皆屬非法，違犯者將會被依法追訴。