

# **TECH ARTICLE**

**Date:** 13/11/2007

**Revision Date (6 months max):** N/A

---

**Topic / Issue:** Compatibility problems with some printers- IP515LM / PSHX3P-B

---

**Written By:** Scott Young

---

Below is a list of incompatible printers that will not work with Alloy Print Servers.

(1.) GDI (Graphic Display Interface) printer  
HP Deskjet 820cxi

(2.) Canon CAPT (Canon Advanced Printing Technology) printer  
Printer : LBP250, LBP-810 ,LBP-1110, LBP-1120, LBP-1210 , LBP-2410

(3.) EPSON LaserWrite Printer  
Printer : EPSON LP1300, 5800, EPL-6200L, C900

---

**Summary:**  
**(If required)**