

# Release Note QuadroM8L/26x/12Li/26xi 5.3.53, Edition 1

THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY INFORMATION OWNED BY EPYGI TECHNOLOGIES LTD. ANY COPYING, USE OR DISCLOSURE OF THE DOCUMENT OR THE INFORMATION CONTAINED HEREIN WITHOUT THE WRITTEN PERMISSION OF EPYGI TECHNOLOGIES LTD. IS STRICTLY PROHIBITED.

THIS DOCUMENT IS PROVIDED TO YOU FOR INFORMATIONAL PURPOSES ONLY. The information furnished in this document, believed by Epygi Technologies to be accurate as of the date of publication, is subject to change without notice. Epygi Technologies assumes no responsibility for any errors or omissions in this document and shall have no obligation to you as a result of having made this document available to you or based upon the information it contains.

Epygi is a registered trademark of Epygi Technologies, Ltd. All other products and services are the registered trademarks of their respective holders

## 1 Introduction

This Release Note describes hardware and software requirements to use with the

QuadroM8L/26x/12Li/26xi software 5.3.53 Date: June 28, 2013

Additional enhancements, bug fixes and known issues incorporated in this software will be listed as known.

Date: July 10, 2013

# 2 Requirements

## 2.1 Hardware requirements

- The software can be used on QuadroM8L/26x/12Li/26xi models.
- The model name is written on the back plate of the unit, and the model number is on the bottom label.

#### 2.2 Software requirements

**Attention:** The software upgrade to 5.3.53 can **ONLY** be done from 5.2.47 and higher 5.2 versions. Before updating to 5.3.53 the unit should be updated to 5.2.47 or higher 5.2 version first.

### 2.3 Supported SIP phones

Listed below are the Epygi Supported SIP phones with the corresponding firmware versions that are tested and recommended for use with QuadroM8L/26x/12Li/26xi SW 5.3.53. All the phones in this list can be automatically configured to work with QuadroM8L/26x/12Li/26xi SW 5.3.53.

Please Note: For the most of phones Quadro supports both the PnP and the auto-configuration options. For some specific phones the auto-configuration option is supported only. Using of the configuration options on each specific SIP phone is described in detail in the Configuring Epygi Supported IP Phones on Quadro document.

Please Note: Any known issues and limitations regarding usage of QuadroM8L/26x/12Li/26xi SW 5.3.53 telephony services and features on these SIP phones are described in detail in the **Quadro Features on Epygi Supported IP Phones** document.

Both mentioned documents are available at <a href="www.epygi.com">www.epygi.com</a> and can be found under the Channel's Portal.

Vendor	Model	Software
snom	300	Application: snom300-SIP 8.4.35
snom	320	Application: snom320-SIP 8.4.35
snom	360	Application: snom360-SIP 8.4.35
snom	370	Application: snom370-SIP 8.4.35
snom	710	Application: snom710-SIP 8.7.3.15
snom	720	Application: snom720-SIP 8.7.3.15
snom	760	Application: snom760-SIP 8.7.3.15
snom	821	Application: snom821-SIP 8.4.35
snom	870	Application: snom870-SIP 8.4.35
snom	MeetingPoint	Application: snomMP-SIP 8.4.35
snom	PA1	8.4.35
snom	m9	9.4.7
Aastra	9143i (33i)	Application version: 2.6.0.2019-SIP
Aastra	9480i (35i)	Application version: 2.6.0.2019-SIP
Aastra	9480iCT(35iCT)	Application version: 2.6.0.2019-SIP
Aastra	6753i	Application version: 2.6.0.2019-SIP
Aastra	6755i	Application version: 2.6.0.2019-SIP
Aastra	6757i	Application version: 2.6.0.2019-SIP

PAGE 2 10-Jul-13

A 1	/757'OT	Application and a 2 / 0 0010 CID
Aastra	6757iCT	Application version: 2.6.0.2019-SIP
Aastra	6730i	Application version: 2.6.0.2019-SIP
Aastra	6731i	Application version: 2.6.0.2019-SIP
Aastra	6737i	Application version: 3.2.2.7137-SIP
Aastra	6739i	Application version: 3.2.2.2088-SIP
Alcatel Temporis	IP200	13.60.0.89
Alcatel Temporis	IP600	14.60.0.89
Alcatel Temporis	IP800	15.60.0.89
Audiocodes	310HD	1.6.0_build_37
Audiocodes	320HD	1.6.0_build_37
Cisco	SPA525G2	7.4.9c
Cisco	SPA303	7.4.9c
Cisco	SPA501G	7.4.9c
Cisco	SPA509G	7.4.9c
Polycom	SoundPoint IP 330SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundPoint IP 331SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundPoint IP 335SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundPoint IP 450SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundPoint IP 550SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundPoint IP 650SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundStation IP 5000*	Application: SIP software 3.3.1.0933
Polycom	SoundStation IP 6000*	Application: SIP software 3.3.1.0933
Polycom	VVX 1500*	Application: SIP software 3.3.1.0933
Polycom	KIRK wireless server 300	PCS08
Polycom	KIRK wireless server 6000	PCS08
Panasonic	KX-TGP550T04	12.17
Panasonic	KX-UT123-B	01.061
Panasonic	KX-UT123NE-B	01.221
Panasonic	KX-UT136-B	01.061
Grandstream	GXP1400	Program- 1.0.4.13
Grandstream	GXP1405	Program- 1.0.4.13
Grandstream	GXP1450	Program- 1.0.4.9
Grandstream	GXP2000	Program- 1.2.5.3
Grandstream	GXP2100	Program- 1.0.4.9
Grandstream	GXP2110	Program- 1.0.4.9
Grandstream	GXP2120	Program- 1.0.4.9
Grandstream	GXP2124	Program- 1.0.4.10
Grandstream	GXV3140	Program- 1.0.7.3
Grandstream	GXV3175	Program- 1.0.3.22
Grandstream	HT286	Program- 1.1.0.26
Grandstream	HT386	Program- 1.0.3.96
Yealink	SIP-T20P	SW version: 9.61.0.85
Yealink	SIP-T22P	SW version: 7.61.0.80
- Julian	1011 1221	344 VOI 310111 710 110100

PAGE 3 10-Jul-13

Yealink	SIP-T26P	SW version: 6.61.0.83
Yealink	SIP-T28P	SW version: 2.61.0.80
Yealink	SIP-T32G	SW version: 32.70.0.100
Yealink	SIP-T38G	SW version: 38.70.0.100
Yealink	VP-2009P	22.21.0.40/22.30.0.60
Yealink	VP-530	23.70.0.40
Yealink	W52P	25.30.0.20
Fanvil	C62	2.2.75.28

Please Note: Quadro IP phones firmware control mechanism will not upgrade snom firmware version from 6.x to 7.x. This should be done manually via snom web site. Once the snom firmware version is 7.x, the Quadro's firmware control will automatically upgrade/downgrade the phone to Epygi's recommended version but not to 6.x.

**Please Note:** In the model's list the Polycom phones with (\*) sign are also presented as **Polycom-xx-Pre-3.3.0** due to backward incompatibility of UCSoftware 3.1.1 configuration. It is recommended to use **Pre-3.3.0** models with Application SIP software 3.2.2.0477.

#### 2.4 Interaction with other Quadro SW releases

QuadroISDN or QuadroFXO external PSTN gateways used in the shared mode should have SW 5.1.12 or higher to achieve maximum feature functionality with the QuadroM8L/26x/12Li/26xi SW 5.3.53.

QuadroFXS 16 Gateway should have SW 5.2.1 or higher for PnP configuration with the QuadroM8L/26x/12Li/26xi SW 5.3.53.

ActiveX Control SW 5.3.0 or higher should be used with 3PCC functions with the QuadroM8L/26x/12Li/26xi SW 5.3.53.

Auto Dialer SW 1.0.5 or higher should be used with the QuadroM8L/26x/12Li/26xi SW 5.3.53.

DCC SW 1.8 or higher should be used with the QuadroM8L/26x/12Li/26xi SW 5.3.53.

Quadro SMR system SW 1.9 or higher should be used with the QuadroM8L/26x/12Li/26xi SW 5.3.53.

To use QuadroM8L/26x/12Li/26xi SW 5.3.53 with a 3pcc or Click2Dial application the "3pcc/Click2Dial Login Allowed" checkbox should be enabled for each extension(s) using this feature.

PAGE 4 10-Jul-13

# 3 New Features History

The table below indicates a high-level list of new features that have been added beginning with the most recent QuadroM8L/26x/12Li/26xi SW release.

Release	New Features
5.3.53	New <b>Overall Calling Time Limit</b> feature. This feature allows a total call duration for all calls to be configured over a specific time frame for each Call Routing entry. Once the total duration has been reached, the entry can be disabled, allowing calls to use the next available route.
	A new feature code for FXS phones. While on a 3-way call, pressing FLASH+0 allows the user to disconnect from the call while the two remaining participants stay connected.
	Added RTP Channel option in the Attendant Ringing Announcement.
	An option in the generalconfig.cgi hidden page was added to remove the "Diversion" header from SIP Invite messages sent out from the Quadro. If an incoming call is being forwarded back to the PSTN, the Quadro will add the "Diversion" header into the outgoing SIP Invite. However, many ITSPs do not support this and reject the call if the
	"Diversion" header is present.  PnP and auto configuration support for new IP phones: Aastra 6737i and Yealink W52P.
5.3.23	A new warning in the security audit for the case when the filtering on the routing rule is enabled, but the Source Call Type is set to anything but PBX.
	New Automatic Fax Receiving Mode.
	A new feature code (*84) for manually configuring and switching no answer call
	forwarding on the phone handset.  PnP and auto configuration support for new IP phones: snom 710, Alcatel Temporis
	IP200/IP600/IP800, Grandstream GXP2124.
	Auto configuration support for new Fanvil C62 IP phone.
	New "URL" functionality in IP Phones advance settings.
	Recording for barge-in call.
	Support for Yealink T2x's hybrid configuration (M7+M1).
5.3.17	Yealink IP phone configuration support enhanced to auto-detect the phone firmware and to provide the proper configuration.
	GUI login for Recording Box extension. The Recording Box extension can be used to access the appropriate Recording Box via Quadro WEB interface by extension name and password.
5.3.12	Support for the new Epygi Desktop Communication Console (DCC) application (with a license key).
	The Caller ID based services are improved by adding the presence state of the extension for use with the DCC application.
	The maximum number of active calls in Find Me/Follow is now configurable. If the number is set to 1 then only one active call will be possible and the next call will go to voice mail. If that number is >1 then the next call will ring the Find Me/Follow phones which are not on a call.
	Added option for the Auto Attendant Customized Scenario to download the generated script in VXML format.
	The Call Recording feature is improved to also allow recording for pass-through calls.
	Added capability to activate Voicemail profile based on caller id and presence state.
	PnP and auto configuration support for new IP phones: snom 720, snom 760, Yealink SIP T32G, Yealink SIP T38G, Yealink VP 530.
	The Zero-Out redirection in the Call Queue settings is modified with a new option to
	redirect the call to the Voice Mail of the extension, or to another destination.
5.3.3	LDAP support for Yealink IP phones.  The Add Multiple Extensions feature is improved which allows the assignment of the IP
0.0.0	Lines to be selected when configuring multiple extensions.

PAGE 5 10-Jul-13

Release	New Features
	A new MS Exchange Server option has been added in the Use External Voice Mail
	settings for extensions. This allows voice messages to be kept in one universal inbox.
5.3.2	The Call Park feature has been expanded with a Directed Call Park method. This allows users to define the call park extension they wish to park the call on.
	There are two methods available: 1) Hold the current call, and then dial the call park
	extension number; 2) Assign the call park extension to a key on the phone and then, just
	press the key during an active call.
	New Call Intercept feature. A new feature code has been added allowing users to dial *94
	followed by the extension number to intercept an inbound call on another extension.
	IP Phone Key Assignment Templates are now available to define a set of extensions
	mapped to keys on IP phones. These templates can be used for multiple IP phones to
	streamline installation and configuration of multiple phones.
	The Find Me/Follow Me announcement message is now customizable. Users can remove
	the message, use the default, define a new recording or use music on hold.
	Added the option to review and modify the system default Find Me/Follow Me welcome
	message like other universal extension messages using the admin *75 feature code on
	the phone.
	Added the option to review and modify the user's personal Find Me/Follow Me welcome
	message like other personal greeting messages using the extensions *0 feature code on
	the phone.
	Added support for P-Asserted-Identity header field defined in RFC 3325. This is important
	to retain original caller information even after a call is transferred within the office.
	The CDR database has been improved adding archiving up to 30 days. Additionally, CDR
	uploading redundancy mechanisms are added to ensure records are not getting lost
	during CDR server downtime or network outage.
	The maximum number of stored CDRs has been increased from 1000 to 3000
	Statistics gathered from the ACD feature and Find Me/Follow Me have been improved for
	greater visibility of call flow.
	A few new options have been added to the GUI based Auto Attendant IVR builder
	integrated into the Quadro IP PBXs. Repeated message play count, repeated message
	timeout duration and timeout after welcome message options are now included in the AA
	IVR builder tool.
	Auto configuration support for new IP phones: Snom m9, Panasonic KX-TGP550T04, KX-UT123-B, KX-UT136-B, Audiocodes 320HD and 310HD.
	A new option to use RTP streaming channel or alternatively, the input from the Audio
	Line IN jack for playing Hold Music is added to the "Universal Extension Recordings"
	configuration page. This allows using an external RTP or analog source as default Hold
	Music for all extensions.
	Intercom settings are improved. Now it will be possible to define whether the phone
	should make a sound when Intercom is activated. The default is silence.
	Call conferencing features are enhanced regarding the Moderator Rights Management,
	conference call terminations options, and the conference statistics.
	Added support for T.38 faxing on IP lines for use on devices such as an ATA for faxing.
	The Maximum recording count option has been restored back in the Recording Box
	Settings.
	The VoIP carrier wizard is improved which allows creating the outbound routing rules not
	only by prefix but also by 7 and 10 digit pattern.
5.2.49	PnP and auto configuration support for Grandstream GXP1400/1405/1450/2100/2110 IP
	phones
	Basic auto configuration support for Polycom KIRK Wireless server 6000 IP phone
	basic auto configuration support for Forgeon Kirk Wheless server 0000 if priorie

PAGE 6 10-Jul-13

Release	New Features
5.2.47	Security enhancement. A new security check has been added to prevent an external 3PCC or Click2Dial application from using any of the Quadro features unless specifically authorized from the user's extension settings. The new option (3pcc/Click2Dial Login Allowed) is displayed when doing an edit on the extension and is disabled by default.  Please note. If the Quadro extension is currently being used with some 3PCC or Click2Dial application, then this option will need to be enabled after the firmware update or the feature will no longer work. Epygi applications that use 3PCC, such as HotCall and HotKeyCall, do not rely on this setting to be enabled to work.  Auto Attendant Customized builder to create Interactive Voice Response (IVR) scenarios from the Quadro GUI.  Support for the new Epygi Auto Dialer application (with a license key).  TDVC and H.263+ codecs support.  Language pack support for Polycom IP phones. Polycom phones change the GUI to the installed custom language.  Local Admin password management enhanced. The local admin login password for GUI access is alphanumeric and a second numerical password can be entered for accessing settings from the phone handset, such as the Auto Attendant greeting messages.
	The Administrator password for phones is added as an item in the security audit.  Auto configuration support for Cisco SPA303, SPA501G, SPA509G, SPA525G2 phones.
	PnP and auto configuration support for Grandstream GXP2120 and GXV3175 phones. PnP support for Grandstream GXV3140 video phone
	PnP and auto configuration support for Yealink VP-2009P model flavor.
	Added the falsealertmsg.cgi hidden page to make timeout for false ALERT message
	configurable. So that Quadro may send to ISDN false ALERT message after some timeout
	(defined in timeout value) if ISDN side does not receive any ringing from Quadros high
5.0.40	level applications.
5.2.40	Support for Video Conferencing (with a license key)
5.2.26	PnP support for Grandstream GXV3140 video phone  New Quadro System Security Management page added with security diagnostics and a
5.2.20	security audit
	Secure system mail allowing to work with TLS or SSL mail servers
	A new option in Call Routing - Local AAA Table: Authentication by PIN code
	Possibility to enable/disable TLS functionality for IP Lines and extensions
	A new option in the extension voice mail settings under the Send new voicemail notifications via e-mail, allowing differentiating between fax messages and voicemail messages when deciding whether or not to receive email notifications, with or without attachments.
	Admin password management enhanced. The admin login password for GUI access is alphanumeric and a second numerical password can be entered for accessing settings from the phone handset, such as the Auto Attendant greeting messages.
	PnP and auto configuration support for snom 821
	PnP and auto configuration support for Aastra 6739i phone
	Auto configuration support for Grandstream GXV3140 video phone
	PnP and auto configuration support for Yealink VP-2009 video phone
	Auto configuration support for snom PA1 paging system
	Polycom KIRK Wireless server 300 phone support
	Call recording soft button implementation for Polycom phones  Downloaded call statistics onbancoments to include detailed information regarding the
	Downloaded call statistics enhancements to include detailed information regarding the used interface for each call (PSTN, ISDN, etc), if call had been forwarded, transferred, etc.
	Viewing the Call Statistics on the Quadro GUI has been updated to select the number of records per page
	Audio-out line support for paging on the QuadroM 8L/26x/12Li/26xi

PAGE 7 10-Jul-13

Release	New Features
	Added the "Audio Line In" option in the "Play Background Music" under the ACD group
	settings
5.2.11	
	Maximum number of IP lines is 96. 32 IP lines are available by default, and two packs of 32 IP lines each to expand.
5.2.7	Full support for Secure RTP (SRTP) to encrypt voice packets.
	Full support for TLS (Transport Layer Security) protocol (RFC 2246) to provide communications privacy for the SIP messaging port over the Internet. The protocol allows client/server applications to communicate in a way that is designed to prevent eavesdropping of the SIP messages.
	HD codecs such as G.722 and G.722.1 are now supported in pass-through mode.
	Security enhancement. Password strength checking has been added in the IP Lines settings table for configuring IP Phones. The system will provide feedback on whether the chosen password is weak. An option is also provided to let the system create a strong, random password. Password strength enforcement can be configured in the hidden menu generalconfig.cgi.
	Security enhancement. Protection against certain SIP DoS attacks has been added by enabling the "SIP IDS" feature in the hidden menu generalconfig.cgi. Enabling this option will automatically block malicious IPs in the firewall.
	Global speed dialing. Configured in Telephony/Call Routing/Global Speed Dial Directory. An Excel .CSV file can be used to upload the entries in the format: Code, Number (e.g. 44, 9726921166). Each entry should be on a new line.
	Emergency Call Interrupt feature in the Caller ID based services. A new feature that will allow specific Caller Ids to be configured so that a call received from one of these
	numbers will immediately disconnect the call in progress and ring the user's extension.  System logging enhancement. If a user encounters a problem while on a phone call the pertinent details related to the call can be saved. The user will dial *82 (getting dialtone and dial *82 from the same or a different phone) as soon as the problem occurs. The details will be saved until the next time someone enters *82. When the systemlogs are downloaded it will contain the details from the most recent *82 entry.
	The voicemail to email option can now be configured in Telephony/Voice Mail Common Settings so that the subject of the email contains a user defined text along with selected system variables (e.g. caller id).
	Option to select the format of FAX in Voice Mail sent by email. Defined in Telephony/Voice Mail Common Settings. TIFF or PDF can be used.
	A prompt to the user is provided with the option to save the system configuration prior to executing a firmware update
	Authorized phones database can now be used with a custom auto attendant scenario.  This allows callers to bypass authentication in custom auto attendants for user's who have been included in the authorized phone database.
	Configurable auto attendant Callback Response Delay allows users to specify a timeout before the system will try to call back the user.
	Configurable auto attendant callback activation timeout from the GUI, which allows activating automatic Call Back for trusted PSTN and SIP callers not after the one - two rings as previously defined, but during the time frame specified in the GUI. So now users can configure the activation timeout in seconds needed to wait for initiating the callback. This configuration is accessible from the hidden menu "extmanagement.cgi".
	Allow the Automatic Callback feature to be used to call back to the originating caller using the "Auto" call type. User can select "Auto" as the "Callback Call Type", while leaving the "Callback Destination" field empty. This will allow to callback to the caller using the Caller ID for callback.
	Quadro FXS gateway PnP support
	Full VLAN support for IP Phones (multiple subnets/DHCP)
	Support for T38 FAX proxy (from standalone IP Phone in the LAN to outside)

PAGE 8 10-Jul-13

T   C   P   II   C   n   P	Yealink IP phone enhancements. PnP and auto configuration support for T20, T22 and T26 models. Advanced button configuration added in the IP Line Settings. Receptionist configuration support for add on modules. A custom logo image can now be displayed. Polycom IP phone enhancements. PnP and auto configuration for Polycom IP335 and P450 models. Advanced button configuration added in the IP Line Settings. Receptionist configuration support for add on modules. Custom data files for Polycom IP phones can now be uploaded from the hidden menu ipphonesdirectory.cgi. PnP and auto configuration for Aastra 6730i phone PnP and auto configuration for snom 870 and snom MeetingPoint Call Forking (Find Me/Follow Me service)
P II c n P	Polycom IP phone enhancements. PnP and auto configuration for Polycom IP335 and P450 models. Advanced button configuration added in the IP Line Settings. Receptionist configuration support for add on modules. Custom data files for Polycom IP phones can now be uploaded from the hidden menu ipphonesdirectory.cgi. PnP and auto configuration for Aastra 6730i phone PnP and auto configuration for snom 870 and snom MeetingPoint
P P	PnP and auto configuration for Aastra 6730i phone PnP and auto configuration for snom 870 and snom MeetingPoint
Р	PnP and auto configuration for snom 870 and snom MeetingPoint
C	Call max duration (disconnecting call after the specified time).
	ACD: zero-out.
	Park slot segmentation (access list for call parking and retrieve)
	Barge-in/Whisper/Listening (*93,*92,*91) (with a license key).
	OHCP support on VLAN (including IP phones VLAN support).
	Shared Voice Mailbox.
	Call routing table debug/tracing tools (new events rise from Routing rule: call failover, fail, success).
Т	The call statistics download in CSV format.
Α	Automatic Call Distribution support (with a license key).
С	Call recording support (with a license key).
	Music on hold can originate from an audio source that is streaming music or broadcasting ive via an IP connection (i.e. internet radio channel).
	The Quadro Call Statistics (CDR) can be automatically sent via email or uploaded to an TFTP or TFTP server.
	While playing back a voice mail the user can rewind (pressing "4") or skip forward (pressing "6"). The amount of seconds to advance or rewind can be optioned for each extension. Default = 3 secs.
C -	Click To Dial (CTD) feature updated to allow calls to be initiated from a Website, connecting two parties together via the Quadro. There are two options to make the call:  Using the HTTP request to specific URI from a third party WEB page or application;  Using a special hidden page on Quadro's WebGUI (in the hidden menu callcontrol.cgi)
S	System events to track IP phones registration status.
A	A custom logo image can be displayed on snom 360, 370 and 820 IP Phones.
S	Speed Dial numbers can now be updated from the phone handset (*76).
C	Outgoing Call Blocking can be updated from the phone handset (*79).
n	Hot Desking feature. This allows a single phone (IP or analogue phone) to be used by many users. Users can login to the Hot Desking phone (*78) using their extension number, and get all the credentials of their extension until they logout (*78).

PAGE 9 10-Jul-13

Release	New Features
	Virtual extensions can be optioned to provide a simulated ring back. The VE can be assigned to a receptionist phone and this option will now give him/her the option to answer the call before it goes to voice mail.
	Zero-out on Auto Attendant.
	Load balancing for the FXO lines (including FXO gateways).
	Easier for extensions to forward their calls to external numbers without compromising the security of Call Routing entries that have the PBX filtering option enabled.
	Possibility for a user to designate a bad call in the system logs by dialing *81 after releasing the bad call.
	Capability to switch via phone the Unconditional Call Forwarding to "ON/OFF" for callers other than "Any/Other callers".
	Random call hunting.
	Capability to choose desired GUI theme on login.
	Capability to Show/Hide extensions attached to disabled IP lines in the Extensions Management.
	Capability to Show/Hide the disabled IP lines.
	Support for Conference Server (with a license key).
	Support for MS OCS and MS Exchange configuration with Quadro.
	SNMP status and configuration.
	The results of system configuration backup & download are reflected in the system events
	snom, Aastra and Grandstream phones automatically reboot when the Quadro is rebooted.
	Possibility to hide/show disabled records in the call routing table.
	Call forwarding configuration through custom Auto Attendant.
	Language pack support for the IP Phones.
	Receptionists' call queue.
	Extension status monitoring.
	Call interception.
	Direct transfer to voicemail.
	Simultaneous ring.

PAGE 10 10-Jul-13

Release	New Features
	Call park.
	Call pickup group.
	Call paging group.
	Plug and play for supported IP phones
	Simplified installation (auto configuration) for tested IP phones.  User rights management.
	Support for an external voicemail system.
	Silence detection on voicemail messages to truncate extended periods of silence.
	QuadroFXO GW and QuadroISDN GW auto configuration.
	Proprietary method for remote extension to bypass certain types of NAT (symmetric RTP).
	Status for registered IP lines and remote extensions.
	Readable transfer statistics.
	New voice mail notifications via e-mail, via phone call and via SMS.
	Universal extension recording (music on hold, VM greetings, incoming/outgoing blocking messages).
	Sending unified fax message from mailbox to fax machine.
	System events reporting.
	Kickback feature on IP lines.
	snom and Aastra phones automatically reboot when the Quadro is rebooted.
	IP phones do not lose registration after Quadro soft reboot (i.e. if the reboot is not initiated by disconnecting/reconnecting the power or pressing the reset button on the back of the Quadro)
	Possibility to upload and customize system messages (in the uploadownmessages.cgi hidden page).
	Attendant ringing announcement for both default and custom AA scenarios.
	Possibility to change the default memory size to be allocated as a temporary storage for unified FAX message (in the extmanagement.cgi hidden page).
	Support for HotCall Add-In for use with Microsoft Outlook.
	SIP address resetting function in the Extensions Management for restoring the default SIP settings of extensions.

PAGE 11 10-Jul-13

Release	New Features
	Possibility to change static, running logos, links and browser mini logo (accessible from loadlogo.cgi hidden page).
	Possibility to change the signaling procedure for hold process in case the "Send Hold Music to Remote Party" is enabled on the extension.
	Voicemail setup wizard to guide new users through the recording of VM greetings.
	SIP trunk.
	3rd party call control (3PCC).
	Flexible numbering plan for extensions.
	Download IP phone FW and reboot of Aastra/snom IP phones.
	Download Quadro directory via XML to snom/Aastra phones.
	Automatic Quadro FW update
	Easier GUI for forwarding lists.
	Terminate a call from Active Calls page.
	Enhanced method for receptionists to watch other extensions, resulting in less networking traffic.
	Distinctive ringing on snom and Aastra IP phones.
	Play custom message instead of ring back tone on Auto Attendant.
	Send EVENTS via SMS.
	CDR tags for billing.
	Enhanced DNS/DHCP settings.
	Daylight savings adjustment.
	SMS and E-mail notification when a call to a given extension has been forwarded.
	Change extension password from phone handset.
	External access to the voice mailbox of users' extensions.
	Automatic backup and download of Quadro configuration.
	QCM centralized licensing included.
	SNMP support for event monitoring.
	Intercom service (for supported IP phones).
	Paging group service (for supported IP phones).

PAGE 12 10-Jul-13

Release	New Features
	Redirection on timeout to the specified address if no action on the AA welcome message.
	AA welcome and menu messages enabling/disabling capability.
	Call queue for virtual extensions.
	Toggling for call routing entries from the handset.
	Retrieve timeout configuration for parked call.
	SDMF caller ID standard.
	Routing rules activity timeout.
	Capability to make SIP calls using TCP as a transport protocol.
	"Client Code Identification" feature on routing rule (with RADIUS enabled).
	Paging support with 3rd party devices.
	Custom profiles for voice mail settings.
	Added silent VM recording option in the Voice Mail Settings.
	PSTN call instant callback.

PAGE 13 10-Jul-13

# 4 Changed Features History

The following table provides a high-level list of changed features that have been changed beginning with the most recent QuadroM8L/26x/12Li/26xi SW release.

5.3.53	Added display names after extension numbers in the Many Extension Ringing Groups,
	allowing users to easily find the desired extension.
	Added display names after extension numbers in the Auto Attendant "Create Scenario"
	page, allowing users to easily find the desired extension.
	The Grandstream GXP2124 phone is added to the phone model list for the Receptionist
	Configuration Wizard.
	The behavior for the announcement that informs callers that the call is being recorded has
	been changed so that the announcement is no longer captured in the recorded file.
	Added VoIPVoice.it as a new carrier to the VoIP Carrier Wizard list.
	Improvement on "Caller ID Based Services" page. Now user is able to navigate to the
	appropriate setting by clicking the links on the ON/OFF status of the service.
	When configuring an IP phone in the IP Line settings, it is now possible to paste a copied
	MAC address for the IP phone.
	Changed the behavior when making changes to parameters that require the IP phone to
	be rebooted to take effect. The system will prompt to reboot the IP phones after changing
	the SRTP policy, IP phones template, transport type, and the registration username and
	password.
	The IP Lines Settings table is now scrollable. Disabled IP lines are hidden from the list by
	default.
	Improved the way Day/Time settings are shown on the Call Routing GUI. When there is no
	rule with Time of Day set, the DT column and the DT description in the glossary are
	removed from the bottom of the page. Also, the Call Routing Table's brief view will now
	show an icon of a clock in the DT column.
	The "VLAN Settings" page has been moved from "DHCP Settings for the VLAN
	Interface" as a submenu to the <b>Network</b> in the main menu.
	Added Use RTP proxy mode in Call routing for PBX type calls.
	Improved the GUI for Recording Box; recordings are displayed as tabbed page (1000
	recordings per page).
	snom PA1 template enhancement: "Intercom Policy" has been added for snom PA1. Its
	default value is set to "off".
	Distinctive Ring tones have been changed for Yealink phones.
	snom 7xx phones (720 & 760) have been upgraded to FW version 8.7.3.15.
	Recommended FW version for Yealink T3X and VP530 phones is updated to public Version
	70 (3x.70.0.100/23.70.0.40 accordingly).
5.3.23	New FW recommendations for Aastra , Grandstream, Cisco and Yealink IP phones.
	Added Speed dial based services for Polycom.
	Added "Park", DirPckUp, " BargeIn" soft keys on Polycom UCSoftware.3.3.1 or higher.
	Language Pack update for Aastra, Alcatel, Grandstream GXP2000 and Polycom (FW
	3.3.1.F) IP phones.
	Voice mail <b>Specific Profile</b> selection is simplified using the drop-down list of the created
	profiles.
	Aastra IP phone template enhancements: Added Callers List Script field, Call Waiting/
	Hold Reminder/Stutter Tones and Password protected "Options" checkboxes.
	Restored the "Edit Watch Access List" link in the extension settings.
5.3.17	Yealink T2x phones default settings updated.
	Call statistics archive mechanism improved to support fast and accurate loading. The
5.3.12	maximum number of records in a page is limited to 500. Added "Clear all Records" button.  Archiving should run if the maximum record count. 2,000 is reached even if the method.
	Archiving should run if the maximum record count – 3 000 is reached even if the method
	of collecting is set to "Archive by time interval".

PAGE 14 10-Jul-13

	All preconfigured functions have been removed from Aastras' Programmable Keys				
	Configuration.				
	Improved the voice message played when collecting the user logs using feature code				
	Improved the voice message played when user marks the call using feature code *81				
	The timeout for the directed Call Park method is changed from two seconds to five				
	seconds. To park a call, put the call on Hold and dial the Call Park extension number. This				
	needs to be done within the five second timeout. If the five second timeout is exceeded,				
5.3.3	then the Quadro will consider it as an attempt for retrieving the parked call. Once the call				
	is parked, it can also be retrieved by dialing the same Call Park extension.				
	New FW recommendations for snom phones.				
	Some of the system voice messages are improved.				
	Added the option to delete the uploaded global speed dialing directory				
F 2 2	Added Kebu.it as a new carrier to the VoIP Carrier Wizard list				
5.3.2	The name of <b>Login/Call Relay</b> column in the Extensions Management is changed to				
	External Access, which indicates whether the GUI login, 3pcc/Click2Dial login or Call				
5.2.49	Relay options are enabled on the extension.				
5.2.49	New FW recommendations for snom, Grandstream and Polycom phones.				
	The maximum number of Successful Call Statistics has been increased from 1000 to 10000 when a CF card is installed.				
	Added option in ACD configuration to prevent the calls to agent in target group during				
	selected period.				
	Added information regarding video codec's under the Details in the call statistics				
	Added P-asserted identity header in all SIP messages that contain "p-preffered identity" or				
5.2.47	"Remote-party-ID".				
	Changed the SIP parser for proper processing of From: field in header if URI scheme is				
	included.				
	The SIP IDS configuration options are available in the SIP IDS settings page.				
	The "3pcc/Click2Dial Login Allowed" checkbox is available when editing multiple extensions				
	at the same time.				
	Multiple SMS numbers can be allowed in SMS destination fields, separated by SMS provider				
F 0 40	required delimiter (the comma for Clickatell)				
5.2.40	The SoTel SIP trunk is modified in the VoIP Carrier Wizard				
	The Skype service is added in the VoIP Carrier list				
	The Call Recording settings page is updated with a second, more simplistic method for				
	enabling extensions. Either of two modes can be used: Basic view and Advanced view.				
	Improvements in Call Recordings FTP retransmission mechanism.				
	Extension Login permission to access the Quadro GUI. The login is disabled by default for				
	all extensions.				
	Multiple DHCP subnet support (two subnets allowed instead of one, making it possible to				
	have about 500 devices getting DHCP from Quadro).				
	LMR (Land Mobile Radio) support for QuadroM (E1/T1 to IP gateway capable of taking a				
5.2.26	channelized T1 to Multicast RTP IP streams by DS0 for use in a Radio over IP network).				
	The "Send Hold Music to remote IP party" is enabled by default in the Basic services for				
	extensions.				
	The Developer Logging is enabled by default.				
	The SIP Server text field is changed to empty by default for auto attendant (00) and two				
	FXS extensions.				
	The default for "Maximum recording duration" is changed to 1 hour in the "Recording box				
	settings" and "Call recording settings".				
	The Secure RTP options in the Extension Codecs are available when editing multiple extensions at the same time.				
	EXICUSIONS AT THE SAME TIME.				
5.2.11					
F 2 7					
5.2.7					

PAGE 15 10-Jul-13

# **5 Fixed Issues**

Issues fixed since version 5.3.23:

The FXS	ports labeled Phones 1 and 2 are swapped
D:	The FXS port labeled Phone 1 on the front panel of the QuadroM8L(QuadroM26x) is actually configured as FXS Line 2. Phone 2 is configured as FXS Line 1.
C:	<b>Note.</b> After updating to 5.2.26 the FXS ports assignments will still be swapped with Phone 1 internally configured as FXS Line 2 and Phone 2 configured as FXS Line 1. Performing a factory reset on the system will correct the port assignments so that Phone 1 is FXS Line 1 and Phone 2 is FXS Line 2. However, the configuration will be lost. If the system is already configured the factory reset should not be done and the RJ-11 cables can remain swapped between Phone 1 and Phone 2.
	vice on the Quadro doesn't work with the pre-defined Clickatell SMS
gateway	17794
D:	The new secure transporting method used by Clickatell is not supported on the Quadro currently.
C:	
It's impossible to auto configure Panasonic IP phones with Quadro through VLAN 17766	
D:	
C:	

PAGE 16 10-Jul-13

# 6 Known Issues

D: DescriptionC: Consequences

Fix: How to avoid the situation, or what to do in case the situation has occurred.

It is im	possible to login as 'admin' after making changes on "Advanced PPP
	possible to logili as admin after making changes on Advanced FFF 9549
D:	You cannot login to the Quadro as 'admin' after making changes on the
D.	"Advanced PPP Settings" page. You can only login as 'user'.
C:	No consequences
Fix:	Restart the Quadro to resolve this.
One wa	ay audio with IPSec VPN in the scenario "Gateway<->Remote Subnet"
	9327
D:	Scenario:
	1. Establish an IP-Sec connection between two Quadros (connection type is
	"Quadro <-> Remote Subnet").
	2. Make an SIP call from Quadro1 (gateway) to Quadro2 (remote subnet).
C:	The call is established, but there is no audio in Quadro1. The same result will
	occur when calling from Quadro2 to Quadro1.
	A direct call cannot be established at all.
Fix:	Add an additional "Quadro <> Remote Gateway" tunnel in IPSec configuration.
	With two tunnels: "Quadro <> Remote Gateway", "Quadro <> Remote Subnet"
	in IPSec VPN configuration this issue will resolved.
Call int	erception fails in a specific scenario with a watched extension in the many
	ion ring list 9399
D:	Scenario:
	1. Use snom360 for receptionist extension (for example, extension #31),
	2. Configure Many Extension Ringing on ext. #31 with extensions #31 and
	#12 in the MER list,
	3. Configure extensions #11 and #12 as watched extensions,
	4. Make a call to extension #31,
	5. The phones for extensions # 31 and #12 will start ringing.
	6. The programmable key for the ext. #12 is flashing on the receptionist's ext.
	#31,
	7. Pressing that key the receptionist stops ringing, but ext. #12 is still ringing,
	8. Hang-up the phone for that caller's extension.
C:	Call interception on the receptionist's line fails. The light for ext. #11 will stay ON
	on the ext. #31.
Fix:	This problem is specific for snom phones only. When using a snom phone, calls
	should be answered on your own extension and not the watched extension.
	and the time that enterior
Firmwa	are update cannot be completed when "High availability" is enabled in SIP
Setting	
D:	Scenario:
υ.	1. Using SIP Timers radio button in Telephony-SIP Settings, define the
	timeouts of the SIP messages retransmission as "High availability".
	2. Try to make firmware update.
C:	
	Firmware update will hang and not complete
Fix:	Set the SIP Timer to RFC3261 standard before firmware update. Under
Δ	investigation, will be fixed in the future releases.
An issu	ie with configuring IP phones as local extensions for Quadro IP PBX
-	13471
D:	Plug and Play and Auto configuration of IP phones is impossible with the modified
	"HTTP Server Port" on the Quadro.

PAGE 17 10-Jul-13

C:	
Fix:	Add the changed http port value in the "option tftp-server-name" row ("dhcpd.conf.lan" file) for each IP phone. Example: "option tftp-server-name "http://172.30.38.1:8080". Will be fixed in the future releases.
	of the Quadro voice mail services could be unavailable if external Voice Mail se for extension 12190
D:	In this scenario some of the features, for example Zero-out and entering the VMS directly with option "1" will not work.
C:	
Fix:	This is normal, as those features are the Quadro's internal VMS system features.  If external VMS system is used, user gets the features of that external system.
	Aastra, Grandstream and Thomson IP phones may disconnect if you press button for a long time (60 min)
D:	
C:	
Fix:	Under investigation, will be fixed in the future releases.
	IP phone is not ringing when it is used in many extensions ringing list 13830
	Scenario:  1. Many extension ringing is enabled on a virtual extension with an Aastra phone in the list
	2. Distinctive Ringing is enabled on that virtual extension with Nickname that contains space
C:	When a call with no Caller ID comes to that extension, the Aastra phone in many extensions ringing list does not ring.
Fix:	The problem is solved if there is a Caller ID available on the incoming call or if the Nickname doesn't contain spaces. This problem is limited to Aastra IP phones only.
An issu	ue with configuring Aastra IP phones as local extensions for Quadro IP PBX 13802
D:	After changing the LAN IP address for the Quadro the 480i, 9133i and 55i Aastra phones with currently recommended 1.4.1.2000 firmware are not registering after restart.
C:	
Fix:	They must be factory reset to register again. Under investigation. Will be fixed in the future FW versions for Aastra phones.
An issu	ue with distinctive ringing on the snom, Aastra and GrandStream IP phones 11519
D:	snom, Aastra and GrandStream phones ring only once if the distinctive ringing is enabled with the "winter" ringing pattern.
C:	No consequences
Fix:	Use other ringing patterns for distinctive ringing on these IP phones.
	terception doesn't work on GrandStream GXP2000 configured as a ionist, when extensions are watched on expansion module 14797
D:	
C:	
Fix:	Use basic 7 keys instead of expansion module. Will be fixed in the future releases.
Paging	and intercom services do not work on the GrandStream BT100 IP phone 14909
D:	
C:	
Fix:	Currently BT100 has no support for paging/intercom.

PAGE 18 10-Jul-13

IP pho	ne doesn't go back to the normally idle state automatically when t	he
-	ing had been started via the Record button and the call was releas	
D:	The "Recording started" message remains on the phone screen after on	
	parties terminate the call by going on-hook.	
C:	Only incoming calls to IP phone are possible in this state.	
Fix:	Need to use "Exit" button to retrieve the IP phone functionality. Will be	fixed in the
, .,	future releases.	
It is no	ot impossible to pickup (via pickup group) the call to extension wit	h
FindMe	e/FollowMe enabled	15942
D:		
C:		
Fix:	Will be fixed in the next releases.	
A prob	lem with incoming Secure RTP call in a specific scenario	16533
D:	When incoming Secure RTP call is connecting to the destination via Call	Routing
	table, Quadro always tries to connect it as an un-secure call and the cal	l is being
	dropped due to the media parameters incompatibility.	
C:		
Fix:	Will be fixed in the next releases.	
An issu	ue with wrongly displayed "Start Recording" message in the Active	e Calls 16184
D:	The recording type is set to "start automatically"; the number of allowed	d parallel
	call recordings is exhausted, therefore the recording for the next call ca	
	started, but the "Start Recording" is wrongly shown in the Active Calls p	
C:	The state of the s	9
Fix:	Will be fixed in the next releases.	
	e/follow me doesn't work for incoming Secure RTP call	16683
D:	Though the call came with SRTP option the FM/FM is making unsecure	
C:	As a result the call isn't established	<u> </u>
Fix:	Will be fixed in the next releases.	
The co	nfiguration page for Expansion Module is missing when configuring the T26 as receptionist phones	g Yealink 16971
D:	In Receptionist Management wizard the Expansion module configuration	
D.	are not available for Yealink T28 and T26 phones.	ii pages
C:	are not available for realitik 128 and 120 phones.	
	Will be fixed in the next releases	
Fix:	Will be fixed in the next releases.	\ ID
	hanging Quadro LAN IP configuration (IP address or subnet mask)	
-	s lose registration and become unusable	16037
D:		
C:	After the color of a Constant LANLID configuration for the chartest the Constant the	
Fix:	After changing Quadro LAN IP configuration first reboot the Quadro the the IP phones. Will be fixed in the next release.	n reboot
An issi		17282
D:	When the snom phone of 8xx series (tested with snom phones 821, 87	
D.	FW version's 8.4.32, 8.4.33) have some watching configured for it's full	
	keys and the status of the watching resource is changed (e.g. the watching resource)	
	phone receives or makes a call), immediately the next intercom call to	•
	phone doesn't activate the intercom but continuously ring the phone.	
C:	As a result, if the calling phone is configured as a watched extension, t	he snom
	phone never activates the intercom for that caller.	
Fix:	Will be fixed in some future FW release for snom.	
		16784
D:	Local authentication configured in the Local AAA table by User Login or	
	code is ignored for the following call scenario; a SIP call to Quadro Auto	•
	Attendant, then call to a SIP destination.	-
	the state of the s	

PAGE 19 10-Jul-13

C: Quadro doesn't ask for authentication in this case.  Fix: Will be fixed in the next release.  The snom phone doesn't allow multiple call park/retrieve 17340  D: Upon successful call park/retrieve on snom phone using programmable key, the call couldn't be parked again on the same call park extension.  C: Will be fixed in some future FW release for snom.  Call which is done after Call Relay(*2) on auto attendant isn't shown in call statistics 17404  D: Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first.  C: Fix: Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases.  Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the *Shared VMail Ext. xxx* option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox. Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails.  T555  Using Call Intercept to directly answer an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: Recording announcement message doesn't play even though the recording indication is selected in the next releases.  Conference recording announcement message doesn't play even though t			
The snom phone doesn't allow multiple call park/retrieve  D: Upon successful call park/retrieve on snom phone using programmable key, the call couldn't be parked again on the same call park extension.  C: Pix: Will be fixed in some future FW release for snom.  Call which is done after Call Relay(*2) on auto attendant isn't shown in call statistics  D: Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first.  C: Fix: Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases.  Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, In the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call falls.  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94) + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Pix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings  T7709  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement message doesn't work  T229  Recording announcement message doesn't body the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.	C:	Quadro doesn't ask for authentication in this case.	
D: Upon successful call park/retrieve on snom phone using programmable key, the call couldn't be parked again on the same call park extension.  C: Fix: Will be fixed in some future FW release for snom.  Call which is done after Call Relay(*2) on auto attendant isn't shown in call statistics.  D: Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first.  C: Fix: Use feature code *1 instead of *2 for call relay, Will be fixed in the next releases.  Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recordin	Fix:		
call couldn't be parked again on the same call park extension.  C: Fix: Will be fixed in some future FW release for snom.  Call which is done after Call Relay(*2) on auto attendant isn't shown in call statistics  D: Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first.  C: Fix: Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases.  Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration  16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  C: Fix: Will be fixed in the next releases.  C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version or GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement message doesn't boys even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li		· · · · · · · · · · · · · · · · · ·	
C: Will be fixed in some future FW release for snom.  Call which is done after Call Relay(*2) on auto attendant isn't shown in call statistics  D: Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first.  C: Fix: Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases.  Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration  Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Hanging up the call from caller to "direct pickup", leaves an active call.  C: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Fix: Will be fixed in the next releases.  The georetic for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement message doesn't laye even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  Dow	D:		e
Fix: Will be fixed in some future FW release for snom.  Call which is done after Call Relay(*2) on auto attendant isn't shown in call statistics  D: Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first.  C:	_	call couldn't be parked again on the same call park extension.	
Call which is done after Call Relay(*2) on auto attendant isn't shown in call statistics    Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first.  C: Filx: Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases.  Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  C: C:  Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C:  Fix: Will be fixed in the next releases.  Conference recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Hill be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17			
D: Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first.  C: Fix: Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases. Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784			
D: Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first.  C: Fix: Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases. Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: Recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784			
relay is missing in the call statistics in case if the external caller is Terminating the call first.  C: Fix: Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases.  Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  C c: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  C- Fix: Will be fixed in the next releases.  C- Fix: Will be fixed in the next releases.  C- Fix: Will be fixed in the next releases.  C- Fix: Will be fixed in the next releases.  D- Fix: Will be fixed in the next releases.  C- Fix: Will be fixed in the next releases.  D- Fix: Will be fixed in the next releases.  D- Fix: Will be fixed in the next rel			
the call first.  C:   Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases.  Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D:   Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C:   However, in the IP Line settings, the "Shared VMail Ext. xxxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix:   Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D:   When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C:   Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D:   C:   Fix:   Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D:   C:   Fix:   Will be fixed in the next releases.  Conference recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C:   Fix:   Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784	<i>υ</i> .		
C:   Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C:   Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C:   Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C:   Will be fixed in the next releases.  Conference recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C:   Fix:   Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration   17784			
Fix: Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases.  Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	C:	the dan mat.	
Shared Mailbox watching doesn't work when using "Allow access to Shared Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C:  Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C:  Fix: Will be fixed in the next releases.  Conference recording announcement ages doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C:  Fix: Will be fixed in the next releases.		Use feature code *1 instead of *2 for call relay. Will be fixed in the next releas	es.
Mailbox for enabled extensions" option in Many Extension Ringing configuration 16635  D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call I Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			
D: Extension has Many Extension Ringing enabled with a few extensions configured for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 1755  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		ox for enabled extensions" option in Many Extension Ringing configuration	1
for Shared Mailbox.  C: However, in the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code ("94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C:  Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C:  Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	D:		-d
C: However, in the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C:  Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C:  C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 1729  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C:  Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	<i>υ</i> .		Ju
in the drop down list for Advanced-Programmable Keys Configuration.  Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 1755  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C:  Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C:  Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	C:		ed.
Fix: Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases.  Using Call Intercept to directly answer an incoming ACD call fails. 17555  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C:  Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C:  Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C:  Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	•		
Using Call Intercept to directly answer an incoming ACD call fails.  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C:  Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C:  Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	Fix:		ох
Using Call Intercept to directly answer an incoming ACD call fails.  D: When ACD calls to an extension of an agent and Call Intercept is used from another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C:  Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C:  Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		Settings for extension. Will be fixed in the next releases.	
another extension to answer the call with the feature code (*94 + extension number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C:  Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D:  C:  Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D:  C:  Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C:  Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D:  C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	Using		
number), the caller hears nothing and the incoming call continues ringing. Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			
Hanging up the call from caller to "direct pickup", leaves an active call.  C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		another extension to answer the call with the feature code (*94 + extension	
C: Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		number), the caller hears nothing and the incoming call continues ringing.	
Fix: Will be fixed in the next releases.  The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D: C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		Hanging up the call from caller to "direct pickup", leaves an active call.	
The Programmable Keys don't function on Grandstream GXP2124 phone if configured using Line Keys in IP line Advanced Settings 17709  D:  C:  Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D:  C:  Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C:  Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D:  C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			
C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			
D: C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		· ·	
C: Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work  17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration  17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		ured using Line Keys in IP line Advanced Settings 17709	
Fix: Use Multi-Purpose Keys when programming Keys. Will be fixed in some next FW version for GXP2124.  Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work  T7229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration  T7784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			
Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		Has Multi Dumage Kaya when programming Kaya Will be fived in some payt	<b></b>
Extension watching doesn't work on Fanvil C62 phone  D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	FIX:		ΓVV
D: C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	Extens		
C: Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work 17229  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		promo	
Fix: Will be fixed in the next releases.  Conference recording announcement doesn't work  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration  D: C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			
Conference recording announcement doesn't work  D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		Will be fixed in the next releases.	
D: Recording announcement message doesn't play even though the recording indication is selected in the conference recording settings to inform participants that the conference recording is started.  C:  Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D:  C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			
indication is selected in the conference recording settings to inform participants that the conference recording is started.  C:  Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration  D:  C:  Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			
that the conference recording is started.  C: Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			3
Fix: Will be fixed in the next releases.  The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			
The ISDN settings are not accessible on the QuadroM12Li in factory default configuration 17784  D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	C:		
configuration17784D:C:C:Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.	Fix:	Will be fixed in the next releases.	
D: C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			_ <b></b>
C: Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.		17704	
Fix: Downgrade FW to some lower (let say to 5.3.17), then upgrade to 5.3.23 again.			
, , , , , ,		Downgrade FW to some lower (let say to 5.3.17), then ungrade to 5.3.23 again	,
	11/4	Will be fixed in the next release.	••

PAGE 20 10-Jul-13

# 7 Upgrading Instructions

## 7.1 Technical Advisory

**Attention:** For manually configured IP phones, it is now required to have the **SIP Registration Timeout** parameter set to 120 seconds or more on your IP phone. Values less than 120 seconds will not be accepted by the Quadro and will cause the IP phone registration failure on the Quadro.

## 7.2 Quadro SW requirements for upgrading to 5.3

**Attention:** The software upgrade to 5.3 can **ONLY** be done from 5.2.47 and higher 5.2 versions. Before updating to 5.3 the unit should be updated to 5.2.47 or higher 5.2 version first.

#### 7.3 General hints

It is recommended to execute the update by downloading the software first to a PC located in the LAN side of the Quadro and perform the firmware update from the LAN side. This is to ensure that the Internet connection will not affect the upgrade process.

In general, the configuration of a system will remain after the software update. Remember that some data is lost during upgrade:

- Call Statistics (only when embedded memory storage is used)
   Workaround to save the existing call statistics, download it to the PC from Call Statistics-Statistics Settings before performing the firmware update. It is also recommended to use an external Compact flash memory to keep the call statistics safe.
- Voice mails (only when embedded memory storage is used)
   Workaround save the recorded voice mails from the Voice Mailbox before performing the firmware update. It is also recommended to use an external Compact flash memory to keep the voice mails safe.
- Call recordings (only when embedded memory storage is used)
   Workaround save the recorded calls from the Recordings Box before performing the firmware update or use the recorded calls automatically upload to the FTP server option. It is also recommended to use an external Compact flash memory to keep the voice mails safe.
- All custom voice greetings (only when embedded memory storage is used)
   Workaround backup and download all configuration and voice data to a PC. It is also recommended to use an external Compact flash memory to keep the custom voice messages safe
- All custom recordings for the custom Auto Attendant (only when embedded memory storage is used)
   Workaround – backup and download all configuration and voice data to a PC. It is also recommended to use an external Compact flash memory to keep the custom recordings safe.
- Pending events (only when embedded memory storage is used)
- Transfer statistics for the network
- DHCP leases

The following steps describe how to correctly perform the firmware update:

PAGE 21 10-Jul-13

- 1. Save the current configuration by doing a Backup and Download of all config and voice data (System->Configuration Management->Backup and download all config and voice data).
- 2. Perform the Firmware Update.
- 3. Is there a Compact Flash memory card installed?
  - Yes No further action is required
  - No Restore the configuration that was saved in Step 1 (System -> Configuration Management -> Upload and Restore all config and voice data).
     This is necessary to restore the extension custom voice messages and the custom Auto Attendant messages.

**Attention**: Always power down the Quadro before inserting/removing any Compact Flash card. The largest recommended Compact Flash card is 8GB.

#### 7.4 Limitations and restrictions

- The memory used by "DSP Capture", "Call Capture" and "Network Capture" hidden pages is limited to 3 MB. This will put a limitation on the duration of captured file
- In case if voice mail recording codec is other than PCMU, the maximum length of VM sent by email is limited to 3 minutes
- The number of VMs in the mailbox for one extension is limited to 300
- Use Session Timer in IP Line Settings is deselected by default

PAGE 22 10-Jul-13