

Release Note QuadroM8L/26x/12Li/26xi 5.3.2, Edition 1

THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY INFORMATION OWNED BY EPYGI TECHNOLOGIES LTD. ANY COPYING, USE OR DISCLOSURE OF THE DOCUMENT OR THE INFORMATION CONTAINED HEREIN WITHOUT THE WRITTEN PERMISSION OF EPYGI TECHNOLOGIES LTD. IS STRICTLY PROHIBITED.

THIS DOCUMENT IS PROVIDED TO YOU FOR INFORMATIONAL PURPOSES ONLY. The information furnished in this document, believed by Epygi Technologies to be accurate as of the date of publication, is subject to change without notice. Epygi Technologies assumes no responsibility for any errors or omissions in this document and shall have no obligation to you as a result of having made this document available to you or based upon the information it contains.

Epygi is a registered trademark of Epygi Technologies, Ltd. All other products and services are the registered trademarks of their respective holders

1 Introduction

This Release Note describes hardware and software requirements to use with the

QuadroM8L/26x/12Li/26xi software 5.3.2 Date: February 20, 2012

Additional enhancements, bug fixes and known issues incorporated in this software will be listed as known.

Date: February 27, 2012

2 Requirements

2.1 Hardware requirements

- The software can be used on QuadroM8L/26x/12Li/26xi models.
- The model name is written on the back plate of the unit, and the model number is on the bottom label.

2.2 Software requirements

A software upgrade can be made from 5.2.7 or later software.

2.3 Supported and Tested SIP phones

Listed below are the Epygi Supported SIP phones with the corresponding firmware versions that are tested and recommended for use with QuadroM8L/26x/12Li/26xi SW 5.3.2.

Vendor	Model	Software
snom	300	Application: snom300-SIP 8.4.32
snom	320	Application: snom320-SIP 8.4.32
snom	360	Application: snom360-SIP 8.4.32
snom	370	Application: snom370-SIP 8.4.32
snom	821	Application: snom821-SIP 8.4.32
snom	870	Application: snom870-SIP 8.4.32
snom	MeetingPoint	Application: snomMP-SIP 8.4.32
Aastra	9143i (33i)	Application version: 2.5.2.1010
Aastra	9480i (35i)	Application version: 2.5.2.1010
Aastra	9480iCT (35iCT)	Application version: 2.5.2.1010
Aastra	6753i	Application version: 2.5.2.1010
Aastra	6755i	Application version: 2.5.2.1010
Aastra	6757i	Application version: 2.5.2.1010
Aastra	6757iCT	Application version: 2.5.2.1010
Aastra	6730i	Application version: 2.5.2.1010
Aastra	6731i	Application version: 2.5.2.1010
Aastra	6739i	Application version: 3.0.1.38

Please Note: Any problems and limitations on these SIP phones are described in detail in the Quadro Features on Supported IP Phones document.

Please Note: Quadro IP phones firmware control mechanism will not upgrade snom firmware version from 6.x to 7.x. This should be done manually via snom web site. Once the snom firmware version is 7.x, the Quadro's firmware control will automatically upgrade/downgrade the phone to Epygi's recommended version but not to 6.x.

Listed below are the Epygi Tested SIP phones with the corresponding firmware versions that are tested and recommended for use with QuadroM8L/26x/12Li/26xi SW 5.3.2. Any problems and limitations on these SIP phones are described in detail in the **Quadro Features** on **Tested Phones** document.

PAGE 2 27-Feb-12

Vendor	Model	Software
Audiocodes	310HD	1.6.0_build_37
Audiocodes	320HD	1.6.0_build_37
Cisco	SPA525G2	7.4.8
Cisco	SPA303	7.4.8
Cisco	SPA501G	7.4.8
Cisco	SPA509G	7.4.8
Polycom	SoundPoint IP 330SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundPoint IP 331SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundPoint IP 335SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundPoint IP 450SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundPoint IP 550SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundPoint IP 650SIP*	Application: SIP software 3.3.1.0933
Polycom	SoundStation IP 5000*	Application: SIP software 3.3.1.0933
Polycom	SoundStation IP 6000*	Application: SIP software 3.3.1.0933
Polycom	VVX 1500*	Application: SIP software 3.3.1.0933
Polycom	KIRK wireless server 300	PCS08
Polycom	KIRK wireless server 6000	PCS08
Panasonic	KX-TGP550T04	12.17
Panasonic	KX-UT123-B	01.061
Panasonic	KX-UT136-B	01.061
snom	PA1	8.4.32
snom	m9	9.4.7
Grandstream	GXP1400	Program- 1.0.1.83
Grandstream	GXP1405	Program- 1.0.1.83
Grandstream	GXP1450	Program- 1.0.1.83
Grandstream	GXP2000	Program- 1.2.5.3
Grandstream	GXP2100	Program- 1.0.1.83
Grandstream	GXP2110	Program- 1.0.1.83
Grandstream	GXP2120	Program- 1.0.1.83
Grandstream	GXV3140	Program- 1.0.7.3
Grandstream	GXV3175	Program- 1.0.3.22
Grandstream	HT286	Program- 1.1.0.26
Yealink	SIP-T20P	SW version: 9.50.0.50
Yealink	SIP-T22P	SW version: 7.50.0.50
Yealink SIP-T26P		SW version: 6.50.0.50
Yealink	SIP-T28P	SW version: 2.50.0.50
Yealink	VP-2009P	22.21.0.40/22.30.0.60

Both mentioned documents are available at www.epygi.com and can be found under the Channel's Portal.

Please Note: In the model's list the Polycom phones with (*) sign are also presented as **Polycom-xx-Pre-3.3.0** due to backward incompatibility of UCSoftware 3.1.1 configuration. It is recommended to use **Pre-3.3.0** models with Application SIP software 3.2.2.0477.

PAGE 3 27-Feb-12

2.4 Interaction with other Quadro SW releases

QuadroISDN or QuadroFXO external PSTN gateways used in the shared mode should have SW 5.1.12 or higher to achieve maximum feature functionality with the QuadroM8L/26x/12Li/26xi SW 5.3.2.

QuadroFXS 16 Gateway should have SW 5.2.1 or higher for PnP configuration with the QuadroM8L/26x/12Li/26xi SW 5.3.2.

ActiveX Control SW 5.3.0 or higher should be used with 3PCC functions with the QuadroM8L/26x/12Li/26xi SW 5.3.2.

Auto Dialer SW 1.0.5 or higher should be used with the QuadroM8L/26x/12Li/26xi SW 5.3.2.

Quadro SMR system SW 1.9 or higher should be used with the QuadroM8L/26x/12Li/26xi SW 5.3.2.

To use QuadroM8L/26x/12Li/26xi SW 5.3.2 with a 3pcc or Click2Dial application the "3pcc/Click2Dial Login Allowed" checkbox should be enabled for each extension(s) using this feature.

PAGE 4 27-Feb-12

3 New Features History

The table below indicates a high-level list of new features that have been added beginning with the most recent QuadroM8L/26x/12Li/26xi release.

Release	New Features
5.3.2	The Call Park feature has been expanded with a Directed Call Park method. This allows users to define the call park extension they wish to park the call on. There are two methods available: 1) Hold the current call, and then dial the call park extension number; 2) Assign the call park extension to a key on the phone and then, just press the key during an active call.
	New Call Intercept feature. A new feature code has been added allowing users to dial *94 followed by the extension number to intercept an inbound call on another extension.
	IP Phone Key Assignment Templates are now available to define a set of extensions mapped to keys on IP phones. These templates can be used for multiple IP phones to streamline installation and configuration of multiple phones.
	The Find Me/Follow Me announcement message is now customizable. Users can remove the message, use the default, define a new recording or use music on hold. Added the option to review and modify the system default Find Me/Follow Me welcome
	message like other universal extension messages using the admin *75 feature code on the phone.
	Added the option to review and modify the user's personal Find Me/Follow Me welcome message like other personal greeting messages using the extensions *0 feature code on the phone.
	Added support for P-Asserted-Identity header field defined in RFC 3325. This is important to retain original caller information even after a call is transferred within the office.
	The CDR database has been improved adding archiving up to 30 days. Additionally, CDR uploading redundancy mechanisms are added to ensure records are not getting lost during CDR server downtime or network outage.
	The maximum number of stored CDRs has been increased from 1000 to 3000 Statistics gathered from the ACD feature and Find Me/Follow Me have been improved for greater visibility of call flow.
	A few new options have been added to the GUI based Auto Attendant IVR builder integrated into the Quadro IP PBXs. Repeated message play count, repeated message timeout duration and timeout after welcome message options are now included in the AA IVR builder tool.
	Auto configuration support for new IP phones: Snom m9, Panasonic KX-TGP550T04, KX-UT123-B, KX-UT136-B, Audiocodes 320HD and 310HD.
	A new option to use RTP streaming channel or alternatively, the input from the Audio Line IN jack for playing Hold Music is added to the "Universal Extension Recordings" configuration page. This allows using an external RTP or analog source as default Hold Music for all extensions.
	Intercom settings are improved. Now it will be possible to define whether the phone should make a sound when Intercom is activated. The default is silence.
	Call conferencing features are enhanced regarding the Moderator Rights Management, conference call terminations options, and the conference statistics.
	Added support for T.38 faxing on IP lines for use on devices such as an ATA for faxing. The Maximum recording count option has been restored back in the Recording Box Settings.
	The VoIP carrier wizard is improved which allows creating the outbound routing rules not only by prefix but also by 7 and 10 digit pattern.
5.2.49	PnP and auto configuration support for Grandstream GXP1400/1405/1450/2100/2110 IP phones
	Basic auto configuration support for Polycom KIRK Wireless server 6000 IP phone

PAGE 5 27-Feb-12

Release	New Features
5.2.47	Security enhancement. A new security check has been added to prevent an external 3PCC or Click2Dial application from using any of the Quadro features unless specifically authorized from the user's extension settings. The new option (3pcc/Click2Dial Login Allowed) is displayed when doing an edit on the extension and is disabled by default. Please note. If the Quadro extension is currently being used with some 3PCC or Click2Dial application, then this option will need to be enabled after the firmware update
	or the feature will no longer work. Epygi applications that use 3PCC, such as HotCall and HotKeyCall, do not rely on this setting to be enabled to work.
	Auto Attendant Customized builder to create Interactive Voice Response (IVR) scenarios from the Quadro GUI.
	Support for the new Epygi Auto Dialer application (with a license key). TDVC and H.263+ codecs support.
	Language pack support for Polycom IP phones. Polycom phones change the GUI to the installed custom language.
	Local Admin password management enhanced. The local admin login password for GUI access is alphanumeric and a second numerical password can be entered for accessing
	settings from the phone handset, such as the Auto Attendant greeting messages. The Administrator password for phones is added as an item in the security audit.
	Auto configuration support for Cisco SPA303, SPA501G, SPA509G, SPA525G2 phones.
	PnP and auto configuration support for Grandstream GXP2120 and GXV3175 phones.
	PnP support for Grandstream GXV3140 video phone
	PnP and auto configuration support for Yealink VP-2009P model flavor.
	Added the falsealertmsg.cgi hidden page to make timeout for false ALERT message configurable. So that Quadro may send to ISDN false ALERT message after some timeout (defined in timeout value) if ISDN side does not receive any ringing from Quadros high level applications.
5.2.40	Support for Video Conferencing (with a license key)
	PnP support for Grandstream GXV3140 video phone
5.2.26	New Quadro System Security Management page added with security diagnostics and a security audit
	Secure system mail allowing to work with TLS or SSL mail servers
	A new option in Call Routing - Local AAA Table: Authentication by PIN code Possibility to enable/disable TLS functionality for IP Lines and extensions
	A new option in the extension voice mail settings under the Send new voicemail notifications via e-mail, allowing differentiating between fax messages and voicemail messages when deciding whether or not to receive email notifications, with or without attachments.
	Admin password management enhanced. The admin login password for GUI access is alphanumeric and a second numerical password can be entered for accessing settings from the phone handset, such as the Auto Attendant greeting messages.
	PnP and auto configuration support for snom 821
	PnP and auto configuration support for Aastra 6739i phone
	Auto configuration support for Grandstream GXV3140 video phone
	PnP and auto configuration support for Yealink VP-2009 video phone Auto configuration support for snom PA1 paging system
	Polycom KIRK Wireless server 300 phone support
	Call recording soft button implementation for Polycom phones
	Downloaded call statistics enhancements to include detailed information regarding the
	used interface for each call (PSTN, ISDN, etc), if call had been forwarded, transferred, etc.
	Viewing the Call Statistics on the Quadro GUI has been updated to select the number of records per page
	Audio-out line support for paging on the QuadroM 8L/26x/12Li/26xi

PAGE 6 27-Feb-12

Release	New Features
	Added the "Audio Line In" option in the "Play Background Music" under the ACD group
	settings
5.2.11	
	Maximum number of IP lines is 96. 32 IP lines are available by default, and two packs of 32 IP lines each to expand.
5.2.7	Full support for Secure RTP (SRTP) to encrypt voice packets.
	Full support for TLS (Transport Layer Security) protocol (RFC 2246) to provide communications privacy for the SIP messaging port over the Internet. The protocol allows client/server applications to communicate in a way that is designed to prevent eavesdropping of the SIP messages.
	HD codecs such as G.722 and G.722.1 are now supported in pass-through mode.
	Security enhancement. Password strength checking has been added in the IP Lines settings table for configuring IP Phones. The system will provide feedback on whether the chosen password is weak. An option is also provided to let the system create a strong, random password. Password strength enforcement can be configured in the hidden menu generalconfig.cgi.
	Security enhancement. Protection against certain SIP DoS attacks has been added by enabling the "SIP IDS" feature in the hidden menu generalconfig.cgi. Enabling this option will automatically block malicious IPs in the firewall.
	Global speed dialing. Configured in Telephony/Call Routing/Global Speed Dial Directory. An Excel .CSV file can be used to upload the entries in the format: Code, Number (e.g. 44, 9726921166). Each entry should be on a new line.
	Emergency Call Interrupt feature in the Caller ID based services. A new feature that will allow specific Caller Ids to be configured so that a call received from one of these numbers will immediately disconnect the call in progress and ring the user's extension.
	System logging enhancement. If a user encounters a problem while on a phone call the pertinent details related to the call can be saved. The user will dial *82 (getting dialtone and dial *82 from the same or a different phone) as soon as the problem occurs. The details will be saved until the next time someone enters *82. When the systemlogs are downloaded it will contain the details from the most recent *82 entry.
	The voicemail to email option can now be configured in Telephony/Voice Mail Common Settings so that the subject of the email contains a user defined text along with selected system variables (e.g. caller id).
	Option to select the format of FAX in Voice Mail sent by email. Defined in Telephony/Voice Mail Common Settings. TIFF or PDF can be used.
	A prompt to the user is provided with the option to save the system configuration prior to executing a firmware update
	Authorized phones database can now be used with a custom auto attendant scenario. This allows callers to bypass authentication in custom auto attendants for user's who have been included in the authorized phone database.
	Configurable auto attendant Callback Response Delay allows users to specify a timeout before the system will try to call back the user.
	Configurable auto attendant callback activation timeout from the GUI, which allows activating automatic Call Back for trusted PSTN and SIP callers not after the one - two rings as previously defined, but during the time frame specified in the GUI. So now users can configure the activation timeout in seconds needed to wait for initiating the callback. This configuration is accessible from the hidden menu "extmanagement.cgi".
	Allow the Automatic Callback feature to be used to call back to the originating caller using the "Auto" call type. User can select "Auto" as the "Callback Call Type", while leaving the "Callback Destination" field empty. This will allow to callback to the caller using the Caller ID for callback.
	Quadro FXS gateway PnP support
ı	Full VLAN support for IP Phones (multiple subnets/DHCP)
	Support for T38 FAX proxy (from standalone IP Phone in the LAN to outside)

PAGE 7 27-Feb-12

Release	New Features
	Yealink IP phone enhancements. PnP and auto configuration support for T20, T22 and T26 models. Advanced button configuration added in the IP Line Settings. Receptionist configuration support for add on modules. A custom logo image can now be displayed.
	Polycom IP phone enhancements. PnP and auto configuration for Polycom IP335 and IP450 models. Advanced button configuration added in the IP Line Settings. Receptionist configuration support for add on modules. Custom data files for Polycom IP phones can
	now be uploaded from the hidden menu ipphonesdirectory.cgi.
	PnP and auto configuration for Aastra 6730i phone PnP and auto configuration for snom 870 and snom MeetingPoint
	Call Forking (Find Me/Follow Me service)
	Call max duration (disconnecting call after the specified time).
	ACD: zero-out.
	Park slot segmentation (access list for call parking and retrieve)
	Barge-in/Whisper/Listening (*93,*92,*91) (with a license key).
	DHCP support on VLAN (including IP phones VLAN support). Shared Voice Mailbox.
	Call routing table debug/tracing tools (new events rise from Routing rule: call failover, fail, success).
	The call statistics download in CSV format.
	Automatic Call Distribution support (with a license key).
	Call recording support (with a license key).
	Music on hold can originate from an audio source that is streaming music or broadcasting live via an IP connection (i.e. internet radio channel).
	The Quadro Call Statistics (CDR) can be automatically sent via email or uploaded to an FTP or TFTP server.
	While playing back a voice mail the user can rewind (pressing "4") or skip forward (pressing "6"). The amount of seconds to advance or rewind can be optioned for each extension. Default = 3 secs.
	Click To Dial (CTD) feature updated to allow calls to be initiated from a Website, connecting two parties together via the Quadro. There are two options to make the call: - Using the HTTP request to specific URI from a third party WEB page or application; - Using a special hidden page on Quadro's WebGUI (in the hidden menu callcontrol.cgi)
	System events to track IP phones registration status.
	A custom logo image can be displayed on snom 360, 370 and 820 IP Phones.
	Speed Dial numbers can now be updated from the phone handset (*76).
	Outgoing Call Blocking can be updated from the phone handset (*79).
	Hot Desking feature. This allows a single phone (IP or analogue phone) to be used by many users. Users can login to the Hot Desking phone (*78) using their extension number, and get all the credentials of their extension until they logout (*78).

PAGE 8 27-Feb-12

Release	New Features
	Virtual extensions can be optioned to provide a simulated ring back. The VE can be assigned to a receptionist phone and this option will now give him/her the option to answer the call before it goes to voice mail.
	Zero-out on Auto Attendant.
	Load balancing for the FXO lines (including FXO gateways).
	Easier for extensions to forward their calls to external numbers without compromising the security of Call Routing entries that have the PBX filtering option enabled.
	Possibility for a user to designate a bad call in the system logs by dialing *81 after releasing the bad call.
	Capability to switch via phone the Unconditional Call Forwarding to "ON/OFF" for callers other than "Any/Other callers".
	Random call hunting.
	Capability to choose desired GUI theme on login.
	Capability to Show/Hide extensions attached to disabled IP lines in the Extensions Management.
	Capability to Show/Hide the disabled IP lines.
	Support for Conference Server (with a license key).
	Support for MS OCS and MS Exchange configuration with Quadro.
	SNMP status and configuration.
	The results of system configuration backup & download are reflected in the system events
	snom, Aastra and Grandstream phones automatically reboot when the Quadro is rebooted.
	Possibility to hide/show disabled records in the call routing table.
	Call forwarding configuration through custom Auto Attendant.
	Language pack support for the IP Phones.
	Receptionists' call queue.
	Extension status monitoring.
	Call interception.
	Direct transfer to voicemail.
	Simultaneous ring.

PAGE 9 27-Feb-12

Release	New Features
	Call park.
	Call pickup group.
	Call paging group.
	Plug and play for supported IP phones
	Simplified installation (auto configuration) for tested IP phones. User rights management.
	Support for an external voicemail system.
	Silence detection on voicemail messages to truncate extended periods of silence.
	QuadroFXO GW and QuadroISDN GW auto configuration.
	Proprietary method for remote extension to bypass certain types of NAT (symmetric RTP).
	Status for registered IP lines and remote extensions.
	Readable transfer statistics.
	New voice mail notifications via e-mail, via phone call and via SMS.
	Universal extension recording (music on hold, VM greetings, incoming/outgoing blocking messages).
	Sending unified fax message from mailbox to fax machine.
	System events reporting.
	Kickback feature on IP lines.
	snom and Aastra phones automatically reboot when the Quadro is rebooted.
	IP phones do not lose registration after Quadro soft reboot (i.e. if the reboot is not initiated by disconnecting/reconnecting the power or pressing the reset button on the back of the Quadro)
	Possibility to upload and customize system messages (in the uploadownmessages.cgi hidden page).
	Attendant ringing announcement for both default and custom AA scenarios.
	Possibility to change the default memory size to be allocated as a temporary storage for unified FAX message (in the extmanagement.cgi hidden page).
	Support for HotCall Add-In for use with Microsoft Outlook.
	SIP address resetting function in the Extensions Management for restoring the default SIP settings of extensions.

PAGE 10 27-Feb-12

Release	New Features
	Possibility to change static, running logos, links and browser mini logo (accessible from loadlogo.cgi hidden page).
	Possibility to change the signaling procedure for hold process in case the "Send Hold Music to Remote Party" is enabled on the extension.
	Voicemail setup wizard to guide new users through the recording of VM greetings.
	SIP trunk.
	3rd party call control (3PCC).
	Flexible numbering plan for extensions.
	Download IP phone FW and reboot of Aastra/snom IP phones.
	Download Quadro directory via XML to snom/Aastra phones.
	Automatic Quadro FW update
	Easier GUI for forwarding lists.
	Terminate a call from Active Calls page.
	Enhanced method for receptionists to watch other extensions, resulting in less networking traffic.
	Distinctive ringing on snom and Aastra IP phones.
	Play custom message instead of ring back tone on Auto Attendant.
	Send EVENTS via SMS.
	CDR tags for billing.
	Enhanced DNS/DHCP settings.
	Daylight savings adjustment.
	SMS and E-mail notification when a call to a given extension has been forwarded.
	Change extension password from phone handset.
	External access to the voice mailbox of users' extensions.
	Automatic backup and download of Quadro configuration.
	QCM centralized licensing included.
	SNMP support for event monitoring.
	Intercom service (for supported IP phones).
	Paging group service (for supported IP phones).

PAGE 11 27-Feb-12

Release	New Features
	Redirection on timeout to the specified address if no action on the AA welcome message.
	AA welcome and menu messages enabling/disabling capability.
	Call queue for virtual extensions.
	Toggling for call routing entries from the handset.
	Retrieve timeout configuration for parked call.
	SDMF caller ID standard.
	Routing rules activity timeout.
	Capability to make SIP calls using TCP as a transport protocol.
	"Client Code Identification" feature on routing rule (with RADIUS enabled).
	Paging support with 3rd party devices.
	Custom profiles for voice mail settings.
	Added silent VM recording option in the Voice Mail Settings.
	PSTN call instant callback.

PAGE 12 27-Feb-12

4 Changed Features History

The following table provides a high-level list of changed features that have been changed beginning with the most recent QuadroM8L/26x/12Li/26xi release.

	Added the option to delete the uploaded global speed dialing directory
5.3.2	Added Kebu.it as a new carrier to the VoIP Carrier Wizard list
	The name of Login/Call Relay column in the Extensions Management is changed to
	External Access, which indicates whether the GUI login, 3pcc/Click2Dial login or Call
	Relay options are enabled on the extension.
5.2.49	New FW recommendations for snom, Grandstream and Polycom phones.
	The maximum number of Successful Call Statistics has been increased from 1000 to 10000
	when a CF card is installed.
	Added option in ACD configuration to prevent the calls to agent in target group during
	selected period.
	Added information regarding video codec's under the Details in the call statistics
5.2.47	Added P-asserted identity header in all SIP messages that contain "p-preffered identity" or "Remote-party-ID".
	Changed the SIP parser for proper processing of From: field in header if URI scheme is
	included.
	The SIP IDS configuration options are available in the SIP IDS settings page.
	The "3pcc/Click2Dial Login Allowed" checkbox is available when editing multiple extensions
	at the same time.
	Multiple SMS numbers can be allowed in SMS destination fields, separated by SMS provider
5.2.40	required delimiter (the comma for Clickatell)
3.2.40	The SoTel SIP trunk is modified in the VoIP Carrier Wizard
	The Skype service is added in the VoIP Carrier list
	The Call Recording settings page is updated with a second, more simplistic method for
	enabling extensions. Either of two modes can be used: Basic view and Advanced view.
	Improvements in Call Recordings FTP retransmission mechanism.
	Extension Login permission to access the Quadro GUI. The login is disabled by default for
	all extensions. Multiple DHCP subnet support (two subnets allowed instead of one, making it possible to
	have about 500 devices getting DHCP from Quadro).
	LMR (Land Mobile Radio) support for QuadroM (E1/T1 to IP gateway capable of taking a
	channelized T1 to Multicast RTP IP streams by DS0 for use in a Radio over IP network).
5.2.26	The "Send Hold Music to remote IP party" is enabled by default in the Basic services for
	extensions.
	The Developer Logging is enabled by default.
	The SIP Server text field is changed to empty by default for auto attendant (00) and two
	FXS extensions.
	The default for "Maximum recording duration" is changed to 1 hour in the "Recording box
	settings" and "Call recording settings".
	The Secure RTP options in the Extension Codecs are available when editing multiple
	extensions at the same time.
5.2.11	
5.2.7	
	- ·

PAGE 13 27-Feb-12

5 Fixed Issues

Issues fixed since version 5.2.49:

D: The FXS port labeled Phone 1 on the front panel of the QuadroM8L(QuadroM26x) is actually configured as FXS Line 2. Phone 2 is configured as FXS Line 1. C: Note. After updating to 5.2.26 the FXS ports assignments will still be swapped with Phone 1 internally configured as FXS Line 2 and Phone 2 configured as FXS Line 1. Performing a factory reset on the system will correct the port assignments so that Phone 1 is FXS Line 1 and Phone 2 is FXS Line 2. However, the configuration will be lost. If the system is already configured the factory reset should not be done and the RJ-11 cables can remain swapped between Phone 1 and Phone 2. An issue when using the variable "Date" in the subject of voice mail send by email 16150 D: If the subject \$[VM_DATE] is placed at the end of the subject line, then Voice Mail will not send as an attachment. C: Add an underscore (_) after the \$[VM_DATE]. Or put the \$[VM_DATE] in the beginning or between other subjects in the subject line. An issue with Emergency Interrupt feature on snom IP phones 16391 D: The Emergency Interrupt fails when snom phone is in a 3-way call. Instead of ringing the phone call goes to VM directly C: A problem with custom Language Pack France 5.1.5 17069 D: The voice messages don't play after switching the system language to the Language Pack France 5.1.5.	The FXS ports labeled Phones 1 and 2 are swapped		
C: Note. After updating to 5.2.26 the FXS ports assignments will still be swapped with Phone 1 internally configured as FXS Line 2 and Phone 2 configured as FXS Line 1. Performing a factory reset on the system will correct the port assignments so that Phone 1 is FXS Line 1 and Phone 2 is FXS Line 2. However, the configuration will be lost. If the system is already configured the factory reset should not be done and the RJ-11 cables can remain swapped between Phone 1 and Phone 2. An issue when using the variable "Date" in the subject of voice mail send by email 16150 D: If the subject \$[VM_DATE] is placed at the end of the subject line, then Voice Mail will not send as an attachment. C: Add an underscore (_) after the \$[VM_DATE]. Or put the \$[VM_DATE] in the beginning or between other subjects in the subject line. An issue with Emergency Interrupt feature on snom IP phones 16391 D: The Emergency Interrupt fails when snom phone is in a 3-way call. Instead of ringing the phone call goes to VM directly C: A problem with custom Language Pack France 5.1.5 17069 The voice messages don't play after switching the system language to the Language Pack France 5.1.5.	D:	'	
with Phone 1 internally configured as FXS Line 2 and Phone 2 configured as FXS Line 1. Performing a factory reset on the system will correct the port assignments so that Phone 1 is FXS Line 1 and Phone 2 is FXS Line 2. However, the configuration will be lost. If the system is already configured the factory reset should not be done and the RJ-11 cables can remain swapped between Phone 1 and Phone 2. An issue when using the variable "Date" in the subject of voice mail send by email 16150 D: If the subject \$[VM_DATE] is placed at the end of the subject line, then Voice Mail will not send as an attachment. C: Add an underscore (_) after the \$[VM_DATE]. Or put the \$[VM_DATE] in the beginning or between other subjects in the subject line. An issue with Emergency Interrupt feature on snom IP phones The Emergency Interrupt fails when snom phone is in a 3-way call. Instead of ringing the phone call goes to VM directly C: A problem with custom Language Pack France 5.1.5 The voice messages don't play after switching the system language to the Language Pack France 5.1.5.		is actually configured as FXS Line 2. Phone 2 is configured as FXS Line 1.	
D: If the subject \$[VM_DATE] is placed at the end of the subject line, then Voice Mail will not send as an attachment. C: Add an underscore (_) after the \$[VM_DATE]. Or put the \$[VM_DATE] in the beginning or between other subjects in the subject line. An issue with Emergency Interrupt feature on snom IP phones 16391 D: The Emergency Interrupt fails when snom phone is in a 3-way call. Instead of ringing the phone call goes to VM directly C: A problem with custom Language Pack France 5.1.5 17069 D: The voice messages don't play after switching the system language to the Language Pack France 5.1.5.	C:	with Phone 1 internally configured as FXS Line 2 and Phone 2 configured as FXS Line 1. Performing a factory reset on the system will correct the port assignments so that Phone 1 is FXS Line 1 and Phone 2 is FXS Line 2. However, the configuration will be lost. If the system is already configured the factory reset should not be done and the RJ-11 cables can remain swapped between Phone 1	
will not send as an attachment. C: Add an underscore (_) after the \$[VM_DATE]. Or put the \$[VM_DATE] in the beginning or between other subjects in the subject line. An issue with Emergency Interrupt feature on snom IP phones 16391 D: The Emergency Interrupt fails when snom phone is in a 3-way call. Instead of ringing the phone call goes to VM directly C: A problem with custom Language Pack France 5.1.5 17069 D: The voice messages don't play after switching the system language to the Language Pack France 5.1.5.	An issu	-	
beginning or between other subjects in the subject line. An issue with Emergency Interrupt feature on snom IP phones 16391 D: The Emergency Interrupt fails when snom phone is in a 3-way call. Instead of ringing the phone call goes to VM directly C: A problem with custom Language Pack France 5.1.5 17069 D: The voice messages don't play after switching the system language to the Language Pack France 5.1.5.	D:	- •	
D: The Emergency Interrupt fails when snom phone is in a 3-way call. Instead of ringing the phone call goes to VM directly C: A problem with custom Language Pack France 5.1.5 The voice messages don't play after switching the system language to the Language Pack France 5.1.5.	C:	· · · · · · ·	
ringing the phone call goes to VM directly C: A problem with custom Language Pack France 5.1.5 The voice messages don't play after switching the system language to the Language Pack France 5.1.5.	An issu	e with Emergency Interrupt feature on snom IP phones 16391	
A problem with custom Language Pack France 5.1.5 D: The voice messages don't play after switching the system language to the Language Pack France 5.1.5.	D:		
D: The voice messages don't play after switching the system language to the Language Pack France 5.1.5.	C:		
Language Pack France 5.1.5.	A probl	A problem with custom Language Pack France 5.1.5 17069	
C:	D:		
	C:		

PAGE 14 27-Feb-12

6 Known Issues

D: Description C: Consequences

Fix: How to avoid the situation, or what to do in case the situation has occurred.

Settings	oossible to login as 'admin' after making changes on "Advanced PPP 5" page 9549
D:	You cannot login to the Quadro as 'admin' after making changes on the "Advanced PPP Settings" page. You can only login as 'user'.
C:	No consequences
Fix:	Restart the Quadro to resolve this.
One wa	y audio with IPSec VPN in the scenario "Gateway<->Remote Subnet" 9327
D:	Scenario:
	 Establish an IP-Sec connection between two Quadros (connection type is "Quadro <-> Remote Subnet").
	2. Make an SIP call from Quadro1 (gateway) to Quadro2 (remote subnet).
C:	The call is established, but there is no audio in Quadro1. The same result will occur when calling from Quadro2 to Quadro1. A direct call cannot be established at all.
Fix:	Add an additional "Quadro <> Remote Gateway" tunnel in IPSec configuration.
FIX.	With two tunnels: "Quadro <> Remote Gateway", "Quadro <> Remote Subnet" in IPSec VPN configuration this issue will resolved.
	rception fails in a specific scenario with a watched extension in the many
	on ring list 9399
D:	 Scenario: Use snom360 for receptionist extension (for example, extension #31), Configure Many Extension Ringing on ext. #31 with extensions #31 and #12 in the MER list,
	3. Configure extensions #11 and #12 as watched extensions,4. Make a call to extension #31,
	5. The phones for extensions # 31 and #12 will start ringing.6. The programmable key for the ext. #12 is flashing on the receptionist's ext #31,
	7. Pressing that key the receptionist stops ringing, but ext. #12 is still ringing,8. Hang-up the phone for that caller's extension.
C:	Call interception on the receptionist's line fails. The light for ext. #11 will stay ON on the ext. #31.
Fix:	This problem is specific for snom phones only. When using a snom phone, calls should be answered on your own extension and not the watched extension.
Firmwa Settings	re update cannot be completed when "High availability" is enabled in SIP page
D:	Scenario:
	 Using SIP Timers radio button in Telephony-SIP Settings, define the timeouts of the SIP messages retransmission as "High availability".
C:	Try to make firmware update.Firmware update will hang and not complete
Fix:	Set the SIP Timer to RFC3261 standard before firmware update. Under
TIX.	investigation, will be fixed in the future releases.
An issue	e with configuring IP phones as local extensions for Quadro IP PBX 13471

PAGE 15 27-Feb-12

D: Plug and Play and Auto configuration of IP phones is imp "HTTP Server Port" on the Quadro. C: Fix: Add the changed http port value in the "option tftp-serve	er-name" row on tftp-server-name leases. e if external Voice Mail 12190 out and entering the VMS all VMS system features. that external system. sconnect if you press assions ringing list 13830
Fix: Add the changed http port value in the "option tftp-serve ("dhcpd.conf.lan" file) for each IP phone. Example: "option "http://172.30.38.1:8080". Will be fixed in the future relevance of the Quadro voice mail services could be unavailable is in use for extension D: In this scenario some of the features, for example Zero-odirectly with option "1" will not work. C: Fix: This is normal, as those features are the Quadro's internatif external VMS system is used, user gets the features of snom, Aastra, Grandstream and Thomson IP phones may dis "Mute" button for a long time (60 min) D: C: Fix: Under investigation, will be fixed in the future releases. Aastra IP phone is not ringing when it is used in many extension in the list	on tftp-server-name leases. If external Voice Mail 12190 But and entering the VMS all VMS system features. That external system. Is connect if you press assions ringing list 13830
("dhcpd.conf.lan" file) for each IP phone. Example: "optic" http://172.30.38.1:8080". Will be fixed in the future relative for the Quadro voice mail services could be unavailable is in use for extension D: In this scenario some of the features, for example Zero-odirectly with option "1" will not work. C: Fix: This is normal, as those features are the Quadro's internatif external VMS system is used, user gets the features of snom, Aastra, Grandstream and Thomson IP phones may dismute" button for a long time (60 min) D: C: Fix: Under investigation, will be fixed in the future releases. Aastra IP phone is not ringing when it is used in many extension the list	on tftp-server-name leases. If external Voice Mail 12190 But and entering the VMS all VMS system features. That external system. Is connect if you press Insions ringing list 13830
D: In this scenario some of the features, for example Zero-ordirectly with option "1" will not work. C: Fix: This is normal, as those features are the Quadro's internal of external VMS system is used, user gets the features of snom, Aastra, Grandstream and Thomson IP phones may discuss "Mute" button for a long time (60 min) D: C: Fix: Under investigation, will be fixed in the future releases. Aastra IP phone is not ringing when it is used in many extension in the list	nut and entering the VMS al VMS system features. that external system. sconnect if you press asions ringing list 13830
C: Fix: This is normal, as those features are the Quadro's internal of external VMS system is used, user gets the features of snom, Aastra, Grandstream and Thomson IP phones may dis "Mute" button for a long time (60 min) D: C: Fix: Under investigation, will be fixed in the future releases. Aastra IP phone is not ringing when it is used in many external of the list.	al VMS system features. that external system. sconnect if you press asions ringing list 13830
Fix: This is normal, as those features are the Quadro's internal fexternal VMS system is used, user gets the features of snom, Aastra, Grandstream and Thomson IP phones may dis "Mute" button for a long time (60 min) D: C: Fix: Under investigation, will be fixed in the future releases. Aastra IP phone is not ringing when it is used in many extension in the list	that external system. sconnect if you press asions ringing list 13830
If external VMS system is used, user gets the features of snom, Aastra, Grandstream and Thomson IP phones may dis "Mute" button for a long time (60 min) D: C: Fix: Under investigation, will be fixed in the future releases. Aastra IP phone is not ringing when it is used in many extension in the list	that external system. sconnect if you press asions ringing list 13830
"Mute" button for a long time (60 min) D: C: Fix: Under investigation, will be fixed in the future releases. Aastra IP phone is not ringing when it is used in many extension: Scenario: 1. Many extension ringing is enabled on a virtual extension the list	nsions ringing list 13830
C: Fix: Under investigation, will be fixed in the future releases. Aastra IP phone is not ringing when it is used in many extension: Scenario: 1. Many extension ringing is enabled on a virtual extension in the list	13830
Fix: Under investigation, will be fixed in the future releases. Aastra IP phone is not ringing when it is used in many extension: Scenario: 1. Many extension ringing is enabled on a virtual extension the list	13830
Aastra IP phone is not ringing when it is used in many extension: Scenario: 1. Many extension ringing is enabled on a virtual extension the list	13830
Scenario: 1. Many extension ringing is enabled on a virtual extension the list	13830
 Many extension ringing is enabled on a virtual extensi in the list 	ion with an Aastra nhone
2. Distinctive Ringing is enabled on that virtual extension	ion with an Aastra phone
contains space	
C: When a call with no Caller ID comes to that extension, th extensions ringing list does not ring.	e Aastra phone in many
Fix: The problem is solved if there is a Caller ID available on t Nickname doesn't contain spaces. This problem is limited only.	
An issue with configuring Aastra IP phones as local extension	ons for Quadro IP PBX 13802
D: After changing the LAN IP address for the Quadro the 48 phones with currently recommended 1.4.1.2000 firmwar after restart.	0i, 9133i and 55i Aastra
C:	
Fix: They must be factory reset to register again. Under invest the future FW versions for Aastra phones.	stigation. Will be fixed in
An issue with distinctive ringing on the snom, Aastra and Grant Company of the snow, Aastra Company	andStream IP phones 11519
D: snom, Aastra and GrandStream phones ring only once if enabled with the "winter" ringing pattern.	the distinctive ringing is
C: No consequences	
Fix: Use other ringing patterns for distinctive ringing on these	e IP phones.
Call Interception doesn't work on GrandStream GXP2000 correceptionist, when extensions are watched on expansion mo	nfigured as a
D:	
C:	
Fix: Use basic 7 keys instead of expansion module. Will be fix releases.	ed in the future
Paging and intercom services do not work on the GrandStream	am BT100 IP phone 14909
D:	-
<u> </u>	

PAGE 16 27-Feb-12

C:	
Fix:	Currently PT100 has no support for paging/intercom
	Currently BT100 has no support for paging/intercom.
	ne doesn't go back to the normally idle state automatically when the ing had been started via the Record button and the call was released 15729
D:	The "Recording started" message remains on the phone screen after one of the parties terminate the call by going on-hook.
C:	Only incoming calls to IP phone are possible in this state.
Fix:	Need to use "Exit" button to retrieve the IP phone functionality. Will be fixed in
	the future releases.
	ot impossible to pickup (via pickup group) the call to extension with 2/FollowMe enabled 15942
D:	
C:	
Fix:	Will be fixed in the next releases.
	lem with "Remove VM On Send" option in Voice mail settings 16432
D:	If this option is enabled new VMs are removed from the extension mailbox even if sending the new VM via e-mail fails because the mail server is unreachable or mail address is incorrect
C:	
Fix:	Will be fixed in the next releases.
A prob	lem with incoming Secure RTP call in a specific scenario 16533
D:	When incoming Secure RTP call is connecting to the destination via Call Routing
	table, Quadro always tries to connect it as an un-secure call and the call is being
	dropped due to the media parameters incompatibility.
C:	
Fix:	Will be fixed in the next releases.
An issu	ue with wrongly displayed "Start Recording" message in the Active Calls 16184
D:	The recording type is set to "start automatically"; the number of allowed parallel
	call recordings is exhausted, therefore the recording for the next call cannot be
	started, but the "Start Recording" is wrongly shown in the Active Calls page.
C:	
Fix:	Will be fixed in the next releases.
Find m	ne/follow me doesn't work for incoming Secure RTP call 16683
D:	Though the call came with SRTP option the FM/FM is making unsecure calls
C:	As a result the call isn't established
Fix:	Will be fixed in the next releases.
	Infiguration page for Expansion Module is missing when configuring Yealink
	nd T26 as receptionist phones 16971
D:	In Receptionist Management wizard the Expansion module configuration pages
٥.	are not available for Yealink T28 and T26 phones.
C:	The standard of the standard o
◡.	
	Will be fixed in the next releases
Fix:	Will be fixed in the next releases.
Fix: After of phone:	Will be fixed in the next releases. Changing Quadro LAN IP configuration (IP address or subnet mask) IP Is lose registration and become unusable 16037
Fix: After of phones D:	hanging Quadro LAN IP configuration (IP address or subnet mask) IP
Fix: After of phones D: C:	changing Quadro LAN IP configuration (IP address or subnet mask) IP s lose registration and become unusable 16037
Fix: After of phones D:	hanging Quadro LAN IP configuration (IP address or subnet mask) IP
After of phones D: C: Fix:	After changing Quadro LAN IP configuration (IP address or subnet mask) IP After changing Quadro LAN IP configuration first reboot the Quadro then reboot the IP phones. Will be fixed in the next release. dio on both sides if you hold the call, then unhold it after the Holding
Fix: After of phones D: C: Fix: No audiremino	After changing Quadro LAN IP configuration (IP address or subnet mask) IP After changing Quadro LAN IP configuration first reboot the Quadro then reboot the IP phones. Will be fixed in the next release. dio on both sides if you hold the call, then unhold it after the Holding der on snom phone running FW 8.4.32
After of phones D: C: Fix:	After changing Quadro LAN IP configuration (IP address or subnet mask) IP After changing Quadro LAN IP configuration first reboot the Quadro then reboot the IP phones. Will be fixed in the next release. dio on both sides if you hold the call, then unhold it after the Holding

PAGE 17 27-Feb-12

	short beep after timeout of 30 sec that you still have somebody on hold.
	Unholding the call after Holding reminder will bring to the audio loss on both
	sides.
C:	
Fix:	This is an issue with snom FW 8.4.32 and should be fixed in the snom next
	releases. Meanwhile to resolve this problem make another hold/unhold when this
	condition happens.
	You may also downgrade the snom FW to 8.4.31, but take into account that in
	this case you will restore the call failure problem when pressing hold/transfer
	during secure (SRTP) calls.
One way	y audio in a scenario when Holding/Retrieving the PSTN call 17245
D:	Scenario:
	1. ext. A is configured to watch the ext. B
	2. PSTN call comes to ext. B and the functional key of the ext. A shows the
	ringing state for ext. B
	3. ext. A presses the functional key and intercepts the call to ext. B
	4. ext. A holds the call
	5. ext. A retrieves the call
C:	Result: ext. A hears the PSTN, but the PSTN doesn't hear the ext. A
Fix:	The reason is the SRTP option on ext. A set to "Make unsecure calls, accept
	anything". Change the SRTP option on the ext. A to "Make and accept only
	unsecure calls". Will be fixed in the next release.
An issue	e with Intercom service on snom 8xx phones 17282
D:	When the snom phone of 8xx series (tested with snom phones 821, 870 running
D.	FW version's 8.4.32, 8.4.33) have some watching configured for it's functional
	keys and the status of the watching resource is changed (e.g. the watching
	phone receives or makes a call), immediately the next intercom call to snom
	phone doesn't activate the intercom but continuously ring the phone.
C:	As a result, if the calling phone is configured as watched extension, the snom
.	phone never activates the intercom for that caller.
Fix:	Will be fixed in some future FW release for snom.
	thentication doesn't work for a call scenario 16784
D:	Local authentication configured in the Local AAA table by User Login or by PIN
	code is ignored for the following call scenario; a SIP call to Quadro Auto
	Attendant, then call to a SIP destination.
C:	Quadro doesn't ask for authentication in this case.
Fix:	Will be fixed in the next release.
An issue	with adding audio files for ACD custom scenario 16817
D:	Scenario:
	- add an audio file with special characters in name (with slashes, dashes,
	brackets, etc.) for Custom Queue Messages in the ACD Customize queue
	scenario;
	- The added file is shown as normally uploaded on the GUI.
C:	Actually the newly added file isn't being uploaded in the system. So the callers to
	ACD with Customize Queue Scenario will hear nothing for that message.
Fix:	Don't use special characters in the name for audio file to be played in the ACD
	queue. Will be fixed in the next releases.
An issue	with call statistics archiving option by time interval of 30 days 17334
D:	Using this option may cause system instability because of the large memory
	requirements for downloading to external server. Avoid using the 30 day option
	when configuring statistics archiving by time interval
C:	<u> </u>
Fix:	Will be fixed in the next release.
1 1/1.	Will be fixed in the flext foldage.

PAGE 18 27-Feb-12

7 Upgrading Instructions

7.1 Technical Advisory

Attention: For manually configured IP phones, it is now required to have the **SIP Registration Timeout** parameter set to 120 seconds or more on your IP phone. Values less than 120 seconds will not be accepted by the Quadro and will cause the IP phone registration failure on the Quadro.

7.2 General hints

It is recommended to execute the update by downloading the software first to a PC located in the LAN side of the Quadro and perform the firmware update from the LAN side. This is to ensure that the Internet connection will not affect the upgrade process.

In general, the configuration of a system will remain after the software update. Remember that some data is lost during upgrade:

- Call Statistics (only when embedded memory storage is used)
 Workaround to save the existing call statistics, download it to the PC from Call Statistics-Statistics Settings before performing the firmware update. It is also recommended to use an external Compact flash memory to keep the call statistics safe.
- Voice mails (only when embedded memory storage is used)
 Workaround save the recorded voice mails from the Voice Mailbox before performing the firmware update. It is also recommended to use an external Compact flash memory to keep the voice mails safe.
- Call recordings (only when embedded memory storage is used)
 Workaround save the recorded calls from the Recordings Box before performing the firmware update or use the recorded calls automatically upload to the FTP server option. It is also recommended to use an external Compact flash memory to keep the voice mails safe.
- All custom voice greetings (only when embedded memory storage is used)
 Workaround backup and download all configuration and voice data to a PC. It is also recommended to use an external Compact flash memory to keep the custom voice messages safe.
- All custom recordings for the custom Auto Attendant (only when embedded memory storage is used)
 Workaround – backup and download all configuration and voice data to a PC. It is also recommended to use an external Compact flash memory to keep the custom recordings safe.
- Pending events (only when embedded memory storage is used)
- Transfer statistics for the network
- DHCP leases

The following steps describe how to correctly perform the firmware update to avoid losing the custom voice greetings and recordings for custom auto attendants:

- Save the current configuration by doing a Backup and Download of all config and voice data (System->Configuration Management->Backup and download all config and voice data).
- 2. Perform the Firmware Update.

PAGE 19 27-Feb-12

All custom voice greetings and all recordings for the custom Auto Attendants can be restored by uploading the configuration that was saved in Step1 (System -> Configuration Management -> Upload and Restore all config and voice data).

Attention: Power down the Quadro before inserting/removing Compact Flash card.

7.3 Limitations and restrictions

- The memory used by "DSP Capture", "Call Capture" and "Network Capture" hidden pages is limited to 3 MB. This will put a limitation on the duration of captured file
- In case if voice mail recording codec is other than PCMU, the maximum length of VM sent by email is limited to 3 minutes
- The number of VMs in the mailbox for one extension is limited to 300
- Use Session Timer in IP Line Settings is deselected by default

PAGE 20 27-Feb-12