

# **TECH ARTICLE**

**Date:** 13/11/2007

**Revision Date (6 months max):** N/A

---

**Topic / Issue:** Flashing Error Led- PS5800

---

**Written By:** Scott Young

---

A Flashing Error Led on the Print Server implies that no USB printer was found

To resolve this please try the following:

- 1) Try a different USB cable.
- 2) Ensure that the USB port is enabled in the printer configuration.
- 3) Ensure that the Printer and Print server are not connected by a USB hub. They must be point to point.

---

**Summary:**  
(If required)