

Release Note QuadroM32x 5.3.5 Edition 2

THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY INFORMATION OWNED BY EPYGI TECHNOLOGIES LTD. ANY COPYING, USE OR DISCLOSURE OF THE DOCUMENT OR THE INFORMATION CONTAINED HEREIN WITHOUT THE WRITTEN PERMISSION OF EPYGI TECHNOLOGIES LTD. IS STRICTLY PROHIBITED.

THIS DOCUMENT IS PROVIDED TO YOU FOR INFORMATIONAL PURPOSES ONLY. The information furnished in this document, believed by Epygi Technologies to be accurate as of the date of publication, is subject to change without notice. Epygi Technologies assumes no responsibility for any errors or omissions in this document and shall have no obligation to you as a result of having made this document available to you or based upon the information it contains.

Epygi is a registered trademark of Epygi Technologies, Ltd. All other products and services are the registered trademarks of their respective holders

1 Introduction

This Release Note describes hardware and software requirements to use with the

QuadroM32x software 5.3.5 Date: April 26, 2012

Additional enhancements, bug fixes and known issues incorporated in this software will be listed as known.

Date: June 14, 2012

2 Requirements

2.1 Hardware requirements

- The software can be used on all QuadroM32x models.
- The model name is written on the back plate of the unit and the model number is on the bottom label.

2.2 Software requirements

Attention: The software upgrade to 5.3.5 can **ONLY** be done from 5.2.47 and higher 5.2 versions. Before updating to 5.3.5 the unit should be updated to 5.2.47 or higher 5.2 version first.

2.3 Supported and Tested SIP phones

Listed below are the Epygi Supported SIP phones with the corresponding firmware versions that are tested and recommended for use with QuadroM32x 5.3.5 SW.

| Vendor | Model | Software |
|--------|-----------------|---------------------------------|
| snom | 300 | Application: snom300-SIP 8.4.35 |
| snom | 320 | Application: snom320-SIP 8.4.35 |
| snom | 360 | Application: snom360-SIP 8.4.35 |
| snom | 370 | Application: snom370-SIP 8.4.35 |
| snom | 821 | Application: snom821-SIP 8.4.35 |
| snom | 870 | Application: snom870-SIP 8.4.35 |
| snom | MeetingPoint | Application: snomMP-SIP 8.4.35 |
| Aastra | 9143i (33i) | Application version: 2.5.2.1010 |
| Aastra | 9480i (35i) | Application version: 2.5.2.1010 |
| Aastra | 9480iCT (35iCT) | Application version: 2.5.2.1010 |
| Aastra | 6753i | Application version: 2.5.2.1010 |
| Aastra | 6755i | Application version: 2.5.2.1010 |
| Aastra | 6757i | Application version: 2.5.2.1010 |
| Aastra | 6757iCT | Application version: 2.5.2.1010 |
| Aastra | 6730i | Application version: 2.5.2.1010 |
| Aastra | 6731i | Application version: 2.5.2.1010 |
| Aastra | 6739i | Application version: 3.0.1.38 |

Please Note: Any problems and limitations on these SIP phones are described in detail in the Quadro Features on Supported IP Phones document.

Please Note: Quadro IP phones firmware control mechanism will not upgrade snom firmware version from 6.x to 7.x. This should be done manually via snom web site. Once the snom firmware version is 7.x, the Quadro's firmware control will automatically upgrade/downgrade the phone to Epygi's recommended version but not to 6.x.

PAGE 2 15-Jun-12

Listed below are the Epygi Tested SIP phones with the corresponding firmware versions that are tested and recommended for use with QuadroM32x 5.3.5.

Any problems and limitations on these SIP phones are described in detail in the **Quadro Features** on Tested Phones document.

| Vendor | Model | Software |
|-------------|---------------------------|--------------------------------------|
| Audiocodes | 310HD | 1.6.0_build_37 |
| Audiocodes | 320HD | 1.6.0_build_37 |
| Cisco | SPA525G2 | 7.4.8 |
| Cisco | SPA303 | 7.4.8 |
| Cisco | SPA501G | 7.4.8 |
| Cisco | SPA509G | 7.4.8 |
| Polycom | SoundPoint IP 330SIP* | Application: SIP software 3.3.1.0933 |
| Polycom | SoundPoint IP 331SIP* | Application: SIP software 3.3.1.0933 |
| Polycom | SoundPoint IP 335SIP* | Application: SIP software 3.3.1.0933 |
| Polycom | SoundPoint IP 450SIP* | Application: SIP software 3.3.1.0933 |
| Polycom | SoundPoint IP 550SIP* | Application: SIP software 3.3.1.0933 |
| Polycom | SoundPoint IP 650SIP* | Application: SIP software 3.3.1.0933 |
| Polycom | SoundStation IP 5000* | Application: SIP software 3.3.1.0933 |
| Polycom | SoundStation IP 6000* | Application: SIP software 3.3.1.0933 |
| Polycom | VVX 1500* | Application: SIP software 3.3.1.0933 |
| Polycom | KIRK wireless server 300 | PCS08 |
| Polycom | KIRK wireless server 6000 | PCS08 |
| Panasonic | KX-TGP550T04 | 12.17 |
| Panasonic | KX-UT123-B | 01.061 |
| Panasonic | KX-UT136-B | 01.061 |
| snom | PA1 | 8.4.32 |
| snom | m9 | 9.4.7 |
| Grandstream | GXP1400 | Program- 1.0.1.83 |
| Grandstream | GXP1405 | Program- 1.0.1.83 |
| Grandstream | GXP1450 | Program- 1.0.1.83 |
| Grandstream | GXP2000 | Program- 1.2.5.3 |
| Grandstream | GXP2100 | Program- 1.0.1.83 |
| Grandstream | GXP2110 | Program- 1.0.1.83 |
| Grandstream | GXP2120 | Program- 1.0.1.83 |
| Grandstream | GXV3140 | Program- 1.0.7.3 |
| Grandstream | GXV3175 | Program- 1.0.3.22 |
| Grandstream | HT286 | Program- 1.1.0.26 |
| Yealink | SIP-T20P | SW version: 9.50.0.50 |
| Yealink | SIP-T22P | SW version: 7.50.0.50 |
| Yealink | SIP-T26P | SW version: 6.50.0.50 |
| Yealink | SIP-T28P | SW version: 2.50.0.50 |
| Yealink | VP-2009P | 22.21.0.40/22.30.0.60 |

Both mentioned documents are available at www.epygi.com and can be found under the Channel's Portal.

Please Note: In the model's list the Polycom phones with (*) sign are also presented as **Polycom-xx-Pre-3.3.0** due to backward incompatibility of UCSoftware 3.1.1 configuration. It is recommended to use **Pre-3.3.0** models with Application SIP software 3.2.2.0477.

PAGE 3 15-Jun-12

2.4 Interaction with other Quadro SW releases

QuadroISDN or QuadroFXO external PSTN gateways used in the shared mode should have SW 5.1.12 or higher to achieve maximum feature functionality with the QuadroM32x SW 5.3.5.

QuadroFXS 16 Gateway should have SW 5.2.1 or higher for PnP configuration with the QuadroM32x SW 5.3.5.

ActiveX Control SW 5.3.0 or higher should be used with 3pCC functions with the QuadroM32x SW 5.3.5.

Auto Dialer SW 1.0.5 or higher should be used with the Quadro32x SW 5.3.5.

Quadro SMR system SW 1.9 or higher should be used with the QuadroM32x SW 5.3.5.

To use QuadroM32x SW 5.3.5 with a 3pcc or Click2Dial application the "3pcc/Click2Dial Login Allowed" checkbox should be enabled for each extension(s) using this feature.

PAGE 4 15-Jun-12

3 New Features History

The table below indicates a high-level list of new features that have been added beginning with the most recent QuadroM32x release.

| Release | New Features |
|---------|--|
| 5.3.5 | The Add Multiple Extensions feature is improved which allows the assignment of the IP |
| | Lines to be selected when configuring multiple extensions. |
| | A new MS Exchange Server option has been added in the Use External Voice Mail |
| F 2 2 | settings for extensions. This allows voice messages to be kept in one universal inbox. |
| 5.3.3 | The Call Park feature has been expanded with a Directed Call Park method. This allows users to define the call park extension they wish to park the call on. |
| | There are two methods available: 1) Hold the current call, and then dial the call park |
| | extension number; 2) Assign the call park extension to a key on the phone and then, just |
| | press the key during an active call. |
| | New Call Intercept feature. A new feature code has been added allowing users to dial *94 |
| | followed by the extension number to intercept an inbound call on another extension. |
| | IP Phone Key Assignment Templates are now available to define a set of extensions |
| | mapped to keys on IP phones. These templates can be used for multiple IP phones to |
| | streamline installation and configuration of multiple phones. |
| | The Find Me/Follow Me announcement message is now customizable. Users can remove |
| | the message, use the default, define a new recording or use music on hold. |
| | Added the option to review and modify the system default Find Me/Follow Me welcome message like other universal extension messages using the admin *75 feature code on |
| | the phone. |
| | Added the option to review and modify the user's personal Find Me/Follow Me welcome |
| | message like other personal greeting messages using the extensions *0 feature code on |
| | the phone. |
| | Added support for P-Asserted-Identity header field defined in RFC 3325. This is important |
| | to retain original caller information even after a call is transferred within the office. |
| | The CDR database has been improved adding archiving up to 30 days. Additionally, CDR |
| | uploading redundancy mechanisms are added to ensure records are not getting lost |
| | during CDR server downtime or network outage. |
| | The maximum number of stored CDRs has been increased from 1000 to 10000 Statistics gathered from the ACD feature and Find Me/Follow Me have been improved for |
| | greater visibility of call flow. |
| | A few new options have been added to the GUI based Auto Attendant IVR builder |
| | integrated into the Quadro IP PBXs. Repeated message play count, repeated message |
| | timeout duration and timeout after welcome message options are now included in the AA |
| | IVR builder tool. Auto configuration support for new IP phones: Snom m9, Panasonic KX-TGP550T04, KX- |
| | UT123-B, KX-UT136-B, Audiocodes 320HD and 310HD. |
| | A special configuration page is added for simple direct mapping of E1/T1 DID numbers to |
| | extension numbers. The configuration screen is accessible from E1T1 Trunk settings page |
| | on CCS trunk types only. This mapping works for both incoming and outgoing E1/T1 |
| | calls, and allows for easy streamlined installation for the majority of E1T1 setups. |
| | A new option to use RTP streaming channel for playing Hold Music is added to the |
| | "Universal Extension Recordings" configuration page. This allows using an external RTP |
| | as default Hold Music for all extensions. |
| | Intercom settings are improved. Now it will be possible to define whether the phone |
| | should make a sound when Intercom is activated. The default is silence. |
| | Call conferencing features are enhanced regarding the Moderator Rights Management, |
| | conference call terminations options, and the conference statistics. |
| | Added support for T.38 faxing on IP lines for use on devices such as an ATA for faxing. |

PAGE 5 15-Jun-12

| Release | New Features |
|---------|--|
| | The Maximum recording count option has been restored back in the Recording Box Settings. |
| | The VoIP carrier wizard is improved which allows creating the outbound routing rules not only by prefix but also by 7 and 10 digit pattern. |
| 5.2.48 | PnP and auto configuration support for Grandstream GXP1400/1405/1450/2100/2110 IP phones. |
| | Basic auto configuration support for Polycom KIRK Wireless server 6000 IP phone. |
| 5.2.47 | |
| 5.2.46 | Security enhancement. A new security check has been added to prevent an external 3PCC or Click2Dial application from using any of the Quadro features unless specifically authorized from the user's extension settings. The new option (3pcc/Click2Dial Login Allowed) is displayed when doing an edit on the extension and is disabled by default. Please note. If the Quadro extension is currently being used with some 3PCC or Click2Dial application, then this option will need to be enabled after the firmware update or the feature will no longer work. Epygi applications that use 3PCC, such as HotCall and HotKeyCall, do not rely on this setting to be enabled to work. |
| | Auto Attendant Customized builder to create Interactive Voice Response (IVR) scenarios from the Quadro GUI. |
| | Support for the new Epygi AutoDialer application (with a license key). |
| | TDVC and H.263+ codecs support. |
| | Language pack support for Polycom IP phones. Polycom phones change the GUI to the installed custom language. |
| | Local Admin password management enhanced. The local admin login password for GUI access is alphanumeric and a second numerical password can be entered for accessing settings from the phone handset, such as the Auto Attendant greeting messages. |
| | The Administrator password for phones is added as an item in the security audit. |
| | Auto configuration support for Cisco SPA303, SPA501G, SPA509G, SPA525G2 phones. PnP and auto configuration support for Grandstream GXP2120 and GXV3175 phones. |
| | PnP and auto configuration support for Yealink VP-2009P model flavor. |
| 5.2.40 | |
| 5.2.39 | Support for Video Conferencing (with a license key). |
| | PnP support for Grandstream GXV3140 video phone |
| 5.2.26 | New Quadro System Security Management page added with security diagnostics and a security audit |
| | Secure system mail allowing to work with TLS or SSL mail servers |
| | A new option in Call Routing - Local AAA Table: Authentication by PIN code |
| | Possibility to enable/disable TLS functionality for IP Lines and extensions A new option in the extension voice mail settings under the Send new voicemail notifications via e-mail, allowing differentiating between fax messages and voicemail messages when deciding whether or not to receive email notifications, with or without attachments. |
| | Admin password management enhanced. The admin login password for GUI access is alphanumeric and a second numerical password can be entered for accessing settings from the phone handset, such as the Auto Attendant greeting messages. PnP and auto configuration support for snom 821 |
| | PnP and auto configuration support for Aastra 6739i phone |
| | Auto configuration support for Grandstream GXV3140 video phone |
| | PnP and auto configuration support for Yealink VP-2009 video phone |
| | Auto configuration support for snom PA1 paging system |
| | Polycom KIRK Wireless server 300 phone support |
| | Call recording soft button implementation for Polycom phones Downloaded call statistics enhancements to include detailed information regarding the used interface for each call (PSTN, ISDN, etc), if call had been forwarded, transferred, |
| | etc. |

PAGE 6 15-Jun-12

| Release | New Features |
|---------|---|
| | Viewing the Call Statistics on the Quadro GUI has been updated to select the number of records per page |
| 5.2.12 | records per page |
| 5.2.10 | Full support for Secure RTP (SRTP) to encrypt voice packets. |
| | Full support for TLS (Transport Layer Security) protocol (RFC 2246) to provide communications privacy for the SIP messaging port over the Internet. The protocol allows client/server applications to communicate in a way that is designed to prevent eavesdropping of the SIP messages. |
| | HD codecs such as G.722 and G.722.1 are now supported in pass-through mode. |
| | Security enhancement. Password strength checking has been added in the IP Lines settings table for configuring IP Phones. The system will provide feedback on whether the chosen password is weak. An option is also provided to let the system create a strong, random password. Password strength enforcement can be configured in the hidden menu generalconfig.cgi. |
| | Security enhancement. Protection against certain SIP DoS attacks has been added by enabling the "SIP IDS" feature in the hidden menu generalconfig.cgi. Enabling this option will automatically block malicious IPs in the firewall. |
| | Global speed dialing. Configured in Telephony/Call Routing/Global Speed Dial Directory. An Excel .CSV file can be used to upload the entries in the format: Code, Number (e.g. 44, 9726921166). Each entry should be on a new line. |
| | Emergency Call Interrupt feature in the Caller ID based services. A new feature that will allow specific Caller Ids to be configured so that a call received from one of these numbers will immediately disconnect the call in progress and ring the user's extension. |
| | System logging enhancement. If a user encounters a problem while on a phone call the pertinent details related to the call can be saved. The user will dial *82 (getting dialtone and dial *82 from the same or a different phone) as soon as the problem occurs. The details will be saved until the next time someone enters *82. When the systemlogs are |
| | downloaded it will contain the details from the most recent *82 entry. The voicemail to email option can now be configured in Telephony/Voice Mail Common Settings so that the subject of the email contains a user defined text along with selected system variables (e.g. caller id). |
| | Option to select the format of FAX in Voice Mail sent by email. Defined in |
| | Telephony/Voice Mail Common Settings. TIFF or PDF can be used. A prompt to the user is provided with the option to save the system configuration prior to executing a firmware update |
| | Authorized phones database can now be used with a custom auto attendant scenario. This allows callers to bypass authentication in custom auto attendants for user's who have been included in the authorized phone database. |
| | Configurable auto attendant Callback Response Delay allows users to specify a timeout before the system will try to call back the user. |
| | Configurable auto attendant callback activation timeout from the GUI, which allows activating automatic Call Back for trusted PSTN and SIP callers not after the one - two rings as previously defined, but during the time frame specified in the GUI. So now users can configure the activation timeout in seconds needed to wait for initiating the callback. This configuration is accessible from the hidden menu "extmanagement.cgi". |
| | Allow the Automatic Callback feature to be used to call back to the originating caller using the "Auto" call type. User can select "Auto" as the "Callback Call Type", while leaving the "Callback Destination" field empty. This will allow to callback to the caller using the Caller ID for callback. |
| | Quadro FXS gateway PnP support |

PAGE 7 15-Jun-12

| Release | New Features |
|---------|---|
| | Full VLAN support for IP Phones (multiple subnets/DHCP) |
| | Support for T38 FAX proxy (from standalone IP Phone in the LAN to outside) |
| | Yealink IP phone enhancements. PnP and auto configuration support for T20, T22 and T26 models. Advanced button configuration added in the IP Line Settings. A custom logo image can now be displayed. |
| | Polycom IP phone enhancements. PnP and auto configuration for Polycom IP335 and IP450 models. Advanced button configuration added in the IP Line Settings. Receptionist configuration support for add on modules. Custom data files for Polycom IP phones can now be uploaded from the hidden menu ipphonesdirectory.cgi. |
| | PnP and auto configuration for Aastra 6730i phone |
| | PnP and auto configuration for snom 870 and snom MeetingPoint |
| 5.1.38 | Ability to configure speed-dial buttons of snom IP phones via IP phone template mechanism |
| | Telematrix IP phones auto configuration support |
| | Call Forking (FindMe/FollowMe service) |
| | Call max duration (disconnecting call after the specified time) |
| | ACD: zero-out |
| | Yealink phone auto configuration |
| 5.1.31 | Reason header in SIP CANCEL message (prevents the call from being reported as "missed" if it was picked up by another extension) |
| | Auto configuration and compatibility for Polycom VVX 1500 video phone |
| | ACD: agent easy login/logout buttons (including the status indication) |
| | Automatic logout for HotDesking phones |
| | Hot Desking capability enabled for remote extensions |
| | Line appearance added on Remote Extensions |
| | Park slot segmentation (access list for call parking and retrieve) |
| | 3PCC: capability for 3pcc programmer to modify username |
| | Barge-in/Whisper/Listening (*93,*92,*91) (with a license key) |
| | ACD: ACD calls to agent should never reach their voicemail |
| | DHCP support on VLAN (including IP phones VLAN support) |
| | Shared Voice Mailbox |
| | Call routing table debug/tracing tools (new events raised from Routing rule: call failover, fail, success) |

PAGE 8 15-Jun-12

| Release | New Features |
|---------|---|
| | Aastra 6731i autoconfiguration and PnP |
| | Polycom Soundpoint IP 331 auto configuration and PnP |
| | 3PCC: ability to differentiate call failure reasons (different error codes) |
| | Added possibility to download the call statistic in CSV format |
| | Added possibility to play Hold Music to conference participants unless moderator will join the conference |
| | Added possibility for conference participants to mute/unmute their phones during the conference by pressing pound sign (#) |
| 5.1.21 | Added possibility for unregistered user to activate the conference call by entering the password for conference moderator |
| | Added zero-out option to the ACD call queue |
| 5.1.18 | Automatic Call Distribution support (with a license key) |
| | Call recording (with a license key) |
| | Music on hold can originate from an audio source that is streaming music or broadcasting live via an IP connection (i.e. internet radio channel). |
| | The Quadro Call Statistics (CDR) can be automatically sent via email or uploaded to an FTP or TFTP server. |
| | While playing back a voice mail the user can rewind (pressing "4") or skip forward (pressing "6"). The amount of seconds to advance or rewind can be optioned for each extension. Default = 3 secs. |
| | Plug and Play for Polycom IP Phones |
| | VLAN support |
| | Click To Dial (CTD) feature updated to allow calls to be initiated from a Website, connecting two parties together via the Quadro. There are two options to make the call: (a) Using the HTTP request to specific URI from a third party WEB page or application; (b) Using a special hidden page on Quadro's WebGUI (in the hidden menu callcontrol.cgi) |
| | New system events added to track IP phones registration status |
| | A custom logo image can be displayed on snom 360, 370 and 820 IP Phones |
| | Speed Dial numbers can now be updated from the phone handset (*76) |
| | Outgoing Call Blocking can be updated from the phone handset (*79) |
| | Hot Desking feature. This allows a single phone (IP or analogue phone) to be used by many users. Users can login to the Hot Desking phone (*78) using their extension number, and get all the credentials of their extension until they logout (*78). |
| | Virtual extensions can be optioned to provide a simulated ring back. The VE can be assigned to a receptionist phone and this option will now give him/her the option to answer the call before it goes to voice mail. |
| | Zero-out on Auto Attendant |
| | The Automatic Call Back option has been expanded to include callback to SIP callers. Previously, this feature was specific to PSTN callers. |
| | TLS/SSIP support added to send and receive encrypted SIP messages from designated peers |

PAGE 9 15-Jun-12

| Release | New Features |
|---------|--|
| | Video phone support (proxy mode) |
| | E1 MELCAS digital hookflash feature added for E1 CAS to SIP calls |
| | The Unconditional Call Forwarding option has been enhanced so that enabling/disabling the feature from the handset can include the designated caller Ids. |
| | Load balancing for the FXO lines (including FXO gateways) |
| | Easier for extensions to forward their calls to external numbers without compromising the security of Call Routing entries that have the PBX filtering option enabled. |
| | Possibility for a user to designate a bad call in the system logs by dialing *81 after releasing the bad call. |
| | The Quadro system voice messages can be browsed and updated from a PC using 3PCC |
| | New features in 3pcc: Using the SIP Dialog package the call states for extensions can be viewed and tracked. |
| | New features in 3pcc: This feature allows the 3pcc application to subscribe to the Quadro's extension's list and receive an event notification the list has changed. |
| | New features in 3pcc: The connect function has been added which allows the application to use an extension's authentication parameters (extension number, password). After successful connection establishment an application can manipulate options on the extension. |
| | New features in 3pcc: Capability to upload the contents of legible configuration files and do the configuration update via 3pCC |
| | An option to "Discard Non-Numeric Symbols" is added in the Call Routing Wizard to delete extra characters that might be received in the caller id. |
| | Possibility to append the called number to the caller id using the format <dialednum:range>. This will allow the user to appropriately answer a call based on the number that was dialed.</dialednum:range> |
| | snom M3 support |
| | snom820 auto-configuration support |
| | Ability to download "packages" of CGI's in legible format |
| | The configuration templates that the Quadro uses for the IP Phones can now be modified. |
| | Ability to remotely access the Auto Attendant and use the admin login menu (*75) to update the AA greeting messages. Previously this login was only accessible from an extension. |
| | Capability to configure emergency numbers from the VoIP Carrier Wizard |
| 5.0.22 | |
| 5.0.21 | Automatic call forwarding on extensions with Unregistered/Inaccessible IP phones |
| 5.0.17 | Capability to switch via phone the Unconditional Call Forwarding to "ON/OFF" for callers other than "Any/Other callers" |
| | Random call hunting |
| | Capability to choose desired GUI theme on login |
| | Capability to Show/Hide extensions attached to disabled IP lines in the Extensions Management |
| | Capability to Show/Hide the disabled IP lines |

PAGE 10 15-Jun-12

| Release | New Features |
|---------|---|
| | Auto configuration support for the following Linksys IP phone models: SPA941, SPA942, SPA921, SPA922 |
| | Ability to remove the Display name of the call passing through Routing Table |
| | New Auto Attendant or extension adding process simplified |
| | Add mechanism for the DND and CallFwd functionality of snom and Aastra IP phones. |
| | |
| 5.0.10 | Support for Conference Server (with a license key). |
| 5.0.8 | Ability to record voice messages from the phone handset that are referenced from the Auto Attendant Interactive Voice Response menu. When needed, the recordings can then be easily updated with current messages. |
| | Support for MS OCS and MS Exchange configuration with Quadro |
| | It is now possible to reboot each IP phone separately from the Quadro's GUI |
| | Added receptionist wizard and expansion module support for Grandstream GXP2000 |
| | Programmable Keys Configuration page added in the IP Line Settings for snom, Aastra, (except for snom300 and Aastra51i, 9112i), Grandstream GXP2000. There is an advanced link on IP Lines page to configure the programmable buttons of each phone models for the "watching" and for the standard services like "DND" and others |
| | Extended flexibility for the Intercom feature: added PBX-Intercom call type in Call Routing wizard and 3 options to enable Intercom service A new checkbox called "Check with 3PCC" is added in Call Routing Wizard. When |
| | checking it will allow 3PCC application to place a hook on calls done through that rule |
| | Local authentication parameters are shown in Details column of Call Statistics |
| | "Check/Update Now" option is added in Automatic Firmware Update page |
| | Added SNMP status and configuration |
| | The results of system configuration backup & download are reflected in the system events |
| | snom, Aastra and Grandstream phones automatically get rebooted when the Quadro is rebooted |
| | Added auto configuration support for the following Polycom IP phone models: Soundpoint IP 330, Soundpoint IP 550 and Soundpoint IP 650 |
| | Intercom and paging support for Grandstream IP phones |
| | Possibility to hide/show disabled records in the call routing table |
| | SIP P-Asserted-Identity support for SIP calls to ISDN network |
| | Caller ID can be used to define the call destination in call routing table |
| | The "Deny reinvites" option is added for ITSPs that do not support this option. |
| | Call forwarding configuration through custom Auto Attendant |
| | Added two stage dialing for FXS calls |
| | G729/G729a codec type selection is GUI configurable |
| | Added dependence for Server status and E1/T1 link status |

PAGE 11 15-Jun-12

| Release | New Features |
|---------|--|
| | Language pack support for the IP Phones |
| | Extended auto configuration capabilities for the Aastra phones. For Aastra phones the "Time-zone" setting has been added to set up this parameter according to Quadro regional settings. Changed the Auto Attendant custom scenario to allow multiple WAV files to be uploaded all at once in a single compressed ZIP file. |
| | Added possibility to change the original display name in the Caller ID |
| | Added Kickback feature allowing not to lose the call after blind transfer |
| | Changed the Subscription limitations and made it configurable from generalconfig.cgi hidden page. |
| 4.1.15 | |
| 4.1.14 | Maximum number of IP lines is 192. 32 lines by default, one expansion of 32 and 2 more expansions of 64 each |
| 4.1.13 | Receptionists' call queue |
| | Extension status monitoring |
| | Call interception |
| | Direct transfer to voicemail |
| | Simultaneous ring |
| | Call park |
| | Call pickup group |
| | Call paging group |
| | Plug and play for supported IP phones |
| | Simplified installation (auto configuration) for tested IP phones |
| | User rights management |
| | Support for an external voicemail system |
| | Silence detection on voicemail messages to truncate extended periods of silence |
| | QuadroFXO GW and QuadroISDN GW auto configuration |
| | Proprietary method for remote extension to bypass certain types of NAT (symmetric RTP) |
| | Status for registered IP lines and remote extensions |
| | Readable transfer statistics |
| | New voice mail notifications via e-mail, via phone call and via SMS |
| | Universal extension recording (music on hold, VM greetings, incoming/outgoing blocking messages) |
| | Sending unified fax message from mailbox to fax machine |

PAGE 12 15-Jun-12

| Release | New Features |
|---------|--|
| | System events reporting |
| | Kickback feature on IP lines |
| | snom and Aastra phones automatically reboot when the Quadro is rebooted |
| | IP phones do not lose registration after Quadro soft reboot (i.e. if the reboot is not initiated by disconnecting/reconnecting the power or pressing the reset button on the back of the Quadro) |
| | Possibility to upload and customize system messages (in the uploadownmessages.cgi hidden page) |
| | Attendant ringing announcement for both default and custom AA scenarios |
| | Possibility to change the default memory size to be allocated as a temporary storage for unified FAX message (in the extmanagement.cgi hidden page) |
| | Support for HotCall Add-In for use with Microsoft Outlook |
| | SIP address resetting function in the Extensions Management for restoring the default SIP settings of extensions |
| | Possibility to change static, running logos, links and browser mini logo (accessible from loadlogo.cgi hidden page) |
| | Possibility to change the signaling procedure for hold process in case the "Send Hold Music to Remote Party" is enabled on the extension |
| | Voicemail setup wizard to guide new users through the recording of VM greetings |
| | SIP trunk |
| | 3rd party call control |
| | Flexible numbering plan for extensions |
| | Download IP phone FW and reboot of Aastra/snom IP phones |
| | Download Quadro directory via XML to snom/Aastra phones |
| | Automatic Quadro FW update |
| | Easier GUI for forwarding lists |
| | Terminate a call from Active Calls page |
| | Enhanced method for receptionists to watch other extensions, resulting in less networking traffic |
| | Distinctive ringing on snom and Aastra IP phones |
| | Play custom message instead of ring back tone on Auto Attendant |
| | Send EVENTS via SMS |
| | CDR tags for billing |
| | Enhanced DNS/DHCP settings |
| | Daylight savings adjustment |
| | SMS and E-mail notification when a call to a given extn. has been forwarded |
| | Change extension password from phone handset |
| | External access to the voice mailbox of users' extensions. |

PAGE 13 15-Jun-12

| Release | New Features |
|---------|--|
| | Automatic backup and download of Quadro configuration |
| | QCM centralized licensing included |
| | SNMP support for event monitoring |
| | Intercom service (for supported IP phones) |
| | Paging group service (for supported IP phones) |
| | Redirection on timeout to the specified address if no action on the AA welcome message |
| | AA welcome and menu messages enabling/disabling capability |
| | Call queue for virtual extensions |
| | Toggling for call routing entries from the handset |
| | Retrieve timeout configuration for parked call |
| | SDMF caller ID standard |
| | Routing rules activity timeout |
| | Capability to make SIP calls using TCP as a transport protocol |
| | "Client Code Identification" feature on routing rule (with RADIUS enabled) |
| | Paging support with 3rd party devices |
| | Custom profiles for voice mail settings |
| | Added silent VM recording option in the Voice Mail Settings |
| | PSTN call instant callback |
| | CCS Signaling |
| | CAS Signaling |
| | Support of 2-stage dialing for E1/T1 |

PAGE 14 15-Jun-12

4 Changed Features History

The following table provides a high-level list of changed features that have been changed beginning with the most recent QuadroM32x release.

| Release | Changed Features |
|---------|---|
| 5.3.5 | The timeout for the directed Call Park method is changed from two seconds to five seconds. To park a call, put the call on Hold and dial the Call Park extension number. This needs to be done within the five second timeout. If the five second timeout is exceeded, then the Quadro will consider it as an attempt for retrieving the parked call. Once the call is parked, it can also be retrieved by dialing the same Call Park extension. New FW recommendations for snom phones. |
| 5.3.3 | Some of the system voice messages are improved. Added the option to delete the uploaded global speed dialing directory Added Kebu.it as a new carrier to the VoIP Carrier Wizard list The name of Login/Call Relay column in the Extensions Management is changed to External Access, which indicates whether the GUI login, 3pcc/Click2Dial login or Call |
| | Relay options are enabled on the extension. |
| 5.2.48 | New FW recommendations for snom, Grandstream and Polycom phones. |
| 5.2.47 | The maximum number of Successful Call Statistics has been increased from 1000 to 10000 when a CF card is installed. Added option in ACD configuration to prevent the calls to agent in target group during selected period. |
| 5.2.46 | Added information regarding video codec's under the Details in the call statistics Added P-asserted identity header in all SIP messages that contain "p-preffered identity" or "Remote-party-ID". Changed the SIP parser for proper processing of From: field in header if URI scheme is included. |
| | The SIP IDS configuration options are available in the SIP IDS settings page. The "3pcc/Click2Dial Login Allowed" checkbox is available when editing multiple extensions at the same time. |
| 5.2.40 | |
| 5.2.39 | Multiple SMS numbers can be allowed in SMS destination fields, separated by SMS provider required delimiter (the comma for Clickatell) The SoTel SIP trunk is modified in the VoIP Carrier Wizard The Skype service is added in the VoIP Carrier list |
| 5.2.26 | The Call Recording settings page is updated with a second, more simplistic method for enabling extensions. Either of two modes can be used: Basic view and Advanced view. Improvements in Call Recordings FTP retransmission mechanism. Extension Login permission to access the Quadro GUI. The login is disabled by default for |
| | all extensions. Multiple DHCP subnet support on M32x (two subnets allowed instead of one, making it possible to have about 500 devices getting DHCP from Quadro). LMR (Land Mobile Radio) support for QuadroM (E1/T1 to IP gateway capable of taking a channelized T1 to Multicast RTP IP streams by DS0 for use in a Radio over IP network) The "Send Hold Music to remote IP party" is enabled by default in the Basic services for |
| | extensions The Developer Logging is enabled by default The SIP Server text field is changed to empty by default for auto attendant (00) and two FXS extensions. The default for "Maximum recording duration" is changed to 1 hour in the "Recording box |
| | settings" and "Call recording settings" |

PAGE 15 15-Jun-12

| Release | Changed Features |
|---------|--|
| | The Secure RTP options in the Extension Codecs are available when editing multiple extensions at the same time. |
| 5.2.12 | |
| | Changed the behavior of intercom and paging to not interrupt current active call by default |
| | Intercom option has been changed so that an audible sound is now provided to the called phone to alert the person when the microphone is opened. |
| 5.2.10 | Indication of BLF/MWI subscription count and raising an event if the upper limit is reached |
| | Allowing to have multiple recording sessions regardless of the "max mail/recording duration" setting on the VM/recording box |
| | FTP retransmission mechanism improvement and manual FTP upload request from WebGUI. Call recordings can be manually uploaded from Web GUI. |
| | The SIP server value for Broadvox in the VoIP Carrier Wizard was changed |
| 5.1.38 | Added an option in the Automatically Download Call Statistic page to choose the download format |
| 5.1.36 | The VM-to-email text for FAX mail was changed to be different from the regular voicemail text |
| | An audible sound to the called phone is provided in case of intercom call |
| | The common limitation of 300 as the maximum recordings count for recording boxes has been eliminated. Now the call recording count is configurable per recording box extension, the available range is of 50-2000 recordings |
| 5.1.31 | The configuration for the call recording is redesigned |
| | After using the feature code *79 (for outgoing call blocking) from phone handset to block a dialed number the "Send Message to Caller Party" option should be enabled automatically |
| | The limitation for the number of entries in the local AAA table has been eliminated |
| | Added new VoIP carriers to the VoIP Carrier Wizard list (Acf2i and babyTEL) |
| | The "Automatic Firmware Update" link is moved from "Configuration Management" to "Firmware update" page |
| 5.1.21 | The auto-configuration and PnP support are added for Polycom SoundStation IP 6000 |
| | The auto-configuration support is added for Yealink T28 IP phone |
| | Changed the view of advanced configuration page for the snom 820 IP phone |
| | Added new VoIP carriers to the VoIP Carrier Wizard list |
| | Adding extensions to Paging and Call Pickup groups has been simplified |
| | The expiration date for trial keys are shown under the Features menu |
| 5.1.18 | The Call Routing Management option for the Auto Attendant has been changed from *7 to *77. This option allows entries in the Call Routing Table to be remotely enabled/disabled. |
| | Possibility to multi-edit the some of the extension's Voice Mailbox Settings |
| | A prefix is added to the Caller ID to identify calls returned by the Kickback option |
| | It is possible to upload the Call Queue messages as Universal Extension Recordings |

PAGE 16 15-Jun-12

| Release | Changed Features |
|---------|---|
| 5.0.22 | |
| 5.0.21 | |
| 5.0.17 | In the System-> IP routing Configuration the name of "VPN Routes" changed to "PPTP/L2TP Routes |
| | Adjusted timezone parameters for Venezuela according to new standards |
| 5.0.10 | The Fail Reason in the call routing changed as group of check boxes instead of drop down list |
| | Added status info in 3PCC settings |
| | Added scrollbars in the tables for Call Routing and Extension Management pages |
| | For snom phones, the "Call join on Xfer (2 calls)" setting is configurable in the phone GUI |
| 5.0.8 | Adjusted timezone parameters for Venezuela according to new standards |
| 5.0.8 | Added status info in 3PCC settings |
| | Added scrollbars in the tables for Call Routing and Extension Management pages |
| | Changed default attendant name from 000 to 00 |
| | Added PSTN Access Code and Emergency Number page in System Configuration Wizard. |
| 4.1.15 | Removed PSTN Access Code from External PSTN Gateways page |
| | Changed default E1/T1 mode to User Mode |
| | Changed default VM indication for IP Lines from Tone to Lamp and for 2 FXS Lines from Lamp to Tone. |
| 4.1.14 | FXS settings(filters) changes for Brazil |
| 4.1.13 | |

PAGE 17 15-Jun-12

5 Fixed Issues

Issues fixed since version 5.3.3:

| | No audio on both sides if you hold the call, then unhold it after the Holding reminder on snom phone running FW 8.4.32 | | |
|---------|---|--|--|
| D: | This problem is specific for snom 3xx models only. When the "Holding reminder" option is set to 'on', the phone reminds you with a short beep after timeout of 30 sec that you still have somebody on hold. Unholding the call after Holding reminder will bring to the audio loss on both sides. | | |
| C: | | | |
| An iss | sue with call statistics archiving option by time interval of 30 days 17334 | | |
| D: | Using this option may cause system instability because of the large memory requirements for downloading to external server. Avoid using the 30 day option when configuring statistics archiving by time interval | | |
| C: | | | |
| | e/FollowMe doesn't work after call forward 17367 | | |
| D: | If the call is forwarded from one extension to another, and FindMe/FollowMe is enabled on the destination extension, the caller hears the FindMe/FollowMe messages but no call is made to the FindMe/FollowMe participants. | | |
| C: | | | |
| Call ir | tercept fails when making call on auto attendant 17364 | | |
| D: | Call Intercept (*94) will not work if the caller has first dialed to the Auto Attendant and then to an extension. | | |
| C: | | | |
| The C | aller ID is not updated during consultative transfer in case of extension to | | |
| exten | sion calls 17365 | | |
| D: | When an outside call is received to an extension on the PBX, and then a consultive transfer is done, the caller id will not show the number of the outside caller on the display of the receiving extension. | | |
| | ot possible to upload tar.gz format archive file in Import/export scenario | | |
| | for Customized Scenario option | | |
| D: | Only xml or vxml files are allowed to upload, which are not applicable in this case | | |
| C: | | | |
| | sue with uploading files for Auto Attendant welcome messages in the mized Scenario 17362 | | |
| D: | The "Please select a file with proper extension! Allowed extensions are: " error is displayed in case of welcome message upload. | | |
| C: | | | |
| Call I | nterception doesn't work on Polycom IP phones configured as receptionist 17410 | | |
| D: | Call Interception using the programmable key doesn't work on Polycom SoundPoint IP 450, 550, 650 phones configured as receptionist. | | |
| C: | | | |
| | o is crashing when trying to intercept a call to an IP Extension which is in already | | |
| D: | The call intercept (*94) function may crash the Quadro if you are trying to intercept a call to an IP extension which is in a call already | | |
| C: | | | |
| An iss | sue with call statistics archiving option by time interval of 7 days 17430 | | |
| D: | The Quadro is falling into an infinite loop and collecting (and sending) 15-30 | | |

PAGE 18 15-Jun-12

| | records per minute when using the option of 7 days. | |
|----|--|--|
| C: | | |
| | A problem with configuring Expansion Modules in the Receptionist Phone Configuration Wizard 17396 | |
| D: | Enabling and configuring Expansion Modules for Receptionist Phone in the Receptionist Phone Configuration Wizard don't have an effect. Functions assigned to programmable keys for Expansion modules won't work. | |
| C: | | |

PAGE 19 15-Jun-12

6 Known Issues

D: DescriptionC: Consequences

Fix: How to avoid the situation, or what to do in case the situation has occurred.

| It is im | possible to login as 'admin' after making changes on "Advanced PPP |
|-----------|--|
| Setting | • |
| D: | You cannot login to the Quadro as 'admin' after making changes on the |
| | "Advanced PPP Settings" page. You can only login as 'user'. |
| C: | No consequences |
| Fix: | Restart the Quadro to resolve this. |
| One wa | y audio with IPSec VPN in the scenario "Gateway<->Remote Subnet" 9327 |
| D: | Scenario: |
| Б. | 1. Establish an IP-Sec connection between two Quadros (connection type is |
| | "Quadro <-> Remote Subnet"). |
| | 2. Make an SIP call from Quadro1 (gateway) to Quadro2 (remote subnet). |
| C: | The call is established, but there is no audio in Quadro1. The same result will |
| | occur when calling from Quadro2 to Quadro1. |
| | A direct call cannot be established at all. |
| Fix: | Add an additional "Quadro <> Remote Gateway" tunnel in IPSec configuration. |
| | With two tunnels: "Quadro <> Remote Gateway", "Quadro <> Remote Subnet" in IPSec VPN configuration this issue will resolved. |
| Call inte | erception fails in a specific scenario with a watched extension in the many |
| | on ring list |
| D: | Scenario: |
| | 1. Use snom360 for receptionist extension (for example, extension #31), |
| | 2. Configure Many Extension Ringing on ext. #31 with extensions #31 and |
| | #12 in the MER list, |
| | 3. Configure extensions #11 and #12 as watched extensions, |
| | 4. Make a call to extension #31,5. The phones for extensions # 31 and #12 will start ringing. |
| | 6. The programmable key for the ext. #12 is flashing on the receptionist's ext. |
| | #31, |
| | 7. Pressing that key the receptionist stops ringing, but ext. #12 is still ringing, |
| | 8. Hang-up the phone for that caller's extension. |
| C: | Call interception on the receptionist's line fails. The light for ext. #11 will stay ON |
| | on the ext. #31. |
| Fix: | This problem is specific for snom phones only. When using a snom phone, calls |
| | should be answered on your own extension and not the watched extension. |
| An icou | e with configuring IP phones as local extensions for Quadro IP PBX |
| All ISSU | 13471 |
| D: | Plug and Play and Auto configuration of IP phones is impossible with the |
| | modified "HTTP Server Port" on the Quadro. |
| C: | |
| Fix: | Add the changed http port value in the "option tftp-server-name" row |
| | ("dhcpd.conf.lan" file) for each IP phone. Example: "option tftp-server-name |
| 0 - | "http://172.30.38.1:8080". Will be fixed in the future releases. |
| | f the Quadro voice mail services could be unavailable if external Voice Mail for extension 12190 |
| D: | |
| υ. | In this scenario some of the features, for example Zero-out and entering the VMS |

PAGE 20 15-Jun-12

| | directly with option "1" will not work. |
|---------|---|
| C: | an early with option 1 will not work. |
| Fix: | This is normal, as those features are the Quadro's internal VMS system features. If external VMS system is used, user gets the features of that external system. |
| | Aastra, Grandstream and Thomson IP phones may disconnect if you press button for a long time (60 min) |
| D: | |
| C: | |
| Fix: | Under investigation, will be fixed in the future releases. |
| Aastra | IP phone is not ringing when it is used in many extensions ringing list 13830 |
| | Scenario: 1. Many extension ringing is enabled on a virtual extension with an Aastra phone in the list |
| | 2. Distinctive Ringing is enabled on that virtual extension with Nickname that contains space |
| C: | When a call with no Caller ID comes to that extension, the Aastra phone in many extensions ringing list does not ring. |
| Fix: | The problem is solved if there is a Caller ID available on the incoming call or if the Nickname doesn't contain spaces. This problem is limited to Aastra IP phones only. |
| An issu | ue with configuring Aastra IP phones as local extensions for Quadro IP PBX 13802 |
| D: | After changing the LAN IP address for the Quadro the 480i, 9133i and 55i Aastra phones with currently recommended 1.4.1.2000 firmware are not registering after restart. |
| C: | |
| Fix: | They must be factory reset to register again. Under investigation. Will be fixed in the future FW versions for Aastra phones. |
| An issu | ue with distinctive ringing on the snom, Aastra and GrandStream IP phones 11519 |
| D: | snom, Aastra and GrandStream phones ring only once if the distinctive ringing is enabled with the "winter" ringing pattern. |
| C: | No consequences |
| Fix: | Use other ringing patterns for distinctive ringing on snom, Aastra and GrandStream IP phones. |
| | terception doesn't work on GrandStream GXP2000 configured as a fonist, when extensions are watched on expansion module 14797 |
| D: | |
| C: | |
| Fix: | Use basic 7 keys instead of expansion module. Will be fixed in the future releases. |
| Paging | and intercom services do not work on the GrandStream BT100 IP phone 14909 |
| D: | |
| C: | |
| Fix: | Currently BT100 has no support for paging/intercom. |
| - | ne doesn't go back to the normally idle state automatically when the ing had been started via the Record button and the call was released 15729 |
| D: | The "Recording started" message remains on the phone screen after one of the parties terminate the call by going on-hook. |
| C: | Only incoming calls to IP phone are possible in this state. |
| Fix: | Need to use "Exit" button to retrieve the IP phone functionality. Will be fixed in |
| | |

PAGE 21 15-Jun-12

| It is not possible to pickup (via pickup group) FindMe/FollowMe enabled D: C: Fix: Will be fixed in the next releases. After changing Quadro LAN IP configuration (phones lose registration and become unusabled) D: C: Fix: After changing Quadro LAN IP configurated the IP phones. Will be fixed in the next releases. A problem with "Remove VM On Send" option D: If this option is enabled new VMs are remailed fails be mailed address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS (Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functit is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connectable, Quadro always tries to connect it a dropped due to the media parameters in | IP address or subnet mask) IP 16037 on first reboot the Quadro then reboot elease. in Voice mail settings 16432 hoved from the extension mailbox even cause the mail server is unreachable or sateway Management" page 16468 hgs->FXS Gateway Management, if FXS |
|--|---|
| FindMe/FollowMe enabled D: C: Fix: Will be fixed in the next releases. After changing Quadro LAN IP configuration (phones lose registration and become unusable) D: C: Fix: After changing Quadro LAN IP configurat the IP phones. Will be fixed in the next result if the IP phones. Will be fixed in the next result if sending the new VM on Send" option D: If this option is enabled new VMs are result from the sending the new VM via e-mail fails be mail address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS (Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" funct it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call is connectable, Quadro always tries to connect it a dropped due to the media parameters in | IP address or subnet mask) IP 16037 on first reboot the Quadro then reboot elease. in Voice mail settings 16432 hoved from the extension mailbox even cause the mail server is unreachable or in the mail server is unreachable or elease. Sateway Management" page 16468 hgs->FXS Gateway Management, if FXS |
| D: C: Fix: Will be fixed in the next releases. After changing Quadro LAN IP configuration (phones lose registration and become unusable) D: C: Fix: After changing Quadro LAN IP configurated the IP phones. Will be fixed in the next restricted in the next releases. A problem with "Remove VM On Send" option D: If this option is enabled new VMs are remail fails be mail address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS CONTINUES. D: In the page Line Settings-> IP Line Setting Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functing it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connectable, Quadro always tries to connect it a dropped due to the media parameters in | on first reboot the Quadro then reboot elease. in Voice mail settings 16432 hoved from the extension mailbox even cause the mail server is unreachable or eateway Management" page 16468 hgs->FXS Gateway Management, if FXS |
| C: Fix: Will be fixed in the next releases. After changing Quadro LAN IP configuration (phones lose registration and become unusable) D: C: Fix: After changing Quadro LAN IP configurated the IP phones. Will be fixed in the next reflected in the next releases. MAC address recognition problem in the FXS CONTINUES. D: In the page Line Settings-> IP Line Setting Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functit is not possible to edit existing records. Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connectable, Quadro always tries to connect it a dropped due to the media parameters in | on first reboot the Quadro then reboot elease. in Voice mail settings 16432 noved from the extension mailbox even cause the mail server is unreachable or sateway Management" page 16468 ngs->FXS Gateway Management, if FXS |
| Fix: Will be fixed in the next releases. After changing Quadro LAN IP configuration (phones lose registration and become unusable) D: C: Fix: After changing Quadro LAN IP configurated the IP phones. Will be fixed in the next reserved in the next reserved in the next reserved if sending the new VM on Send" option D: If this option is enabled new VMs are remailed address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS of Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functing it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will a problem with incoming Secure RTP call in a dropped due to the media parameters in | on first reboot the Quadro then reboot elease. in Voice mail settings 16432 noved from the extension mailbox even cause the mail server is unreachable or sateway Management" page 16468 ngs->FXS Gateway Management, if FXS |
| After changing Quadro LAN IP configuration (phones lose registration and become unusable) D: C: Fix: After changing Quadro LAN IP configurat the IP phones. Will be fixed in the next reserved in the IP phones. Will be fixed in the next reserved if sending the new VM on Send" option D: If this option is enabled new VMs are remailed address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS of Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" funct it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a dropped due to the media parameters in | on first reboot the Quadro then reboot elease. in Voice mail settings 16432 noved from the extension mailbox even cause the mail server is unreachable or sateway Management" page 16468 ngs->FXS Gateway Management, if FXS |
| D: C: Fix: After changing Quadro LAN IP configurat the IP phones. Will be fixed in the next reaching the new VM On Send" option D: If this option is enabled new VMs are remailed fails be mail address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS On the page Line Settings-> IP Line Setting Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functing it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call is connectable, Quadro always tries to connect it addropped due to the media parameters in | on first reboot the Quadro then reboot elease. in Voice mail settings 16432 noved from the extension mailbox even cause the mail server is unreachable or sateway Management" page 16468 ngs->FXS Gateway Management, if FXS |
| D: C: Fix: After changing Quadro LAN IP configurat the IP phones. Will be fixed in the next reached and the IP phones. Will be fixed in the next reached and the IP phones. Will be fixed in the next reached and the IP phones. Will be fixed in the new VMs are reached and the sending the new VM via e-mail fails be mail address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS CONTINUES. D: In the page Line Settings-> IP Line Setting Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functing it is not possible to edit existing records. Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a dropped due to the media parameters in | on first reboot the Quadro then reboot elease. in Voice mail settings 16432 noved from the extension mailbox even cause the mail server is unreachable or interest of the extension mailbox even cause the mail server is unreachable or interest of the extension mailbox even cause the mail server is unreachable or interest of the extension mailbox even cause the mail server is unreachable or |
| C: Fix: After changing Quadro LAN IP configurat the IP phones. Will be fixed in the next reaction option with "Remove VM On Send" option D: If this option is enabled new VMs are remailed fails be mailed address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS On the page Line Settings-> IP Line Setting Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functing it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will a problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connectable, Quadro always tries to connect it a dropped due to the media parameters in | in Voice mail settings 16432 noved from the extension mailbox even cause the mail server is unreachable or ateway Management" page 16468 ngs->FXS Gateway Management, if FXS |
| Fix: After changing Quadro LAN IP configurat the IP phones. Will be fixed in the next research with "Remove VM On Send" option D: If this option is enabled new VMs are remissed if sending the new VM via e-mail fails be mail address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS CONTROL TO THE SETTING | in Voice mail settings 16432 noved from the extension mailbox even cause the mail server is unreachable or ateway Management" page 16468 ngs->FXS Gateway Management, if FXS |
| the IP phones. Will be fixed in the next reached and reproblem with "Remove VM On Send" option D: If this option is enabled new VMs are remailed fails be mailed address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS On the page Line Settings-> IP Line Setting Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functing it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connected addressed and reproblem with media parameters in the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call is connected and reproblem to the media parameters in the secure RTP call in the secure RTP call is connected and reproblem to the secure RTP call in the secure RTP call | in Voice mail settings 16432 noved from the extension mailbox even cause the mail server is unreachable or iateway Management" page 16468 ngs->FXS Gateway Management, if FXS |
| A problem with "Remove VM On Send" option D: | in Voice mail settings noved from the extension mailbox even cause the mail server is unreachable or iateway Management" page 16468 ngs->FXS Gateway Management, if FXS |
| D: If this option is enabled new VMs are rerifful if sending the new VM via e-mail fails be mail address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS (Content of the page Line Settings-> IP Line Setting Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functing it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will a problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connectable, Quadro always tries to connect it a dropped due to the media parameters in | noved from the extension mailbox even cause the mail server is unreachable or sateway Management" page 16468 ngs->FXS Gateway Management, if FXS |
| if sending the new VM via e-mail fails be mail address is incorrect C: Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS (In the page Line Settings-> IP Line Setting Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functing it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connectable, Quadro always tries to connect it addropped due to the media parameters in | cause the mail server is unreachable or cause |
| Fix: Will be fixed in the next releases. MAC address recognition problem in the FXS of the page Line Settings-> IP Line Settin | ngs->FXS Gateway Management, if FXS |
| D: In the page Line Settings-> IP Line Setting Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" functing it is not possible to edit existing records. Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connected to the media parameters in the secure of the se | ngs->FXS Gateway Management, if FXS |
| D: In the page Line Settings-> IP Line Setti Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" funct it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connect table, Quadro always tries to connect it a dropped due to the media parameters in | ngs->FXS Gateway Management, if FXS |
| Gateway is added manually, the system Gateway entered in uppercase. C: As a result the "Edit" and "Reboot" funct it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connect table, Quadro always tries to connect it a dropped due to the media parameters in | |
| it is not possible to edit existing records Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connect table, Quadro always tries to connect it a dropped due to the media parameters in | |
| Fix: Enter the MAC address in lowercase. Will A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connect table, Quadro always tries to connect it a dropped due to the media parameters in | |
| A problem with incoming Secure RTP call in a D: When incoming Secure RTP call is connect table, Quadro always tries to connect it a dropped due to the media parameters in | |
| D: When incoming Secure RTP call is connect table, Quadro always tries to connect it a dropped due to the media parameters in | |
| table, Quadro always tries to connect it a dropped due to the media parameters in | |
| dropped due to the media parameters in | |
| | • |
| C: | |
| Fix: Will be fixed in the next releases. | |
| An issue with wrongly displayed "Start Record | ling" message in the Active Calls |
| D: The recording type is set to "start autom | |
| call recordings is exhausted, therefore th | · |
| started, but the "Start Recording" is wro | |
| C: | |
| Fix: Will be fixed in the next releases. | |
| Find me/follow me doesn't work for incoming | Secure RTP call 16683 |
| D: Though the call came with SRTP option t | |
| C: As a result the call isn't established | To Thin I W 13 Hidding discours calls |
| | |
| | ubles with 2nes connection to an |
| ACD behavior becomes incorrect in case of troapplication | ubles with spec connection to an |
| D: It affects to ACD calls | |
| C: | |
| Fix: Will be fixed in the next release. | |
| The configuration page for Expansion Module T28 and T26 as receptionist phones | is missing when configuring Yealink 16971 |
| D: In Receptionist Management wizard the are not available for Yealink T28 and T26 | expansion module configuration pages |
| C: | • |
| Fix: Will be fixed in the next release. | |

PAGE 22 15-Jun-12

| one way | y audio in a scenario when Holding/Retrieving the PSTN call 17245 |
|--|---|
| D: | Scenario: |
| | 1. ext. A is configured to watch the ext. B |
| | 2. PSTN (E1/T1) call comes to ext. B and the functional key of the ext. A shows |
| | the ringing state for ext. B |
| | 3. ext. A presses the functional key and intercepts the call to ext. B |
| | 4. ext. A holds the call |
| | 5. ext. A retrieves the call |
| | |
| C: | Result: ext. A hears the PSTN, but the PSTN doesn't hear the ext. A |
| Fix: | The reason is the SRTP option on ext. A set to "Make unsecure calls, accept |
| | anything". Change the SRTP option on the ext. A to "Make and accept only |
| | unsecure calls". Will be fixed in the next release. |
| An issue | with Intercom service on snom 8xx phones 17282 |
| D: | When the snom phone of 8xx series (tested with snom phones 821, 870 running |
| | FW version's 8.4.32, 8.4.33) have some watching configured for it's functional |
| | keys and the status of the watching resource is changed (e.g. the watching |
| | phone receives or makes a call), immediately the next intercom call to the snom |
| | phone doesn't activate the intercom but continuously ring the phone. |
| C: | As a result, if the calling phone is configured as a watched extension, the snom |
| | phone never activates the intercom for that caller. |
| Fix: | Will be fixed in some future FW release for snom. |
| | thentication doesn't work for a call scenario 16784 |
| D: | Local authentication configured in the Local AAA table by User Login or by PIN |
| | code is ignored for the following call scenario; a SIP call to Quadro Auto |
| | Attendant, then call to a SIP destination. |
| C: | Quadro doesn't ask for authentication in this case. |
| Fix: | Will be fixed in the next release. |
| | e with adding audio files for ACD custom scenario 16817 |
| D: | Scenario: |
| | - add an audio file with special characters in name (with slashes, dashes, |
| | brackets, etc.) for Custom Queue Messages in the ACD Customize queue scenario; |
| | I SCENATIO |
| | |
| C. | - The added file is shown as normally uploaded on the GUI. |
| C: | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to |
| | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. |
| C: | The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD |
| Fix: | The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. |
| Fix: The sno | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 |
| Fix: The sno D: | The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. |
| Fix: The sno D: C: | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. |
| Fix: The sno D: C: Fix: | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. |
| Fix: The sno D: C: Fix: Fix: | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. |
| Fix: The sno D: C: Fix: Fix: Call whi statistic | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. ch is done after Call Relay(*2) on auto attendant isn't shown in call 17404 |
| Fix: The sno D: C: Fix: Fix: Call whi | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. ch is done after Call Relay(*2) on auto attendant isn't shown in call 17404 Only the call to attendant is shown in the call statistics. The call leg after call |
| Fix: The sno D: C: Fix: Fix: Call whi statistic | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. ch is done after Call Relay(*2) on auto attendant isn't shown in call 17404 Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating |
| Fix: The sno D: C: Fix: Fix: Call whi statistic D: | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. ch is done after Call Relay(*2) on auto attendant isn't shown in call 17404 Only the call to attendant is shown in the call statistics. The call leg after call |
| Fix: The sno D: C: Fix: Fix: Call whi statistic | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. ch is done after Call Relay(*2) on auto attendant isn't shown in call 17404 Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first. |
| Fix: The sno D: C: Fix: Fix: Call whi statistic D: C: Fix: | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. ch is done after Call Relay(*2) on auto attendant isn't shown in call iss 17404 Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first. Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases. |
| Fix: The sno D: C: Fix: Fix: Call whi statistic D: C: Fix: | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. ch is done after Call Relay(*2) on auto attendant isn't shown in call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first. Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases. Mailbox doesn't work when using "Allow access to Shared Mailbox for |
| Fix: The sno D: C: Fix: Fix: Call whi statistic D: C: Fix: Shared | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. ch is done after Call Relay(*2) on auto attendant isn't shown in call iss 17404 Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first. Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases. |
| Fix: The sno D: C: Fix: Fix: Call whi statistic D: C: Fix: Shared | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. ch is done after Call Relay(*2) on auto attendant isn't shown in call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first. Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases. Mailbox doesn't work when using "Allow access to Shared Mailbox for |
| Fix: The sno D: C: Fix: Fix: Call whi statistic D: C: Fix: Shared i enabled | - The added file is shown as normally uploaded on the GUI. Actually the newly added file isn't being uploaded in the system. So the callers to ACD with Customize Queue Scenario will hear nothing for that message. Don't use special characters in the name for audio file to be played in the ACD queue. Will be fixed in the next releases. m phone doesn't allow multiple call park/retrieve 17340 Upon successful call park/retrieve on snom the call couldn't be parked again. Will be fixed in some future FW release for snom. Will be fixed in the next release. ch is done after Call Relay(*2) on auto attendant isn't shown in call 17404 Only the call to attendant is shown in the call statistics. The call leg after call relay is missing in the call statistics in case if the external caller is terminating the call first. Use feature code *1 instead of *2 for call relay. Will be fixed in the next releases. Mailbox doesn't work when using "Allow access to Shared Mailbox for extensions" option in Many Extension Ringing configuration 16635 |

PAGE 23 15-Jun-12

| C: | However, in the IP Line settings, the "Shared VMail Ext. xxx" option is not listed in the drop down list for Advanced-Programmable Keys Configuration. | |
|---------|---|--|
| Fix: | Use the "Shared Mailbox: Edit Voice Mailbox Access List" link in the Voice Mailbox Settings for extension. Will be fixed in the next releases. | |
| The Voi | The Voice Mail playing order is incorrect in automatically mode 17479 | |
| D: | When accessing the voice mailbox the newly received (unread) voice mails should play first, after all received voice mails started from the first received. | |
| C: | However in the current FW version the voice mails in mailbox are playing in order they are received. | |
| Fix: | Will be fixed in the next releases. | |

PAGE 24 15-Jun-12

7 Upgrading Instructions

7.1 Technical Advisory

Attention: For manually configured IP phones, it is now required to have the **SIP Registration Timeout** parameter set to 120 seconds or more on your IP phone. Values less than 120 seconds will not be accepted by the Quadro and will cause the IP phone registration failure on the Quadro.

7.2 Quadro SW requirements for upgrading to 5.3

Attention: The software upgrade to 5.3 can **ONLY** be done from 5.2.47 and higher 5.2 versions. Before updating to 5.3 the unit should be updated to 5.2.47 or higher 5.2 version first.

7.3 General hints

It is recommended to execute the update by downloading the software first to a PC located in the LAN side of the Quadro and perform the firmware update from the LAN side. This is to ensure that the Internet connection will not affect the upgrade process.

In general, the configuration of a system will remain after the software update. Remember that some data is lost during upgrade:

- Call Statistics (only when embedded memory storage is used)
 - Workaround to save the existing call statistics, download it to the PC from Call Statistics-Statistics Settings before performing the firmware update. It is also recommended to use an external Compact flash memory to keep the call statistics safe.
- Voice mails (only when embedded memory storage is used)
 - Workaround save the recorded voice mails from the Voice Mailbox before performing the firmware update. It is also recommended to use an external Compact flash memory to keep the voice mails safe.
- Call recordings (only when embedded memory storage is used)
 - Workaround save the recorded calls from the Recordings Box before performing the firmware update or use the recorded calls automatically upload to the FTP server option. It is also recommended to use an external Compact flash memory to keep the voice mails safe.
- All custom voice greetings (only when embedded memory storage is used)
 - Workaround backup and download all configuration and voice data to a PC. It is also recommended to use an external Compact flash memory to keep the custom voice messages safe.
- All custom recordings for the custom Auto Attendant (only when embedded memory storage is used)
 - Workaround backup and download all configuration and voice data to a PC. It is also recommended to use an external Compact flash memory to keep the custom recordings safe.
- **Pending events** (only when embedded memory storage is used)
- Transfer statistics for the network
- DHCP leases

The following steps describe how to correctly perform the firmware update:

PAGE 25 15-Jun-12

- Save the current configuration by doing a Backup and Download of all config and voice data (System->Configuration Management->Backup and download all config and voice data).
- 2. Perform the Firmware Update.
- 3. Is there a Compact Flash memory card installed?
 - Yes- No further action is required
 - No- Restore the configuration that was saved in Step 1 (System -> Configuration Management -> Upload and Restore all config and voice data).
 This is necessary to restore the extension custom voice messages and the custom Auto Attendant messages.

Attention: Always power down the Quadro before inserting/removing any Compact Flash card. The largest recommended Compact Flash card is 8mb.

7.4 Limitations and restrictions

- The memory used by "DSP Capture", "Call Capture" and "Network Capture" hidden pages is limited to 3 MB. This will put a limitation on the duration of captured file
- In case if voice mail recording codec is other than PCMU, the maximum length of VM sent by email is limited to 3 minutes
- The number of VMs in the mailbox for one extension is limited to 300
- Use Session Timer in IP Line Settings is deselected by default

PAGE 26 15-Jun-12